

NOVEMBER 18, 2019

BASCARA, MICHELLE ANNE
#5 JOSEPH ST. VILLA ESPAÑA BRGY. TATALON
QC. 0906-3152496/ 0936-8015386
0936-8015386

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KAG-150DME

SJR: 0591948

Parts	Amount
Evaporator	3,300.00
Fan Capacitor	165.00
System Reprocess	2,000.00
Pull Out Delivery	<u>500.00</u>
Total:	5,965.00
Total Estimated Charge:	P <u><u>5,965.00</u></u>

Note:

1. *Replacement Of Evaporator, Fan Capacitor.*
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at **852-6868 or 0917-806-0920.**
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair.
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. *Initial Quotation.*

DP: ₱3,000.00

Prepared by:


ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:

JOEL CORIA
SHOP FOREMAN

Conforme:

Via Email / 11.18.19 / 12:02 PM

SIGNATURE OVER PRINTED NAME

11/18/19
Sent Quotation ok

2:37 / 11.19.19

17:28