

SEPTEMBER 26, 2019

BOBIER, ROSE
920-E.I. TRINIDAD ST. BRGY. VERGARA
MANDALUYONG 234-9541/ 05196397921
234-9541

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KAG-110RSINV

SJR: 0585225

Parts

Amount

Evaporator

10.00

System Reprocess

2,000.00

Pull Out Delivery

500.00

Total:

2,500.00

Total Estimated Charge:

P 2,500.00

Note:

1. *Replacement Of Evaporator.*
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at **852-6868 or 0917-806-0920.**
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding for repair.
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. *Initial Quotation.*

Prepared by:

9.26.19
ANGEL DE TORRES
ASSISTANT

Noted by:

09-26-2019
JOEL CORIA
SHOP FOREMAN

Conforme:

Via Email / 10.9.19 / 9:40 PM
SIGNATURE OVER PRINTED NAME

Sta. St., Guadalupe Nuevo, Makati City
phil.com.ph

(632) 851-2711, 12 or 15

Fax: (632) 852-2170 / Sales Dept. Fax: (632) 852-4791

Kolin Plant:

Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy,
Langkaan I, Dasmariñas, Cavite

Tel.: (632) 749-2118

Fax: (046) 402-0793

for
years