

SEPTEMBER 26, 2019

JAMLA CORP.  
151 PINATUBO ST. BARANGKA ILAYA  
MANDALUYONG CITY 747-3138  
747-3100

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KAG-200RSINV

SJR: 0583895

Parts	Amount
Evaporator	4,400.00
Fan Capacitor	220.00
System Reprocess	<u>2,000.00</u>
Total:	6,620.00

Total Estimated Charge:

P 6,620.00

**Note:**

1. *Replacement of Evaporator, Fan Capacitor.*
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at **852-6868 or 0917-806-0920.**
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding the repair
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. *Initial Quotation.*

DP: ₱ 3,310.00

Balance: ₱ 3,310.00

Prepared by:

  
ANGEL ARLAN DE TORRES  
SHOP ASSISTANT

Noted by:

  
JOEL CORIA  
SHOP FOREMAN

Conforme:

*Via Email / 9-20-19 / 2:09 pm*  
SIGNATURE OVER PRINTED NAME