

SEPTEMBER 26, 2019

JAMLA CORP.
151 PINATUBO ST. BARANGKA ILAYA
MANDALUYONG CITY 747-3138
747-3100

Sir/Ma'am;

Please find below the quotation for repair of the following unit.

MODEL: KAG-200RSINV

SJR: 0583896

Swing Motor	• 385.00
Display Board	715.00
Evaporator	4,400.00
Condenser	4,950.00
Base Pan	1,000.00
System Reprocess	<u>2,000.00</u>
Total:	<u>13,450.00</u>

Total Estimated Charge:

P 13,450.00

Note:

1. *Replacement of Evaporator, Condenser, Base Pan.*
2. Final charges will be based on actual repair of unit.
3. Repaired units are guaranteed for a period of 90 days (*Parts & Labor*) from date of unit acceptance and for the same encountered defects.
4. If you need assistance don't hesitate to call the under signed (*Angel Arlan De Torres*) at *852-6868 or 0917-806-0920.*
5. Once quotation was confirmed 50% downpayment needs to be deposit before proceeding the repair
6. The remaining balance of 50% downpayment is to be paid to Kolin technician before install the unit.
7. *Initial Quotation.*

DP: ~~₱~~ 6,175.00

Balance: ~~₱~~ 7,275.00

Prepared by:


ANGEL ARLAN DE TORRES
SHOP ASSISTANT

Noted by:

JOEL CORIA
SHOP FOREMAN

Conforme:

Via Email / 9.20.19 / 2:09 PM

SIGNATURE OVER PRINTED NAME