

20-Jan-2026

MR. DANNY/DANIEL DY

#15 SOLIVEN 1 AVE., LOYOLA GRAND VILLAS, KATIPUNAN, QUEZON CITY
TEL#: 0917-3235462/0917-8123767/0917-5090539/0917-5090772

Dear Sir / Madam,

This is to remind you regarding the **unsettled billing** for service jobs completed on your units across the following years. The details of the charges are outlined below, and a copy of the **Service Job Report(s)** is attached for your reference.

DATE ATTENDED	SJR #	MODEL	SERVICE JOB DONE	AMOUNT (₱)
25-Mar-23	HO-00145581	KSM-IW15-6H1M	General Cleaning	1,500.00
10-Jul-23	HO-00162134	KSM-10CB1INV	General Cleaning	1,500.00
24-Jan-24	HO-00185566	KSM-10CB1INV	General Cleaning	1,500.00
24-Jan-24	HO-00185590	KSM-IW15-6H1M	General Cleaning	1,500.00
23-Feb-24	HO-00188888	KSM-25CB1INV	Replaced (O) Sensor	1,470.00
15-Apr-24	HO-00195441	KSM-15CB1INV	General Cleaning	1,500.00
02-May-24	HO-00199621	KSM-25CB1INV	General Cleaning	1,500.00
03-May-24	HO-00200198	KSM-25CB1INV	Replaced Discharged Sensor	220.00
31-Jul-24	HO-00215500	KSM-10CB1INV	General Cleaning	1,500.00
05-Nov-24	HO-00228894	KSM-10CB1INV	General Cleaning	1,500.00
14-Mar-25	HO-00245201	KSM-10CB1INV	General Cleaning	1,500.00
14-Mar-25	HO-00245203	KSG-250B1G	General Cleaning	1,500.00
14-Mar-25	HO-00245899	KSG-250B1G	General Cleaning	1,500.00
08-May-25	HO-00253829	KSM-25CB1INV	General Cleaning	1,500.00
20-May-25	HO-00256122	KFG-40F1	Replaced Parts	8,385.00
Total Amount Due:				₱ 28,075.00

Notes:

* If check payment, please prepare check payable to **Kolin Philippines International Inc.**


Account #: 011808000428 - BDO - KALAYAAN

* In case thru Bank Deposit under BDO Account, kindly indicate **(1) SJR#** as Reference No. on the deposit slip.

Kindly send proof of payment/deposit slip to **viber 0917-807-9481** or E-mail to: **svcacctg@kolinphil.com.ph**

For any clarifications please feel free to call the undersigned at **(02) 8851-27-11 Loc. 309**

Prepared by:


Jerome F. Castro

Service Accounting Specialist

Noted by:


Ms. Richell V. Hicban

Service Accounting - Supervisor


Received by:

Signature over printed name

 **Kolin Philippines Int'l. Inc.**

Plant and Head Office:
Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite
Tel: (632) 8749-2118
Fax (046) 402-0793
www.kolinphil.com.ph / kolinphilippines

Operation Office:
1854 Sta. Rita St., Guadalupe Nuevo,
Makati City
Tel: (632) 8851-2711, 12 or 15
Fax: (632) 8852-2170
Sales Dept. Fax: (632) 8852-4791



Kolin Philippines International, Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
 Tel. No.: 09852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph    

SERVICE JOB REPORT

Customer					Date	HO-00162154					
Address	Dy. Danny / Daniel #15 Soliven 1 Ave., Loyola Grand Villas, Katipunan, QUEZON CITY, Metro Manila				Start Time	07-08-2023					
Telephone No.			Mobile No.			End Time	07:32 pm				
Contact Person		Mobile No.		Tel. No.			Relayed by	07:39 pm			
Warranty Code	Service Dy	0917-8123767		Room Size			Warranty Type	ADM			
Model			Call Origin			Job Class	C	LVL	GC		
S/N (I)	KG-10CB1INV	S/N (O)	10	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>			
Dealer	10051006-10419	DOP	10051006-10417	Notes					07/11/2023		
Installer	KMI	Complaint CUEVAS FOR GC-TS									
Location			Before	Water Dripping							
Mode Setting (Cool)	Bedroom / daughter	Cool	Cool	No. of Visit			Tentative Sched				
WAC Setting Temp(16°C-RE)/(10/12-ME)	16		17	1st Action		Findings		07/11/2023			
SAC/PAC Setting Temp (17°)	17	17	Clogged Drain Line, Dirty Unit, Defective Louver (Horizontal)								
Discharge Temperature (High)	15	14									
Intake Temperature (High)	25.9	25.7									
Ampere	5.1	5.4	Recommendation								
Wattage (Inverter)	170		230	For observation							
Voltage	230		230								
SAC/PAC Pressure (PSI)	170		170								
Part Code	Description				Qty	Unit Price	Amount				
SR No.					Labor	1,500 -					
Repair Done	General Cleaning of Indoor & Outdoor				Handling						
Repair Code					Others						
Date Attended	07-10-23	Date Finished	07-10-23	Total	1,500 -						
Time Attended	1340H	Time Finished	1445H	Amount Paid	for collection						
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch						
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.									
Cortez		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.									
B297		Created by:		Conformed by:							
Technician(s)		CSR		Customer (Signature over printed name)							

No.
Previous SJR No.

HO-00185566

Customer	Dy, Denby / Daniel			Date	01-23-2024				
Address	#15 Saliven 1 Ave., Loyola Grand Villas, Katipunan, QUEZON CITY, Metro Manila			Start Time	10:30 am				
Telephone No.	Mobile No.		Mobile No.	0917-3235482	End Time	10:32 am			
Contact Person	Bernice Dy	Mobile No.	0917-8123767	Tel. No.	Relayed by Bernice Dy				
Warranty Code				Room Size	Warranty Type C				
Model	KSM-10CB1INV			Call Origin	10	Job Class	CC	LVL	1
S/N (I)	10661008-10419		S/N (O)	10661008-10447	Permit? <input type="checkbox"/> Parking? <input checked="" type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>	
Dealer	KMI		DOP	Notes <i>last GC - July 10, 2023, SJR NO. 00182134</i>					
Installer			Complaint	<i>For General Cleaning</i>					
Location	Bamboo room / daughter		Before	After					
Mode Setting (Cool)			<i>Cool</i>		No. of Visit	1st action	Tentative Sched	01/24/2024	
WAC Setting Temp(16°C-RE)/(10/12-ME)					Findings				
SAC/PAC Setting Temp (17°)			<i>17°C</i>	<i>Dirty unit</i>					
Discharge Temperature (High)			<i>13°C</i>						
Intake Temperature (High)			<i>24°C</i>						
Ampere			<i>3A</i>	Recommendation					
Wattage (Inverter)				<i>CLEAR AIR FILTER RECOMMEND</i>					
Voltage			<i>230V</i>						
SAC/PAC Pressure (PSI)			<i>110</i>						
Part Code	Description				Qty	Unit Price	Amount		
<i>NOTE: IF G.C. NEED 4 PAXS PAYMENT FOR COLLECTION & KMI KEEP DRAINS (H2O) WASH NEXT G.C. 1/28/24</i>									
SR No.					Labor	<i>1500-</i>			
Repair Done	<i>GENERAL CLEANING 0-10</i>				Handling				
					Others				
Repair Code					Total	<i>1500-</i>			
Date Attended	<i>1-24-24</i>	Date Finished	<i>1-24-24</i>	Amount Paid					
Time Attended	<i>2:11</i>	Time Finished	<i>4:10</i>	Balance	<i>1500-</i>				
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch				
Serviced by: <i>Manuel Roque Boyet Cuen</i>		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.							
<i>Boyle</i>		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
<i>BRAZOS</i>		Created by: <i>ALVIN DE PERA</i>		Conformed by: <i>ALVIN DE PERA</i>					
Technician(s)				Customer (Signature over printed name)					

HO-00185590

No. **HO-00188888**
Previous SJR No. **HO-00188888**

Customer	Dy, Danny / Daniel				Date	02-22-2024			
Address	#15 Soliven 1 Ave., Loyola Grand Villas (NEED FOR 4PAX KAPAG GENERAL MATAAS ANG PAGDADALHAN NG GAMIT), Katipunan, QUEZON CITY, Metro Manila				Start Time	03:47 pm			
Telephone No.			Mobile No.	0917-3235462		End Time	03:48 pm		
Contact Person	Danny Dy	Mobile No.	0917-3235462	Tel. No.		Warranty Type	C		
Warranty Code				Room Size		Job Class	TS	LVL	1
Model	KSM-25CB1INV			Call Origin	IO	Job Type	FD		
S/N (I)	10711011-10588		S/N (O)		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>	
Dealer			DOP		Notes *Dining Area - E5				
Installer			Complaint	E5 Error Code					
Location	Dining area		Before	After					
Mode Setting (Cool)			COOL		No. of Visit	1st action	Tentative Sched	02/23/2024	
WAC Setting Temp(16°C-RE)/(10/12-ME)					Findings				
SAC/PAC Setting Temp (17°)			17°C						
Discharge Temperature (High)			20°C						
Intake Temperature (High)			30°C						
Ampere			5.1		Recommendation				
Wattage (Inverter)									
Voltage			230						
SAC/PAC Pressure (PSI)			150PSI						
Part Code			Description	Qty	Unit Price	Amount			
(outdoor thermistor)	(0)		TEMP sensor	1pc	220	220			
<p style="text-align: center;">LIQUIDATED BY: <i>[Signature]</i> 2/23/2024 DATE: <i>[Signature]</i></p> <p style="text-align: center;">for collection <i>[Signature]</i> 2/24</p>									
SR No.	35003			Labour	1,250				
Repair Done	REPLACED OUTDOOR TEMP SENSOR TEST RUN, UNIT NORMAL OPERATION			Handling					
Repair Code				Others					
Date Attended	2-23-24	Date Finished	2-23-24	Total	1,470				
Time Attended	7:40	Time Finished	3:10	Amount Paid	FOR collection				
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch				
Serviced by: <i>Richard Talavera, Ericson V. Medina</i>		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.							
<i>TALAVERA, BERMEJO, MEDINA</i>		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
Technician(s)		Created by: ALVIN DE RIVERA CSR		Conformed by: <i>Chaloy</i> Customer (Signature over printed name)					



Customer	Dy, Danny / Daniel				Date	05-03-2024		
Address	#15 Soliven 1 Ave. , Loyola Grand Villas (NEED FOR 4PAX KAPAG GENERAL AIR CON)				Start Time	08:22 am		
3 MATAAS ANG PAGDADALHAN NG GAMIT), Katipunan, QUEZON CITY, Metro Manila					End Time	08:24 am		
Telephone No.			Mobile No.	0917-3235462		Relayed by	ADR	
Contact Person	Danny Dy	Mobile No.	0917-3235462	Tel. No.		Warranty Type	L	
Warranty Code				Room Size		Job Class	TS	LVL 1
Model	KSM-25CB1INV			Call Origin	ID	Job Type	FD	
S/N (I)	10711011-10588		S/N (O)	1072100-10240	Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>		
Dealer			DOP		Notes in back up team ref sjr HO-00199621			
Installer			Complaint	Not Cooling				
Location	Master bedroom	Before	After					
Mode Setting (Cool)	Cool	60°		No. of Visit	1st Action	Tentative Sched	05/03/2024	
WAC Setting Temp(16°C-RE)/(10/12-ME)				Findings				
SAC/PAC Setting Temp (17°)	15	17°		Weak Cooling. Fladen system w/ oil 3/4 under valve. Discharge fan stop.				
Discharge Temperature (High)	25.5	21.6						
Intake Temperature (High)	31.2	30.1						
Ampere	6.2	7.5		Recommendation				
Wattage (Inverter)				For system Reprocess on site 1pax				
Voltage	235	225		2nd Action				
SAC/PAC Pressure (PSI)	150	150						
Part Code	Description				Qty	Unit Price	Amount	
	Discharged Sensor				1	220	220	
Brin - Nitrogen gas	Treas 410A				1			
-	-							
- possible parts	-							
- mapp gas	-							
- Silver seal	-							
- Consumable copper 7/8" x 3/8"	-							
- Access valve	-							
- Union valve U-Bend 5/8" x 5/8"	-							
- A-tape - C-tape - E-tape	-							
SR No.	30359				Liquidated			
Repair Done	Replaced Discharged sensor & Fladen Fan.				DATE: 05/03/2024			
	But unit still weak cooling				Time: 08:58 am			
Repair Code								
Date Attended	May 3, 2024	Date Finished	May 3, 2024	Amount Paid				
Time Attended	12:00 pm	Time Finished	2:15 pm	Balance	For collection			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch			
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.						
Dy, Danny		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.						
Oscar		Created by: LUIS REBUYAS Conformed by: JOHN W. INGRAM						
Technician(s)		CSR Customer (Signature over printed name)						

HO-00215500



No. HO-00199621

Previous SJR No.

Customer	Dy, Danny / Daniel				Date	07-29-2024			
Address	#15 Soliven 1 Ave., Loyola Grand Villas (NEED FOR 4PAX KAPAG GENERAL 3 MATAAS ANG PAGDADALHAN NG GAMIT), Kalipunan, QUEZON CITY, Metro Manila.				Start Time...	01:04 pm			
Telephone No.			Mobile No.	0917-3235462	End Time	01:05 pm			
Contact Person	Bernice Dy	Mobile No.	0917-8123767	Tel. No.		Warranty Type	C		
Warranty Code			Room Size		Job Class	PGL	LVL	22	
Model	KSM-10CB1INV		Call Origin	IO	Job Type	FD			
S/N (I)	10651008-10419		S/N (O)	10661008-10447	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>
Dealer	KMI		DOP		Notes *water dripping *need 4 pax *Last GC - January 2024				
Installer			Complaint	For GC					
Location	Bernice room / daughter	Before	After						
Mode Setting (Cool)		COOL		No. of Visit	1st action	Tentative Sched	07/31/2024		
WAC Setting Temp(16°C-RE)/(10/12-ME)				Findings					
SAC/PAC Setting Temp (17°)		17°C	CLOSED DRAIN LINE / DIRTY UNIT						
Discharge Temperature (High)		13°C							
Intake Temperature (High)		21°C							
Ampere				Recommendation					
Wattage (Inverter)				CLEAN AIR FILTER REGULARLY					
Voltage		230V							
SAC/PAC Pressure (PSI)									

Part Code	Description	Qty	Unit Price	Amount
NOTE: NEXT CLEANING BLOWING DRAIN HOSE AND CEMENT.				
PAYMENT c/o KMI				
				
				

SR No.					Labor	\$1,500	
Repair Done	GENERAL CLEANING				Handling		
Repair Code					Others		
Date Attended	7-31-24	Date Finished	7-31-24	Total	\$1,500		
Time Attended	12:02	Time Finished	1:30	Amount Paid			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		
Serviced by: Boyet Brasas, Boyet Cuevas		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
BOYET REX		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
LITO ARJAY		Created by: ALVIN DE RIVERA CSR		Conformed by: ARLEN BRIAN ANINAN Customer (Signature over printed name)			
Technician(s)							

Customer	Dy, Danny / Daniel				Date	11-04-2024			
Address	#15 Saliven 1 Ave., Loyola Grand Villas (NEED FOR 4PAX KAPAG GENERAL CLEANING)				Start Time	10:38 am			
3 MATAAS ANG PAGDADALHAN NG GAMIT), Katipunan, QUEZON CITY, Metro Manila.									
Telephone No.			Mobile No.	0917-3235462		Relayed by	ADR		
Contact Person	Lexine Dy	Mobile No.	0917-5090539.	Tel. No.		Warranty Type	C		
Warranty Code				Room Size		Job Class	GC	LVL 1	
Model	KSM-10CB1INV			Call Origin	IO	Job Type	FD		
S/N (I)	10661008-10419		S/N (O)	10661008-10447	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>
Dealer	KMI		DOP		Notes TALAVERA				
Installer			Complaint	For GC					
Location	Bernice room / daughter	Before	After						
Mode Setting (Cool)	Cool	Cool		No. of Visit	1st Action	Tentative Sched	11/05/2024		
WAC Setting Temp(16°C-RE)/(10/12-ME)	—	—	Findings						
SAC/PAC Setting Temp (17°)	17°C	17°C	Dirty Unit / Water dripping / Clogged drain						
Discharge Temperature (High)	15°C	14°C	Broken Louver / Motor						
Intake Temperature (High)	30°C	29°C	Nasty Fan						
Ampere	3.5Amp	3.8Amp	Recommendation						
Wattage (Inverter)	—	—	FOR GC						
Voltage	230V	230V							
SAC/PAC Pressure (PSI)	135Psi	135Psi							
Part Code	Description					Qty	Unit Price	Amount	
SR No.						Labor	\$1,500.00		
Repair Done	General Cleaning / Check parameters					Handling			
	Rustest / Unit ok					Others			
Repair Code						Total	\$1,500.00		
Date Attended	11-5-24	Date Finished	11-5-24		Amount Paid	for collection			
Time Attended	12:30 pm	Time Finished	1:30		Balance	100			
This serves as temporary receipt when properly filled up by authorized representative.			Check No.		Bank / Branch				
Serviced by: Richard Talavera, Michael V.		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.							
TALAVERA VISTAN		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
RIVERO BERMEO		Created by: LUIS REBUNAS CSR		Conformed by: 			Customer (Signature over printed name)		
Technician(s)									

No.
Previous S.I.R No

HO-00245203



Customer	Dy. Danny / Daniel				Date	03-10-2025				
Address	#15 Soliven 1 Ave. Loyola Grand Villas (NEED FOR 4PAX KAPAG GENERAL CALANIN)				Start Time	03:51 pm				
3 MATAAS ANG PAGDADALHAN NG GAMIT 1. Katipunan, QUEZON CITY, Metro Manila										
Telephone No.			Mobile No.	0917-3235482		Relayed by	Ms. Bernice - 0917-812...			
Contact Person	Bernice Dy	Mobile No.	0917-8123767	Tel. No.		Warranty Type	C			
Warranty Code				Room Size		Job Class	GC	LVL		
Model	SAC-REG XSG 1250B1G			Call Origin	MH	Job Type	FD			
S/N (I)	10071011-10587		S/N (O)		Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input checked="" type="checkbox"/>	O.R.? <input checked="" type="checkbox"/>	Ladder? <input type="checkbox"/>	
Dealer			DOP	Notes		JH Villafuerte - pls verify model name and serial number on site (Location: Guest Room Split type)				
Installer			Complaint	Water Dripping						
Location	MASTER BED RM		Before	After						
Mode Setting (Cool)	COOL	COOL		No. of Visit	1st Action	Tentative Sched		03/14/2025		
WAC Setting Temp(16°C-RE)/(10/12-ME)	Findings									
SAC/PAC Setting Temp (17°)	17°C	17°C	DIRTY UNIT							
Discharge Temperature (High)	13°C	15°C								
Intake Temperature (High)	24°C	25°C								
Ampere	10	11	Recommendation							
Wattage (Inverter)	CLEAN AIR FROM REGULATORY									
Voltage	230	220								
SAC/PAC Pressure (PSI)	50	60								
Part Code	Description					Qty	Unit Price	Amount		
<p>NOTE: FOR COLLECTION C/O KM1</p> <p>DATA COLLECTED BY SICKS</p> <p>3/17</p>										
SR No.						Labor	1500-			
Repair Done	GENERAL CLEANING ONLY					Handling				
						Others				
Repair Code						Total	1500-			
Date Attended	3-14-25	Date Finished	3-14-25	Amount Paid						
Time Attended	8:15	Time Finished	10:00	Balance						
This serves as temporary receipt when properly filled up by authorized representative.					Check No.	Bank / Branch				
Serviced by: Gary Munday, Neil Villafuerte		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.								
Salomon		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.								
Technician(s)		Created by: Shirley Anne B. Gom...		Conformed by: <i>Shirley Anne B. Gom...</i> Customer (Signature over printed name)						

No. **HO-00245899**
Previous SJR No.

Customer	Dy, Danny / Daniel				Date	03-14-2025			
Address	#15 Soliven 1 Ave., Loyola Grand Villas (NEED FOR 4PAX KAPAG GENERAL) 3 MATAAS ANG PAGDADALHAN NG GAMIT), Katipunan, QUEZON CITY, Metro Manila				Start Time	12:57 pm			
Telephone No.			Mobile No.	0917-3235462		End Time	01:01 pm		
Contact Person	Nana Dy	Mobile No.	0917-5090772	Tel. No.		Warranty Type	C		
Warranty Code				Room Size		Job Class	GC	LVL	1
Model	SAC-REG. KIM-10715-GHIM		Call Origin	MH	Job Type	FD			
S/N (I)	18852103-22131		S/N (O)		Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>
Dealer			DOP		Notes VILLAFUERTE PLS UPDATE MODEL & LOCATION ON SITE				
Installer			Complaint	For GC					
Location			Before	After					
Mode Setting (Cool)					No. of Visit	1st Action	Tentative Sched	03/17/2025	
WAC Setting Temp(16°C-RE)/(10/12-ME)					Findings				
SAC/PAC Setting Temp (17°)	17		17		DIRTY UNIT				
Discharge Temperature (High)	14.2		14.6						
Intake Temperature (High)	27.1		27.9						
Ampere	3.7		3.8		Recommendation				
Wattage (Inverter)					CLEAN FILTER REGUARLY				
Voltage	220		220						
SAC/PAC Pressure (PSI)	140		140						
Part Code	Description				Qty	Unit Price	Amount		
SR No.					Labor	1,500			
Repair Done	GENERAL CLEANING, MUN TEST				Handling				
Repair Code	WUT CLR!				Others				
Date Attended	03-17-25	Date Finished	03-17-25	Amount Paid					
Time Attended	9:00 AM	Time Finished	10:00	Balance	1,100				
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch				
Serviced by: Garry Munday, Neil Villafuerte		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.							
Technician(s)		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
Technician(s)		Created by: LUIS REBUYAS CSR	Conformed by: AKLON, K. BANNA Customer (Signature over printed name)						

No.	HO-00253829										
Previous SJR No.	HO-00245201										
Customer	Dy. Danny / Daniel			Date	05-02-2025						
Address	#15 Saliven 1 Ave., Loyola Grand Villas (NEED FOR 4PAX KAPAG GENERAL MATAAS ANG PAGDADALHAN NG GAMIT), Katipunan, QUEZON CITY, Metro Manila			Start Time	01:27 pm						
Telephone No.			Mobile No.	0917-3235462		End Time	01:28 pm				
Contact Person	Bernice Dy	Mobile No.	0917-8123767	Tel. No.			Warranty Type	C			
Warranty Code				Room Size			Job Class	GC	LVL	1	
Model	KSM-25CB1INV			Call Origin	MH		Job Type	FD			
S/N (I)			S/N (O)	1072100-10240		Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input checked="" type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>	
Dealer			DOP			Notes IH Villafuerte -apt -pls verify model name and serial number on-site (location: master bedroom)					
Installer			Complaint	For GC							
Location	Master bedroom	Before	After								
Mode Setting (Cool)	COOL	COOL		No. of Visit	1st Action			Tentative Sched	05/07/2025		
WAC Setting Temp(16°C-RE)/(10/12-ME)			Findings								
SAC/PAC Setting Temp (17°)	17°C	17°C	DIRTY UNIT								
Discharge Temperature (High)	15°C	13°C									
Intake Temperature (High)	27°C	25°C									
Ampere	10.5A	12.1A	Recommendation								
Wattage (Inverter)			CLEAN AIR FILTER FEEUARILY								
Voltage	230V	230V									
SAC/PAC Pressure (PSI)	30PSI	25PSI									
Part Code	Description			Qty	Unit Price	Amount					
SR No.							Labor	1,500			
Repair Done	GENERAL CLEANING						Handling	1,500			
Repair Code							Others	1,500			
Date Attended	5-8-25	Date Finished	5-8-25	Amount Paid		1,500					
Time Attended	9:30	Time Finished	10:50	Balance		1,500					
This serves as temporary receipt when properly filled up by authorized representative.				Check No.			Bank / Branch				
Serviced by: <u>Gerry Munday, Neil Villafuerte</u>		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.									
NEIL		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.									
GARRY		Created by: <u>Sherry Anne B. Gom...</u> Conformed by: <u>DANWY, DX</u>									
Technician(s)		Customer (Signature over printed name)									

No. **HO-00256122**
Previous SJR No. **HO-00245201**

Customer	Dy, Danny / Daniel				Date	05-16-2025	
Address	#15 Soliven 1 Ave., Loyola Grand Villas (NEED FOR 4PAX KAPAG GENERAL 3 MATAAS ANG PAGDADALHAN NG GAMIT), Katipunan, QUEZON CITY, Metro Manila				Start Time	07:38 am	
Telephone No.			Mobile No.	0917-3235462	End Time	07:45 am	
Contact Person	Bernice Dy	Mobile No.	0917-8123767	Tel. No.	Relayed by CUEVAS		
Warranty Code				Room Size	Job Class		TS LVL 3
Model	KFG-40F1			Call Origin	SA	Job Type	FD
S/N (I)	Faded	S/N (O)	10281004-14541	Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>		
Dealer	KMI	DOP		Notes CUEVAS Findings - Outdoor unit not running , Recommendation - For 2nd action bring all possible parts and royal cord 4C , Repair Done - Try to replaced all parts and communication wire still not working / Payment upon completion			
Installer		Complaint	Not Cooling				
Location	Living Room	Before	After				
Mode Setting (Cool)		Cool		No. of Visit	3rd Action	Tentative Sched	05/20/2025
WAC Setting Temp(16°C-RE)/(10/12-ME)				Findings			
SAC/PAC Setting Temp (17°)		17°C		compressor Not Running			
Discharge Temperature (High)		14					
Intake Temperature (High)		27					
Ampere		21		Recommendation			
Wattage (Inverter)				clean A/C filter Regularly			
Voltage		230					
SAC/PAC Pressure (PSI)		75					
Part Code	Description			Qty	Unit Price	Amount	
	Capacitor 98uF			1	550	550	
	Display Board			1	2,200	2,200	
	AC contactor			1	1,600	1,600	
	PCB Indoor board			1	1,735	1,735	
Note: payment for collection							
Send SDA  LIQUIDATION DATE:  5/21/25							
SR No.	45479			Labor	₱ 2,300		
Repair Done	Replaced parts mention above			Handling			
				Others			
Repair Code				Total	₱ 8,385		
Date Attended	5-20-25	Date Finished	5-20-25	Amount Paid			
Time Attended	12:30	Time Finished	2:05	Balance	₱ 8,385		
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		
Serviced by: <i>Jeselito Bracas, Bayet Cuevas</i>		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
<i>Bayet</i>		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
<i>Joel</i>		Created by: <i>RECHILLA</i>	Conformed by: <i>ALLEN</i>	Customer (Signature over printed name)			
Technician(s)		CSR					