

# kolin

air conditioner

29-Oct-2021

**ATTN: MS. ASUNCION YAP**

UNIT 7, #51 JOSE ABAD SANTOS ST. HEROES HILL SUBD., QUEZON CITY

**TEL: 0917-858-8550**

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of OCTOBER 2021.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
26-Jun-21	HO-00070798	(1) KSM-SW20-5G1M	Installation Indoor & Outdoor	17,630.00
26-Jun-21	HO-00070799	(1) KSM-SW20-5G1M	Installation Indoor & Outdoor	14,615.00
26-Jun-21	HO-00070800	(1) KSG-SW30-6H1M	Installation Indoor & Outdoor	16,235.00
09-Oct-21	HO-00082736	(1) KSM-15CB1INV	Installation Indoor & Outdoor	12,670.00
09-Oct-21	HO-00082910	(1) KSM-15CB1INV	Dismantle of Outdoor Unit	1,250.00
<b>TOTAL</b>				<b>P 62,400.00</b>
<b>LESS: DISCOUNT</b>				<b>(3,120.00)</b>
<b>TOTAL AMOUNT DUE</b>				<b>P 59,280.00</b>

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

**Note:** If check payment, please prepare check payable to **Kolin Philippines International Inc.**

**Account #: BDO - KALAYAAN**

**011808000428**

**Note:** In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi\_asst@kolinphil.com.ph**

Prepared by:

*Gina 11/02/21*  
**Gloria Tiffany T. Abesamis**  
KMI - Accounting Assistant

Noted by:

*Mart Nathaniel R. Flores*  
**Mart Nathaniel R. Flores**  
KMI - Assistant Supervisor

Received by:

**KOLIN PHILS. INT'L., INC.**

Plant and Office:  
Blk 3 Lt 5 Main Drive, FCIE Compound,  
Brgy, Langkaan I, Dasmariñas, Cavite

Tel.: (632) 8749-2118

Fax: (046) 402-0793

www.kolinphil.com.ph / kolinphilippines

Operations Office:

1854 Sta. Rita St., Guadalupe Nuevo,  
Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791

**25<sup>th</sup>**  
**ANNIVERSARY**  
EST. 1996

Bringing comfort to your home.

Kolin Philippines International Inc.  
1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
Tel. No. 8852-6868 / Mobile: 0917-8118982 / Email: [service@kolinphil.com.ph](mailto:service@kolinphil.com.ph)  
Website: [www.kolinphil.com.ph](http://www.kolinphil.com.ph)

No. \_\_\_\_\_  
Previous SJR No. \_\_\_\_\_

SVC-SJR-01-100119      White - Customer      Blue - Accounting      Green - Service      Yellow - Guard / Claim Study

Kolin Philippines International Inc.  
1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
Tel. No. 8852-6868 / Mobile: 0917-8118982 / Email: [service@kolinphil.com.ph](mailto:service@kolinphil.com.ph)  
Website: [www.kolinphil.com.ph](http://www.kolinphil.com.ph)

No.	70794
Previous SJR No.	


SVC-SJR-01-100119

White - Customer

**Blue - Accounting**

**Green - Service**

Yellow - Guard / Claim Stub

Customer				No. <b>7080</b>			
Address <b>Y30, Asuncion</b>				Previous SJR No.			
Unit 7, #51 Jose Abad Santos St., Heroes Hill Subdivision, Quezon Ave. QUEZON CITY				Date <b>HO-0070800</b>			
Tel. No. <b>ITV, Metro Manila</b>				Start Time <b>06:23:2021</b>			
Mobile No.				End Time <b>07:26 pm</b>			
Contact Person <b>0917-8588550</b> Mobile No. Tel. No.				Relayed by <b>02:27 pm</b>			
Model <b>MS. ASUNCION</b> <b>0917-8588550</b>				Warranty Type <b>KMI</b>			
S/N (I) <b>KSG-SW30-SH1M</b> S/N (O)				Job Class <b>C</b>			
Dealer <b>10212012-10524</b> DOP <b>10222012-10340</b>				Job Type <b>NET</b>			
Installer <b>KMI</b> Complaint <b>06/21/2021</b>				Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>			
Fernando Lopez Before After For Ins				Tentative Sched <b>LOPEZ TRANSFER TO TALAVERA</b>			
Mode Setting (Cool)				Findings <b>06/26/2021</b>			
WAC Setting Temp(16°C-RE)/(10-ME)				1st Action			
SAC/PAC   Setting Temp (17°)				Recommendation			
Discharge Temperature (High)				for installation / to start-up			
Intake Temperature (High)							
Ampere							
WAC   Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure							
Part Code		Description		Qty	Unit Price	Amount	
		C. tube 1/4 x 1/8		30ft	300	7,000	
		1 Cord 2.0mm x 40		43ft	35	1,155	
		Stick 455 tape		5			
		piping clamp (S)		5			
		piping clamp (S)		8			
		Mount bracket 30mm		1			
		Wall bracket installation (S)		1			
		1 Cord 3.5mm x 30		7ft	40	280	
		Floor 410 (A)		1			
		LIQUIDATED					
		BY: 					
		DATE: <b>6/26/21</b>					
SR No.		initial charge		Labor		7,000	
Repair Done		installation indoor and outdoor unit		Handling			
Repair Code		to start-up		Others			
Date Attended <b>June 25, 2021</b>		Date Finished <b>June 26, 2021</b>		Total		16,235	
Time Attended <b>8:55 AM</b>		Time Finished <b>3:50 PM</b>		Amount Paid			
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch		to collect	
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.					
Talavera		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Borner		Created by:		Conformed by:			
Technician(s)		ARCHIE ALARCON		Customer <b>Kasulayan Datin</b>			
				(Signature over printed name)			



Kolin Philippines International Inc.  
1854 Sta. Rita St. dalupe Nuevo, Makati City  
Tel. No. 8852-686 Mobile: 0917-8118982 / Email: service@kolinphil.com.ph  
Website: www.kolinphil.com.ph

# SERVICE JOB REPORT

No.

Previous SJR No.

10-0502738

10-0502738

82724

Customer	Fap. Asuncion				Date	10-07-2021	
Address	Unit 7, 101 Jose Abad Santos St., Heroes Hill Subdivision, Quezon Ave, Quezon City				Start Time	02:30 pm	
	111, Metro Manila				End Time	02:41 pm	
Tel. No.					Relayed by	Engr. Karel	
Mobile No.	0917-8588550				Warranty Type	C	
Contact Person	MS. ASUNCION	Mobile No.	0917-8588550	Tel. No.		Job Class	INST
Model	ASM-15CB11W			Call Origin	10	Job Type	FI
S/N (I)		S/N (O)		Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>
Dealer		DOP		Notes: TALavera / FOR INSTALLATION /			
Installer	METERS ROYAL COND / NO DSAT / NO TAB		Complaint	FOR INSTALLATION BRIMS 4 METERS COPPER TUBE AND 6			
	Before	After	No. of Visit	1st Action	Tentative Sched	10/09/2021	
Mode Setting (Cool)				Findings			
WAC Setting Temp (16°C-RE) / (10-ME)							
SAC/PAC   Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)				Recommendation			
Ampere				for installation, for start-up			
WAC   Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure							
Part Code	Description			Qty	Unit Price	Amount	
	C. tube 1/2 x 7/4			11ft	80	880	
	C. COND 2.0mm x 4C			18ft	50	900	
	C. COND 3.5mm x 3C			7ft	60	420	
	C. Bracket 20amp			1			
	Wall bracket (0) installer			1			
	stickers tape			1			
	piping clamp (S)			1			
	piping clamp (O)			1			
	pvc pipe 3/4 x 10			2			
	pvc elbow 3/4			4			
<b>LIQUIDATED</b>							
BY:							
DATE:	10/9/21						
SR No.	initial change				Labor	7500	
Repair Done	Installation indoor & outdoor				Handling		
	hugf. for start-up				Others		
Repair Code					Total	12,670.00	
Date Attended	Oct. 9, 2021		Date Finished	Oct. 9, 2021		Amount Paid	
Time Attended	10:30 AM		Time Finished	1:10 PM		Balance	12,670.00
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		
Serviced by:				By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its Implementing rules & regulations.			
Talavera, Mervina				I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Valle				Created by: ARTICA			
Technician(s)				CSR		Conformed by: Jerome	
						Customer (Signature over printed name)	

Kolin Philippines International Inc.  
1854 Sta. Rita St. Alajuela, San Jose, Costa Rica  
Tel. No. 8852-6866 Mobile: 0917-8118962 / Email: [service@kolinphil.com.ph](mailto:service@kolinphil.com.ph)  
Website: [www.kolinphil.com.ph](http://www.kolinphil.com.ph)

**No.**  
**Previous SJR No.**

SVC-SJR-01-100119

White - Customer

Blue - Accounting

Green - Service

Yellow - Guard / Claim Stub