



N.V.F.S MAINTENANCE AIRCON & REFRIGERATION SYSTEM TRADING
MANILA: Office Unit Q Monserrat St B.F. Homes Phase 1 Sucat Rd Paranaque
+639171163534 | +639455920222 | +632 85146379
E-mail: sales@about-nvfs-ph.com | inquiry@about-nvfs-ph.com
www.nvfs-ph.com
TIN Number: 305-342-355-00000

QOUTATION

TO : Patts College Of Aeronautics

ADDRESS: Lombos St., Brgy. San Isidro, PARAÑAQUE CITY, Metro Manila

REFERENCE NO:

DATE : August 13, 2024

CUSTOMER NO : 0933-8120909 / 0995-3650589

Repair Code	BRAND AND ITEM DESCRIPTION	QTY	UNIT	UNIT PRICE	GROSS AMOUNT	DISCOUNT	NET PRICE
*	Room 311 - KSG-250B1G - Kolin Wall Mounted						
*	Compressor	1	Set	P10,700.00	P10,700.00		P10,700.00
10.5	System Reprocess	1	Set	P3,500.00	P3,500.00		P3,500.00
						Total:	P14,200.00

Mode of Payments

	Cash, Gcash, maya
	Bank Transfer or Check Payment under: NVFS Maintenance Aircon & Refrigeration System Trading
	BDO Account 004128020472 President's Avenue BF Paranaque Branch
	Metrobank Account 034-7-03452574-5 BF Homes Aguirre Branch

TERMS & CONDITIONS

- Unit Price are VAT Inclusive.
- Price are subject to change after sales offer validity which seven (7) days from the date of issue.
- We need 50% down payment to process the parts needed/request.

WARRANTY

- Parts has no warranty if installed by Unauthorized Service Center of Panasonic/Kolin or Technician.

Ryan L. Guerra

NVFS Maintenance Aircon and Refriegration System Trading

Date :

Conforme:


Client's Signature over Printed Name / Date

AUTHORIZED DEALER OF THE FOLLOWING BRANDS



AUTHORIZED SERVICE CENTER OF THE FOLLOWING BRANDS





kolín
AUTHORIZED SERVICE CENTER

Model No:	D.O.P
S/S (I)	S/S (O)
Product Type	16071602-12915

KK-250BAC-0
1608A08-11314

Permit	Appointment
Ladder	Trolley
Parking	O.R

Location : Room 311

Room 311

1

	Retail Shop
	Commercial Shop
	Construction Site
	Production Area

CM-LP-0455

Email:	
Mobile No.	0933-8120909 / 0995-3650589

Job Service History:

CHECK UP SAC

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There are no margins, text, or other markings on the paper.

Robert Curison Signature:

Signature: R. I. GAN

Repair Done:

REPAIR COMPLETED		WARRANTY NO OF MONTHS					
		3	6	12	24	36	60
YES							
	N/A						

Amount Paid	Total
FOR SOA	
Balance	

P430.00		

PARAMETERS		Before	After	Findings
Room Temperature / Mode Settings(Cool)				
WAC/ Settings Temp (16°C-RE)(10-ME)				
SAC/PAC Settings Temp °C				
Discharge Temperature °C				
FC / Intake Temperature °C				
Ampere				
WAC/ Wattage (Inverter)				*FOR REPLACEMENT OF COMPRESSOR SYSTEM REFRIGERANT R-22.
SAC/PAC / Pressure				
Voltage			230V	NOED SAFETY HAZARDS.

03 AUG 2024
FOR QUOTATION

504