



7-Oct-2024

**HARDWORKERS MANPOWER SERVICES**

U105 G/F ZEN TOWER, 1111 NATIVIDAD LOPEZ ST., BRGY. 659-A ERMITA, MANILA

TEL: 0917-8719889 / 0927-2473312

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of SEPTEMBER 2024.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
25-Sep-24	HO-00222861	(1) KSM-IW25-WCT10M1M32	INSTALLATION	33,120.00
25-Sep-24	HO-00222862	n/a	DISMANTLING	2,500.00
25-Sep-24	HO-00223438	(1) KSM-IW25-WCT10M1M32	PULL OUT OF SCAFFHOLDING	1,800.00
TOTAL				P 37,420.00
LESS: DISCOUNT				(2,619.40)
TOTAL AMOUNT DUE				P 34,800.60

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**


**Note:** If check payment, please prepare check payable to **Kolin Philippines International Inc.**

**Account #: BDO - KALAYAAN**


**011808000428**

**Note:** In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi\_asst@kolinphil.com.ph**

Prepared by:

  
**Janelle S. Lim**  
KMI - Assisitant

Noted by:

  
**Mar Nathaniel R. Flores**  
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,  
Brgy. Langkaan I, Dasmariñas, Cavite

Tel.: (632) 8749-2118

Fax (046) 402-0793

[www.kolinphil.com.ph](http://www.kolinphil.com.ph) / [kolinphilippines](mailto:kolinphilippines)

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,  
Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170


Sales Dept. Fax: (632) 8852-4791





Customer		Handworkers Manpower Services Inc.		No. Previous SJR No.		HO-00222861	
Address		U106 G/F Zen Tower, 1111 Natividad Lopez St., Brgy. 659-A, Ermita, MANILA CITY		Date		09-19-2024	
Metro Manila				Start Time		11:19 am	
Telephone No.		Mobile No.		End Time		11:22 am	
		0917-8719889		Relayed by		Donna- KMI	
Contact Person		Mobile No.		Warranty Type		C	
Sammy		0917-8719889		Room Size			
Warranty Code				Job Class		INST LVL 2	
Model		KSM-IW25-WCT10M1M32		Job Type		FD	
S/N (I)		S/N (O)		Permit?		Parking?	
18672406-10576		18682907		<input type="checkbox"/>		<input type="checkbox"/>	
Dealer		DOP		Appointment?		O.R.?	
KMI		09/19/2024		<input type="checkbox"/>		<input type="checkbox"/>	
Installer		Complaint		Ladder?		<input type="checkbox"/>	
		For installation		Notes		Talavera FOR INSTALL DOP: 09/19/2024 EDD: 09/24/2024 PAYMENT COLLECTION C/O CUSTOMER DIRECT TO TECHNICIAN FOR REFERRAL KINDLY ADVISE CLIENT AHEAD OF TIME	
Location		Before		After			
ACCOUNTING ROOM							
Mode Setting (Cool)				No. of Visit		Tentative Sched	
				1st Action		09/25/2024	
WAC   Setting Temp (16°C-RE)/(10/12-ME)				Findings			
SAC/PAC   Setting Temp (17°)				For installation			
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere				Recommendation			
Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
		✓ Copper tube 1/4 x 1/2		60 ft.		50 x P 350 = P 17,500.00	
		✓ Royal cord 2mm x 4c		67 ft.		57 x P 100 = P 5,700.00	
		✓ s-tape		1			
		* R-92		1		Re-182400	
		✓ Wall bracket		1			
		✓ Circuit breaker 30A		1		P 1,000.00	
		✓ P-clamp (S)		10			
		✓ P-clamp (D)		10			
		✓ Drain hose		7 ft.			
		✓ Royal cord 3.5mm x 3c		7 ft.		7 x P 60 = P 420.00	
		less 71.				P 8,500.00	
SR No.		40120		Labor		P 8,500.00	
Repair Done		Installed unit / FOR MONT LIQUIDAT		Handling			
KID POWER SUPPLY				Others			
Repair Code				Total		P 33,120.00	
Date Attended		Date Finished		Amount Paid		P 33,120.00	
9-25-24				Balance			
Time Attended		Time Finished		Bank/Branch			
9:15am							
This serves as temporary receipt when properly filled up by authorized representative.				Check No.			
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
TALAVERA VISTAN		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
RIVERO GUTIERREZ		Created by:		Conformed by:		Customer (Signature over printed name)	
Technician(s)		KATHY DE GUZMAN		CSR			





1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: [service@kolinphil.com.ph](mailto:service@kolinphil.com.ph)  
Website: [www.kolinphil.com.ph](http://www.kolinphil.com.ph)    [kolinphilippines](https://www.facebook.com/kolinphilippines)

## SERVICE JOB REPORT

No.	HO-00222862
Previous SJR No.	HO-00222181

Customer	Hardworkers Manpower Services Inc.				Date	09-19-2024									
Address	U105 G/F Zen Tower, 1111 Natividad Lopez St., Brgy. 859-A, Ermita, MANILA CITY				Start Time	11:22 am									
Metro Manila...					End Time	11:23 am									
Telephone No.				Mobile No.	0917-8719889		Relayed by	Donna- KMI							
Contact Person	Sammy	Mobile No.	0917-8719889		Tel. No.			Warranty Type	C						
Warranty Code					Room Size			Job Class	DSM LVL 1						
Model	n/a				Call Origin	IC		Job Type	FD						
S/N (I)			S/N (O)			Permit?	<input type="checkbox"/>	Parking?	<input type="checkbox"/>	Appointment?	<input type="checkbox"/>	O.R.?	<input type="checkbox"/>	Ladder?	<input type="checkbox"/>
Dealer			DOP			Notes	Talavera For dismantle of 1.5HP								
Installer			Complaint	Others											
Location			Before	After											
Mode Setting (Cool)					No. of Visit	1st Action		Tentative Sched	09/25/2024						
WAC   Setting Temp(16°C-RE)/(10/12-ME)					Findings										
SAC/PAC   Setting Temp (17°)															
Discharge Temperature (High)															
Intake Temperature (High)															
Ampere					Recommendation										
Wattage (Inverter)															
Voltage															
SAC/PAC   Pressure (PSI)															

[illegible]

SR No.				Labor	\$ 2,500.00
Repair Done	Dismantled unit			Handling	
				Others	
Repair Code				Total	7,500
Date Attended	9-25-24	Date Finished	9-25-24	Amount Paid	FOR collection
Time Attended	9:15am	Time Finished		Balance	2,500
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank/ Branch

Served by: <u>Richard Talavera, Michael V. Reyes</u>		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.	
<u>TALAVERA</u> <u>WISAN</u>		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.	
<u>REYES</u>	<u>GUTIERREZ</u>	Created by:  <u>KATHY DE GUZMAN</u> CSR	Conformed by:  <u>Jocelyn S. Sanchez</u> Customer (Signature over printed name)
Technician(s)			



# Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph  
Website: www.kolinphil.com.ph

## SERVICE JOB REPORT

Customer		Hardworkers Manpower Services Inc.		No. Previous SJR No.		HO-00223438	
Address		U105 G/F Zen Tower, 1141 Natividad Lopez St., Brgy. 859-A, Ermita, MANILA CITY		Date		09-24-2024	
Telephone No.		Mobile No. 0917-8719869		Start Time		10:19 am	
Contact Person		Mobile No. 0917-8719899		End Time		10:22 am	
Warranty Code		Room Size		Relayed by		OADIOS	
Model		Call Origin		Warranty Type		C	
S/N (I)		S/N (O)		Job Class		SCF LVL 1	
Dealer		DOP		Job Type		FD	
Installer		Complaint		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>			
Location		Before After		Notes		TALAVERA BRING SCAFFOLDING 3 LAYERS	
Mode Setting (Cool)		No. of Visit		Tentative Sched		09/25/2024	
WAC   Setting Temp (16°C-RE)/(10/12-ME)		Findings					
SAC/PAC   Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere		Recommendation					
Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
SR No.		Labor				P1,800.00	
Repair Done		Used scaffolding (4 layers)		Handling			
Repair Code		Others		Total		1,800	
Date Attended		Date Finished		Amount Paid		For collection	
Time Attended		Time Finished		Balance		1,800	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
TALAVERA VISTAN		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
RIVERA GUTIERREZ		Created by:		Conformed by:		Customer	
Technician(s)		LUIS REBUCAS CSR		(Signature over printed name)			