

**KOLIN PHILIPPINES INTERNATIONAL INC.**

1854 Sta. Rita St., Guadalupe Nuevo,

1212 Makati City

EMAIL ADDRESS: inhouse.shop@kolinphil.com.ph

TEL.: (02)8-9625610

MOBILE: (+63)9178060920

REPAIR COST ESTIMATE**CUSTOMER:****IRANG, IVEE**

1600A CAMINO DELA FE ST. BRGY. GUADALUPE NUEVO

MAKATI CITY, METRO MANILA

TEL#:

MOBILE:0977-3835921

DATE:	MARCH 11 2025
SJR #:	HO-00244849
MODEL:	KAG-110RSINV
DOP:	CHARGEABLE
SERIAL#:	FADED

TERMS AND CONDITION

1. The repair will proceed after indicating acceptance of this quote with 50% downpayment.
2. Customer shall conform within 2 working days otherwise unit will be considered refuse to repair hence, unit will be delivered back un-repaired with fitting charges.
3. Kindly deposit your 50% down-payment to the bank account: Reference SJR# HO-00244849 (Not Bills Payment)

BDO

Account Name: Kolin Philippines International Inc.

Account Number: 0118-0800-0428

4. Should any additional work or materials be found necessary in the course of these repairs or subsequent testing, it will be necessary to make an extra charge. Where this additional work involves a substantial increase in the amount estimated, a supplementary estimate will be submitted for acceptance.

5. Repaired units are guaranteed for a period of 90 days (**Parts & Labor**) from date of unit acceptance and for the same encountered defects.

6. If you have any questions about this price quote, please contact under signed **Paolo Jose Lu** (02)8-9625610 or (+63)9178060920 and "inhouse.shop@kolinphil.com.ph".

7. Payment of remaining 50% balance will be due upon delivery/pick-up of unit.

8. Please email the signed price quote to the address above.

Customer Acceptance and return.(sign below)

X

Print Name:

DESCRIPTION**AMOUNT**

[LABOR] System Reprocess + General Cleaning (Part Replacement / Dirty Unit)	P	2,600.00
[PARTS] Evaporator (Leaking & Icing)	P	3,300.00
[PARTS] Condenser (Leaking)	P	4,000.00
[PARTS] Compressor Lead Wire (Defective)	P	650.00
Handling Fee within Metro Manila	P	500.00

SUBTOTAL P 11,050.00

Less: Check Up Fee SJR Ref # HO-00244362 P 450.00

GRAND TOTAL P 10,600.00

Prepared by

PAOLO JOSE LU
SHOP ASSISTANT

Reviewed by:

GARIE PUIG
SHOP FOREMAN

Noted by:

ENGR. KENNETH ZAMORA
SERVICE SUPERVISOR**K** Kolin Philippines Int'l., Inc.

Plant and Head Office:

Bldg 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite

Tel.: (632) 8749-2118

Fax (046) 402-0793

www.kolinphil.com.ph / kolinphilippines

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,
Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791

