

Customer		Chua, Fina		Date		09-24-2024	
Address		Unit 2 & 4, 14 Lantana St., Brgy. New Manila, QUEZON CITY.		Start Time		03:38 pm	
				End Time		03:39 pm	
Telephone No.				Mobile No.		0917-5252177	
Contact Person		Fina		Mobile No.		0917-5252177	
Warranty Code				Tel. No.			
Model		n/a		Room Size			
S/N (I)				Call Origin		TF	
Dealer				Permit?		<input type="checkbox"/>	
Installer				Parking?		<input type="checkbox"/>	
Location		Before		Appointment?		<input type="checkbox"/>	
Mode Setting (Cool)				O.R.?		<input type="checkbox"/>	
WAC Setting Temp (16°C-RE)/(10/12-ME)				Ladder?		<input type="checkbox"/>	
SAC/PAC Setting Temp (17°)				Notes			
Discharge Temperature (High)				IH-Dadios Note: Yung sa master's bedroom yun yung tatanggalin tapos ililipat sa office nila na'am sa QC, tapos yung ilalagay sa master's bedroom mangagaling sa baba nila same address, customer is also requesting for discount.			
Intake Temperature (High)				No. of Visit		1st Action	
Ampere				Tentative Sched		09/25/2024	
Wattage (Inverter)				Findings			
Voltage							
SAC/PAC Pressure (PSI)				Recommendation			
				NEED TO PHC-UM WAIT FOR SAPP REPAIR (KSG-SW30-6H/M) IN LANTANA, QC.			
Part Code		Description		Qty		Unit Price	
		KSG-SW30-6H/M					
		TO BE INSTALLED AT MASTER BEDROOM					
SR No.				Labor		500	
Repair Done		SWAP X/M		Handling			
Repair Code				Others			
Date Attended		9-25-24		Total		500	
Time Attended		10:45 AM		Amount Paid		FOR COLLECTION	
Date Finished		9-25-24		Balance		C/O K/M	
Time Finished		11:30 AM		Bank / Branch			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.			
Served by: Jeffrey Dadios		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Technician(s)		ERICA C. CALIBOT CSR		Conformed by:		And C. Antina Customer (Signature over printed name)	