

Customer		Supreme Care Medical Diagnostic Center		Date		HO-00120371 HO-00117003 2022	
Address		92 Claudio St., Brgy. San Juan LM NEAR RIZAL PROVINCIAL HOSPITAL, MARIKINA		Start Time		11:20 am	
Tel. No.				End Time		11:43 am	
Mobile No.				Relayed by		Kmi	
Contact Person		Mobile No. 0917-3124887		Tel. No. 0917-3124887		Warranty Type	
Model		KSG-IWE-25WEY-8K1M324		Job Class		INST	
S/N (I)		18492112-10466		Job Type		ED	
S/N (O)		18502112-1047		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>			
Dealer		KMI		Notes:		LOPEZ / MARKINGS BY TEAM LOPEZ	
Installer		Complaint		DOP		07/27/2022	
Before		After		No. of Visit		Tentative Sched	
Mode Setting (Cool)				Findings		08/10/2022	
WAC Setting Temp(16°C-RE)/(10-ME)				Location		CT 590	
SAC/PAC Setting Temp (17°)				Recommendation			
Discharge Temperature (High)				For start-up		wait Customer Call	
Intake Temperature (High)				Voltage			
Ampere				SAC/PAC Pressure			
WAC Wattage (Inverter)				Part Code		Description	
Voltage				Qty		Unit Price	
SAC/PAC Pressure				Amount			
Liquitated		8/10/2022		Copper Tube 5/8" x 1/4"		29' 19' x 400 7,600	
BY:		DATE:		P-cord 2mm x 4L		136' 26' x 50 1,300	
				W/supply P-cord 3.5mm x 2L		14' 60 240	
				Rubber insulation 2 1/8" x 3/4" x 6'		13 350 1,050	
				Mobilization		1 800	
				S-tape		13	
				Clamp (S)		15	
				Clamp (D)		15	
				Elbow 3/4"		12	
				Circuit Breaker (30)		1	
				Wall Bracket (L)		1	
				Pvc pipe 3/4" x 10'		1	
SR No.				Labor		5,500	
Repair Done		Install indoor & Out door unit		Handling			
Repair Code				Others			
Date Attended		August 10, 2022		Total		16,490.00	
Time Attended		9:30 am		Amount Paid			
Date Finished		August 11, 2022		Balance			
Time Finished		5:35 pm		Bank / Branch			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.			
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.					
Kevin		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Lib		Created by:		Conformed by:			
Arjay		ARCHIE ARTIGA CSR		Daven Customer (Signature over printed name)			

Customer		Date		No.		120370	
Address		Start Time		Previous SJR No.		HO-00120373	
82 Claudio St., Brgy. San Juan LM. NEAR RIZAL PROVINCIAL HOSPITAL, MARIKINA CITY		End Time		Date		HO-00117003	
Tel. No.		Relayed by		Start Time		08-09-2022	
Mobile No.		Warranty Type		End Time		11:43 am	
Contact Person		Job Class		Relayed by		Kini	
Model		Job Type		Warranty Type		C	
S/N (I)		S/N (O)		Job Class		INST	
Dealer		DOP		Job Type		FD	
Installer		Complaint		Notes:		O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>	
Before		After		Notes:		07/12/2022	
Mode Setting (Cool)		Tentative Sched		Notes:		LOPEZ / MARKINGS BY TEAM LOPEZ	
WAC (Setting Temp (16°C-RE)/(10-ME))		Findings		Notes:		08/10/2022	
SAC/PAC Setting Temp (17°)		Recommendation		Notes:		For start-up	
Discharge Temperature (High)		Wait		Notes:		Customer call	
Intake Temperature (High)		Wait		Notes:		Customer call	
Ampere		Wait		Notes:		Customer call	
WAC Wattage (Inverter)		Wait		Notes:		Customer call	
Voltage		Wait		Notes:		Customer call	
SAC/PAC Pressure		Wait		Notes:		Customer call	
Part Code		Description		Qty		Unit Price	
		Copper Tube 1/8" x 1/4"		23'		13' x 40	
		R-cord 2mm x 1/4"		30'		20' x 50	
		W/supply R-cord 3.5mm x 3c		4'		60	
		Rubber insulation 2 1/8" x 6' x 3/4"		2		350	
		mobilization		1		800	
		S-tape		1			
		Clamp (S)		1			
		Elbow 3/4"		2			
		Clamp (D)		15			
		Circuit Breaker (30)		1			
		Wall Bracket (L)		1			
		Pvc pipe 3/4" x 10'		12		150	
SR No.		Labor		Amount		5,500	
Repair Done		Handling		Amount		13,590	
Repair Code		Others		Amount		13,590	
Date Attended		Date Finished		Amount Paid		13,590	
Time Attended		Time Finished		Balance		13,590	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch		Collection Unit	
Served by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.					
Kavin		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Libo		Created by:					
Technician(s)		Conformed by:					
ARCHIE ARTIGA		Customer					
CSR		(Signature over printed name)					

Customer		Date		No. 120075	
Address		Start Time		Previous SJR No. HO-00120375	
, 92 Claudio St., Brgy. San Juan LM: NEAR RIZAL PROVINCIAL HOSPITAL, MARIKINA...		End Time		HO-00117003	
Tel. No. Rizal...		Relayed by		11:44 am	
Mobile No.		Warranty Type		11:45 am	
Contact Person		Job Class		KMI	
Model		Job Type		C	
S/N (I)		Call Origin		INST	
S/N (O)		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/>		O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>	
Dealer		Notes:			
Installer		Complaint		LOPEZ / MARKINGS BY TEAM LOPEZ	
Before		After		Tentative Sched	
Mode Setting (Cool)		Findings		08/10/2022	
WAC Setting Temp(16°C-RE)/(10-ME)		Location - Operator			
SAC/PAC Setting Temp (17°)		Recommendation			
Discharge Temperature (High)		for start - up			
Intake Temperature (High)		wait for call			
Ampere					
WAC Wattage (Inverter)					
Voltage					
SAC/PAC Pressure					
Part Code	Description	Qty	Unit Price	Amount	
	Copper Tube 1/4" x 3/8"	15'	5' x 350	1,750	
	P-Cord 2mm x 4c	22'	12' x 50	600	
	W/supply P-cord 3.5mm x 7c	4'	60	240	
	Rubber insulation 1/8" x 3/4" x 6'	1	350	350	
	Mobilization	1		800	
	Circuit Breaker (20)	1			
	S-tape	2			
	Clamp (S)	5			
	Clamp (D)	5			
	Wall Bracket (S)	1			
	Pvc pipe 3/4" x 6'	1			
SR No.		Labor		4,500	
Repair Done		Handling			
Repair Code		Others			
Date Attended		Total		8,240.00	
Time Attended		Amount Paid			
Date Finished		Balance		8,240.00	
Time Finished		Bank / Branch		Collection KMT	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.			
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.			
Kevin		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Lito		Created by:			
Arjay		Conformed by:			
Technician(s)		ARCHIE ARTICA CSR			
		Customer (Signature over printed name)			

Customer		Supreme Care Medical Diagnostic Center		No.		HO-00120377	
Address		92 Claudio St., Brgy. San Juan LM: NEAR RIZAL PROVINCIAL HOSPITAL, MARIKINA CITY		Previous SJR No.		HO-00117003	
Tel. No.				Date		08-09-2022	
Mobile No.				Start Time		11:45 am	
Contact Person		Mobile No. 0917-3124887		End Time		11:45 am	
Model		KSG-IWF-15W-FY-8K1M32-I		Relayed by		Kmi	
S/N (I)		18952112-10772		Warranty Type		C	
Dealer		KMI		Job Class		INST	
Installer		DOP 07/27/2022		Job Type		FD	
Complaint		For Installation		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>			
Notes:		LOPEZ / MARKINGS BY TEAM LOPEZ					
Before		After		Tentative Sched		08/10/2022	
Mode Setting (Cool)				Findings			
WAC Setting Temp (16°C-RE) / (10-ME)				Location - X-Ray Rm.			
SAC/PAC Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)				Recommendation			
Ampere				For Start-up			
WAC Wattage (Inverter)				Wait Customer Call			
Voltage							
SAC/PAC Pressure							
Part Code		Description		Qty		Unit Price	
		Copper Tube 1/2" x 3/8"		16		6 x 350	
		P-cord 2mm x 4C		23		13 x 50	
		W/supply P-cord 3.5mm x 3C		4		60	
		Rubber insulation 2 1/8" x 3/4" x 6'		1		350	
		Mobilization		1		800	
		Circuit Breaker (20)		1			
		5-tape		2			
		Wall Bracket (5)		1			
		Clamp (5)		5			
		Clamp (10)		5			
		Elbow 3/4"		2			
		Pvc pipe 1/2" x 10'		1			
SR No.				Labor		4,500	
Repair Done		Install indoor & outdoor unit		Handling			
Repair Code				Others			
Date Attended		August 10, 2022		Total		₱ 8,640.00	
Time Attended		9:30		Amount Paid			
Date Finished		August 11, 2022		Balance		₱ 8,640.00	
Time Finished		5:35 pm		Bank / Branch		Collection PM	
This serves as temporary receipt when properly filled up by authorized representative.				Check No.			
Serviced by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.					
Kevin		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Lito		Created by: ARCHIE ARTIGA					
Fernando		Conformed by: Daven Odiste					
Arjay		(Signature over printed name)					
Technician(s)		CSR					

Customer		Supreme Care Medical Diagnostic Center		Date		08-09-2022	
Address		92 Claudio St., Brgy. San Juan LM: NEAR RIZAL PROVINCIAL HOSPITAL, M. Rizal...		Start Time		11:45 am	
Tel. No.				End Time		11:46 am	
Mobile No.				Relayed by		Kmi	
Contact Person		Mobile No. 0917-3124887		Tel. No. 0917-3124887		Warranty Type	
Model		KSG-IWF-10W-FY-8K1M32-I		Call Origin		IO	
S/N (I)		18432112-10558		S/N (O)		18432112-11005	
Dealer		KMI		DOP		07/27/2022	
Installer				Complaint		For installation	
		Before		After		No. of Visit	
						1st Action	
Mode Setting (Cool)				Findings			
WAC Setting Temp(16°C-RE)/(10-ME)				Location -		Mamogram	
SAC/PAC Setting Temp (17°)				Recommendation			
Discharge Temperature (High)				For start-up		wait for call	
Intake Temperature (High)							
Ampere							
WAC Wattage (Inverter)							
Voltage							
SAC/PAC Pressure							
Part Code		Description		Qty		Unit Price	
		Copper Tube 1/4" x 3/8"		20'		10' x 350	
		R-cord 2mm x 4c		27'		17' x 50	
		W/supply R-cord 3.5mm x 3c		4'		60	
		Rubber insulation 2 1/8" x 6 x 3/4"		2		350	
		Mobilization		1		800	
		Circuit Breaker 20		1			
		S-tape		3			
		Wall Bracket (S)		1			
		Clamp (S)		5			
		Clamp (D)		5			
		Elbow 3/4"		2			
		Pvc pipe 1 1/2"		1			
		Fleon R32		1			
SR No.				Labor		4,500	
Repair Done		Install indoor & outdoor unit		Handling			
Repair Code				Others			
Date Attended		August 10, 2022		Date Finished		August 11, 2022	
Time Attended		9:30 am		Time Finished		5:35 pm	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch		Collection kmi	
Serviced by:		By signing below, I allow KPIL to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.					
Kevin		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Lito		Created by: ARCHIE ARTIGA					
Technician(s)		Conformed by: Davon Odisto					
		Customer (Signature over printed name)					

SERVICE JOB REPORT

[illegible]