

Customer		Monaco Manufacturing Corporation		Date		10-03-2022	
Address		101 Matutum cor. Mauban St., Brgy. Manresa, QUEZON CITY, Metro Manila		Start Time		04:41 pm	
Tel. No.				End Time		04:43 pm	
Mobile No.		8365-4562 loc 224		Relayed by		Zelle	
Contact Person		Zelle		Mobile No.		0939-9714031	
Model		KFG-40F1		Tel. No.		8365-4487	
S/N (I)		10270810-00582		Call Origin		VH	
Dealer		DOP		Job Class		TS	
Installer		Complaint		Job Type		FD	
		Before		After		No. of Visit	
						Tentative Sched	
Mode Setting (Cool)				Findings		10/06/2022	
WAC Setting Temp(16°C-RE)/(10-ME)				Burnt leadwire, undervalue comp cap			
SAC/PAC Setting Temp (17°)				5/40 uf & corroded Relay			
Discharge Temperature (High)				Recommendation			
Intake Temperature (High)				for 2nd person			
Ampere				BRING ALL POSSIBLE PARTS			
WAC Wattage (Inverter)				LEAVE WIRE 5-5mm			
Voltage							
SAC/PAC Pressure							
Part Code		Description		Qty		Unit Price	
SR No.				Labor		600-	
Repair Done		Check-up only, for 2nd person		Handling			
Repair Code				Others			
Date Attended		10-06-22		Total		600-	
Time Attended		11:14		Amount Paid		for collection	
Date Finished		10-06-22		Balance			
Time Finished		1330H					
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by:		By signing below, I allow KPIL to collect, store & process my personal information as necessary to avail of service & fully understand that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.					
Cortez		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Pagat		Created by:		Conformed by:			
Technician(s)		JOMNA ANDRINO		Customer			
		CSR		(Signature over printed name)			