

SERVICE JOB REPORT

KOLIN										Tel. No. 8852-6860 / Mobile: 0917-8118982 / Email: service@kolinphil.com.ph Website: www.kolinphil.com.ph										No. 10-00129786 Previous SJR No. 10-00118380																																							
Customer: Global Lighting Phils. Inc.										Date: 10-25-2022										Start Time: 10:29 am																																							
Address: 14433 Governors Drive, Brgy. Bangkal, CARMONA, Cavite										End Time: 10:32 am										Relayed by: KML Jozelle																																							
Tel. No.										Warranty Type: C										Job Class: TS																																							
Mobile No. 0921-4983317										Job Type: ID										Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>																																							
Contact Person: Jallyn					Mobile No. 0921-4983317					Tel. No.					Notes: CUEVAS - COLLECTION C/O CUSTO																																												
Model: KLE-43DTE32					Call Origin: ID					Installer: KML																																																	
S/N (I): 03121804-10861					S/N (O):					DOP: 07/28/2021					Complaint: Dead Set																																												
Dealer: KML					Before:					After:					No. of Visit:					Tentative Sched: 11/02/2022																																							
Mode Setting (Cool)										Findings: DEFECTIVE CPU																																																	
WAC Setting Temp(16°C-RE)/(10-ME)										SAC/PAC Setting Temp (17°)																																																	
Discharge Temperature (High)										Intake Temperature (High)																																																	
Ampere										Recommendation: FOR PULL OUT FOR SHOP REPAIR																																																	
WAC Wattage (Inverter)										Voltage																																																	
SAC/PAC Pressure										Part Code										Description										Qty										Unit Price										Amount									
ESTIMATED COST ONLY										LABOR - 1000										PAINTS - ?										NOTE: PAYMENT UPON COMPLETION																													
DATE: 10-28-22										BY: [Signature]										SR No.										Labor: 400.00																													
Repair Done: DIRECT PULLOUT FOR SHOP REPAIR										Handling: 400.00										Others: 400.00										Total: 400.00																													
Repair Code: 10-28-22										Date Finished: 10-28-22										Amount Paid: 400.00																																							
Time Attended: 9:30 AM										Time Finished: 10:00 AM										Balance: 400.00																																							
This serves as temporary receipt when properly filled up by authorized representative.										Check No.										Bank / Branch																																							
Serviced by: NOEL BOYET										By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.										I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.																																							
CREX BIAN										Created by: RODEN PULONGBARIT										Conformed by: ALBERT R. RICAPUTER																																							
Technician(s)										CSR										Customer (Signature over printed name)																																							