

Customer		Date		No. HO-00130637	
Address QC Holiday Spa 150 D Tuazon Street, Brgy. Lourdes, QUEZON CITY, Metro Manila		Start Time 11-03-2022		Previous SJR No. HO-00120566	
Tel. No.		End Time 08:26 am		Relayed by ENGR KEN	
Mobile No.		Warranty Type		Job Class	
Contact Person Jonathan	Mobile No. 0916 8427241	Tel. No.	Job Type	TS	
Model KAG-250ME	Call Origin	Job Type	FD		
S/N (I) 11811011-11585	S/N (O)	Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/> O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>			
Dealer	DOP	Notes:	LOPEZ DEFECTIVE THERMOSTAT B		
Installer	Complaint	RING 2 PCS THERMOSTAT NG			
Before		After	No. of Visit	Tentative Sched	
Mode Setting (Cool)		Cool	Findings		
WAC Setting Temp(16°C-RE)/(10-ME)		7	Defective Thermostat		
SAC/PAC Setting Temp (17°)					
Discharge Temperature (High)		12.6			
Intake Temperature (High)		25.7	Recommendation		
Ampere		10.1	For Replacement Thermostat		
WAC Wattage (Inverter)					
Voltage		225			
SAC/PAC Pressure					
Part Code	Description	Qty	Unit Price	Amount	
	Thermostat	1	660	660	
<div style="border: 2px solid red; padding: 5px; display: inline-block;"> LIQUIDATED DATE: 11/3/22 </div>					
SR No.	Labor			900	
Repair Done	Replaced Thermostat, Test run unit normally operation			Handling	
Repair Code	Total			#1,560.00	
Date Attended	Nov. 2, 2022	Date Finished	Nov. 2, 2022	Amount Paid	
Time Attended	10:07 am	Time Finished	10:45	Balance For collection c/p	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.	Bank / Branch	KMT	
Served by:		By signing below, I allow KPII to collect, store & process my personal information as necessary to avail of service & fully understood that my personal information shall be used in accordance w/ Philippine Data Privacy Act & its implementing rules & regulations.			
Kavin Fernando		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Lito		Created by:	Conformed by:	Customer	
Technician(s)		LUIS REBUYAS CSR	Jonathan Labani	(Signature over printed name)	