



16-Aug-2024

SPRING PALACE RESTAURANT INC.

ATTN: MS. CECILLE LEI

1947 H. PASEO DE CARMONA, FORMERLY: LEI YUAN GRILL & SEAFOOD RESTAURANT
BRGY. MADUYA, CARMONA CAVITE

TEL: 0966-5262080/0917-5248989

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of JUNE 2024.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
13-Jun-24	HO-00207609	(1) KSM-IW20-4F1M	CHECK UP	450.00
13-Jun-24	HO-00207611	(1) KSM-25MB1INV	PARTS REPLACEMENT	7,355.00
06-Aug-24	HO-00215890	(1) KSM-25MB1INV	PULL OUT OF SCAFFHOLDING	1,500.00
08-Aug-24	HO-00216336	(1) KSM-25MB1INV	INSTALLATION	15,945.00
TOTAL				₱ 25,250.00
LESS: DISCOUNT				(2,525.00)
TOTAL AMOUNT DUE				₱ 22,725.00


For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: BDO - KALAYAAN 011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assisitant

Noted by:


Mari Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

K Kolin Philippines Int'l., Inc.

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite

Tel.: (632) 8749-2118

Fax (046) 402-0793

 www.kolinphil.com.ph / kolinphilippines

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,
Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791



K Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-8868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

SERVICE JOB REPORT

No. HO-00207611
Previous SJR No. HO-00203453

Customer	Spring Palace Restaurant Inc.			Date	06-11-2024		
Address	1947 H. Paseo De Camona, Formerly : Lei Yuan Grill & Seafood Restaurant, Brgy. Iduya, CARMONA, Cavite...			Start Time	07:45 am		
Telephone No.		Mobile No.	0986-5262080/ 0986-5261762		Relayed by	neil villafuerte	
Contact Person	Ms. Cecille	Mobile No.	0917-5248989	Tel. No.	0917-5248989	Warranty Type	C
Warranty Code		Room Size		Job Class	TS	LVL	1
Model	KSM-25MB1INV		Call Origin	IO	Job Type	PO	
S/N (I)	(I) 10911311-12117	S/N (O)	(O) 10921311-12203	Permit?	☐	Parking?	☐
Dealer		DOP		Notes	SHOP Findings - . . . Recommendation - . . . Repair Done - . . . Pull out indoor and outdoor unit / With indoor plate, 1pc flare nut 3/8, 2pcs flare nut 5/8, drain hose, e. cover indoor, 2pcs filter louver		
Installer		Complaint	Check - Up Only				
Location	VIP Room	Before	After				
Mode Setting (Cool)		No. of Visit	1st Action	Tentative Sched	06/17/2024		
WAC Setting Temp (16°C-RE)/(10/12-ME)		Findings					
SAC/PAC Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere		Recommendation					
Wattage (Inverter)							
Voltage							
SAC/PAC Pressure (PSI)							
Part Code	Description			Qty	Unit Price	Amount	
D1012412184	Pressure valve 5/8			1.00	1540.00		
R33000027	Capacitor 35uF/450V			1.00	800.00		
R1020023	Capacitor 3.5uF/450V : Php165.00			1.00	165.00		
11080005	Freon 410a (11.3kg)			1.00	0.00		
Payment upon delivery DATE: 8/7/24 CLABEL c/o KMI 8/7							
SR No.	SR-HO-00038626			Labor	4,250.00		
Repair Done	Findings - Yup! ang pressure valve 5/8, fan capacitor 3.1uf (3.5uf) under valve, compressor capacitor rusted 35uf, face cover may dumung sa neg na plastic			Handling	800.00		
Repair Code	replacement of pressure v			Others			
Date Attended	06/13/2024	Date Finished	07/13/2024	Total	77,355.00		
Time Attended	01:15 pm	Time Finished	10:40 am	Amount Paid	0.00		
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		
Served by:	Hemino Barrera			By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.				Created by:			
Technician(s)				RECHILLA CSR			
				Conformed by:			
				Customer (Signature over printed name)			



TPWR 41547

SERVICE JOB REPORT

No.	HO-00215890
Previous SJR No.	HO-00203453


Customer	Spring Palace Restaurant Inc.						Date	07-31-2024							
Address	1947 H. Paseo De Carmona, Formerly : Lei Yuan Grill & Seafood Restaurant, Brgy						Start Time	11:52 am							
Iduya, CARMONA, Cavite...							End Time	11:57 am							
Telephone No.				Mobile No.	0968-5262080 / 0968-5261762		Relayed by	IH-SHOP							
Contact Person	Ms. Cecille		Mobile No.	0917-5248989		Tel. No.	0917-5248989		Warranty Type	C					
Warranty Code						Room Size			Job Class	DEL LVL 2					
Model	KSM-25MB1INV					Call Origin	ID		Job Type	FD					
S/N (I)	I) 10911311-12117		S/N (O)	(O) 10921311-1220		Permit?	☐	Parking?	☐	Appointment?	☐	O.R.?	☐	Ladder?	☐
Dealer			DOP			Notes *Payment Upon Delivery of Unit *as per customer request need Surveyor for survey other location									
Installer			Complaint	For Delivery Shop Repair											
Location	VIP Room		Before	After											
Mode Setting (Cool)			No. of Visit	1st Action		Tentative Sched	08/06/2024								
WAC Setting Temp(16°C-RE)/(10/12-ME)			Findings												
SAC/PAC Setting Temp (17°)															
Discharge Temperature (High)															
Intake Temperature (High)															
Ampere			Recommendation												
Wattage (Inverter)															
Voltage															
SAC/PAC Pressure (PSI)															
Part Code	Description	Qty	Unit Price	Amount											
Refrigerant															
FSC 100 BTU															
Indoor and outdoor															
(*) FC 011810 - 21458															
Ref SRT 216336 c/o KMI															
SR No.	38785		Labor	1,500											
Repair Done	DELIVERED AND RATED		Handling												
Repair Code	SCAFFOLDING		Others												
Date Attended	8.8.24		Date Finished	8.8.24		Total	1,500								
Time Attended	12:50		Time Finished	3:50		Amount Paid	FOR collection								
This serves as temporary receipt when properly filled up by authorized representative.						Check No.	Balance 1,500								
Served by Garry Munday, Neil Villafuerte						By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.									
Technician(s) DANLOS						I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.									
Created by: PAOLO JOSE LU						Conformed by:									
Technician(s)						Customer Richardlei (Signature over printed name)									

Kolin Philippines Int'l., Inc.

1654 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-5858 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

SERVICE JOB REPORT

No. HO-00216336
Previous SJR No. HO-00223453

Customer	Spring Palace Restaurant Inc.			Date	08-02-2024		
Address	1947 H. Paseo De Carmona, Formerly : Lei Yuan Grill & Seafood Restaurant, Brgy. Kuya, CARMONA, Cavite...			Start Time	02:42 pm		
Telephone No.		Mobile No.	0968-5262080 / 0968-526176	End Time	02:44 pm		
Contact Person	Ms. Cecille	Mobile No.	0917-5248989	Relayed by	Joaffray Dadios		
Warranty Code		Tel. No.	0917-5248989	Warranty Type	C		
Model	KSM-25MB11HV	Room Size		Job Class	SCF	LVL	1
S/N (I)	I) 10911311-12117	Call Origin	IO	Job Type	FD		
S/N (O)	O) 10921311-122	Permit?	☐	Parking?	☐	Appointment?	☐
Dealer		DOP		O.R.?	☐	Ladder?	☐
Installer		Complaint	Others	Notes VILLAFUERTE NEED 4 SETS SACFFOLDINGS			
Location	MP-Room	Before	After				
Mode Setting (Cool)		No. of Visit	1st Action	Tentative Sched	08/08/2024		
WAC Setting Temp(16°C-REY)(10/12-ME)		Findings					
SAC/PAC Setting Temp (17°)		FOR INSTALL					
Discharge Temperature (High)		FOR INSTALLATION					
Intake Temperature (High)		NEED FLAT NUT					
Ampere		T/B 2PCS 3/4" x 2PCS					
Wattage (Inverter)							
Voltage							
SAC/PAC Pressure (PSI)							
Part Code	Description	Qty	Unit Price	Amount			
	CUTTER 3/8-9/8	4M	400	1,600			
	R-ROD 4x1mm	20M	100	2,000			
	R-ROD 3x5mm	7FT	60	420			
	CAMP (D)	10	-	-			
	CAMP (C)	10	-	-			
	PVC PIPE 3/4	2PCS	150	300			
	TRAIL HOSE	7FT	25	175			
	START	2PCS	-	-			
	PVC ELBOW	4PCS	-	-			
	C-BRACKET 3DA	1PC	1,000	1,000			
	BRACKET (W2)		-	1,650			
	INTERHARD						
SR No.	MOBILIZATION			Labor	800		
Repair Done	MOUNTING OF INDOOR AND OUTDOOR FOR FITTING OF INDOOR AND OUTDOOR			Handling	4,000		
Repair Code	F			Others			
Date Attended	8-6-24	Date Finished	8-6-24	Total	15,945		
Time Attended	12:50 pm	Time Finished		Amount Paid	FOR collection		
This serves as temporary receipt when properly filled up by authorized representative.				Balance	15,945		
Check No.				Bank / Branch	KIN		
Serviced by: Gerry Munday, Neil Villafuerte				By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
Created by: LUIS REYES				Conformed by: 			
Technician(s)				Customer (Signature over printed name)			