



9-Aug-2024

LUCENDI SHOP

ATTN: JOHN RAY

CW HOME DEPOT, JULIA VARGAS AVE., BRGY. SAN ANTONIO, PASIG CITY

TEL: 0917-8855863 / 8655-0715

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of MAY & JUNE 2024.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
05-Jul-24	HO-00211795	(1) KSM-30MBINV	CHECK UP	450.00
TOTAL AMOUNT DUE				₱ 450.00

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**


Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: BDO - KALAYAAN

011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Jahellen S. Lim
KMI - Assistant

Noted by:


Mari Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:
Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite
Tel.: (632) 8749-2118
Fax (046) 402-0793
www.kolinphil.com.ph / kolinphilippines

Operation Office:
1854 Sta. Rita St., Guadalupe Nuevo,
Makati City
Tel: (632) 8851-2711, 12 or 15
Fax: (632) 8852-2170
Sales Dept. Fax: (632) 8852-4791



Customer		Lucendi Shop		No. Previous SJR No.		HO-00211795	
Address		OW Home Depot, Julia Vargas Ave., Brgy San Antonio, PASIG CITY, Metro Manila		Date		07-02-2024	
Telephone No.		0655-0715		Mobile No.		0917-8855863 / 0977-837879	
Contact Person		Johnny		Tel. No.		Warranty Type	
Warranty Code				Room Size		Job Class	
Model		KSM-30MB11HV		Call Origin		Job Type	
S/N (I)		18011512-12252		S/N (O)		18021512-12370	
Dealer		Fair 'N' Square		DOP		Notes	
Installer				Complaint		Others	
Location		209D-ACU2		Before		After	
Mode Setting (Cool)				No. of Visit		Tentative Sched	
WAC Setting Temp(16°C-RE)/(10/12-ME)				Findings		KUNG ISANG... ILELAY-OUT NA... 1st AC COPPER TUBE & ROYAL COPPER TUBE	
SAC/PAC Setting Temp (17°)				Discharge Temperature (High)		Intake Temperature (High)	
Ampere				Wattage (Inverter)		Voltage	
SAC/PAC Pressure (PSI)				Part Code		Description	
				Qty		Unit Price	
				Amount			
SR No.		open gate valve, check...		Labor		P 450	
Repair Done		gate Per...		Handling			
Repair Code				Others			
Date Attended		7-5-24		Date Finished		11-7-24	
Time Attended		10:10		Time Finished		11:16	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by: Gary Munday, Neil Villafuerte		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
I hereby agree to the above repair charges incurred to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.		Created by: RECHILLA CSR					
Technician(s)		Conformed by: JOHN P. S. SEQUIN Customer (Signature over printed name)					