



25-Nov-2024

MR. JONATHAN GO
ATTN: MS. CHARLENE

540 WACK WACK RD., WACK WACK VILLAGE, BRGY. WACK-WACK MANDALUYONG CITY
TEL: 0917-3270066 / 0917-5843186

Sir/ Madam,

This is to bill you on the service job done to your unit for the following dates.
Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
09-Nov-24	HO-00229584	(1) KSM-25CB1INV	INSTALLATION	20,570.00
	TOTAL			P 20,570.00
	LESS: DISCOUNT			(2,057.00)
	TOTAL AMOUNT DUE			P 18,513.00

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**
Account #: BDO - KALAYAAN 011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assistant

Noted by:


Mart Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 Kolin Philippines Int'l, Inc.

Plant and Head Office:
Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite
Tel: (632) 8749-2118
Fax (046) 402-0793
www.kolinphil.com.ph / kolinphilippines

Operation Office:
1854 Sta. Rita St., Guadalupe Nuevo,
Makati City
Tel: (632) 8851-2711, 12 or 15
Fax: (632) 8852-2170
Sales Dept. Fax: (632) 8852-4791



Customer	Go, Jonathan			Date	11-08-2024		
Address	540 Wack Wack Rd., Wack Wack Village, Brgy. Wack-wack, MANDALUYONG			Start Time	11:11 am		
Manila...				End Time	11:13 am		
Telephone No.			Mobile No.	0917-3270066		Relayed by	Go, Jonathan
Contact Person	Gigi Jonathan	Mobile No.			Tel. No.		
Warranty Code			Room Size			Job Class	INST LVL 2
Model	KSM-25CB1INV		Call Origin	MH		Job Type	FD
S/N (I)	10711102-11053	S/N (O)	10721101-10958	Permit?	<input type="checkbox"/>	Parking?	<input type="checkbox"/>
Dealer			DOP			Appointment?	<input type="checkbox"/>
Installer			Complaint	For installation			
Location	Dismantled unit	Before	After				
Mode Setting (Cool)		Cool		No. of Visit	1st Action	Tentative Sched	11/09/2024
WAC Setting Temp(16°C-RE)/(10/12-ME)				Findings			
SAC/PAC Setting Temp (17°)		17°C	For delivery & installation				
Discharge Temperature (High)		15.8°C					
Intake Temperature (High)		29°C					
Ampere		8.5A	Recommendation				
Wa'tage (Inverter)							
Voltage		240V					
SAC/PAC Pressure (PSI)		135PSI					
Part Code	Description			Qty	Unit Price	Amount	
	Copper tube 3/8 x 5/8			25 FT.	400 x 25 =	10,000 ✓	
	Royal cord 2mm x 4c			32 FT.	100 x 32 =	3,200 ✓	
	Royal cord 3.5mm x 3C			7 FT.	60 x 7 =	420 ✓	
	Wall bracket			1	1,650 =	1,650 ✓	
	Circuit breaker (30A) ROYU			1	1,000 =	1,000 ✓	
	PVC pipe (blue) 3/4			2	150 =	300 ✓	
	PVC elbow			3			
	R410			1			
	Piping clamp (D)			5		10% discount	
	Piping clamp (S)			5			
	S-tape			1			
	Add front unit (KAG 2400S) dismantle & install					1,200	
SR No.	Initial charge			Labor	4,000		
Repair Done	Delivery & install unit			Handling			
Repair Code	LIQUIDATED			Others			
Date Attended	11-9-24	Date Finished	11-9-24	Total	20,570.00		
Time Attended	10:15am	Time Finished	3:45pm	Amount Paid	For collection		
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		
Serviced by: Richard Talavera, Michael V. Talavera				By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
TALAVERA VISTAN RIVERA DADIDS				I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Created by: LUIS REBUYAS CSR				Conformed by: Customer (Signature over printed name)			