



4-Dec-2024

MR. JONATHAN GO

ATTN: MS. CHARLENE

540 WACK WACK RD., WACK WACK VILLAGE, BRGY. WACK-WACK MANDALUYONG CITY

TEL: 0917-3270066 / 0917-5843186

Sir/ Madam,

This is to bill you on the service job done to your unit for the following dates.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
11-Aug-22	HO-00119606	(1) KSM-25CB1INV	PARTS REPLACEMENT	6,444.00
TOTAL AMOUNT DUE				<u>P 6,444.00</u>

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

**Note:** If check payment, please prepare check payable to **Kolin Philippines International Inc.**

**Account #: BDO - KALAYAAN**

**011808000428**

**Note:** In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi\_asst@kolinphil.com.ph**

Prepared by:

  
**Janellen S. Lim**  
KMI - Assistant

Noted by:

  
**Mari Nathaniel R. Flores**  
KMI - Supervisor

Received by:

Signature over printed name

 Kolin Philippines Int'l., Inc.

Plant and Head Office:  
Blk 3 Lt 5 Main Drive, FCIE Compound,  
Brgy. Langkaan I, Dasmariñas, Cavite

Tel: (632) 8749-2118

Fax (046) 402-0793

 [www.kolinphil.com.ph](http://www.kolinphil.com.ph) / [kolinphilippines](http://kolinphilippines)

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,  
Makati City

Tel: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791





No. HO-00119606  
Previous SJR No. HO-00111075

Customer	Go, Jonathan			Date	08-02-2022		
Address	540 Wack Wack Rd., Wack Wack Village, Brgy. Wack-wack, MANDALUYONG			Start Time	03:38 pm		
Manila...				End Time	03:46 pm		
Telephone No.		Mobile No.	0917-3270066		Relayed by	Garry Munday	
Contact Person	Charlene	Mobile No.	0926-7580799		Tel. No.		
Warranty Code		Room Size			Warranty Type	C	
Model	KSM-25CB1INV		Call Origin	IO		Job Class	TS LVL 1
S/N (I)	10711102-11053		S/N (O)	10721101-10958		Job Type	PO
Dealer		DOP		Permit?	Parking?	Appointment?	O.R.? Ladder?
Installer		Complaint	Check - Up Only				
Location	Dismantled unit	Before	After	Notes: OREJO For check up only as per sir jonathan gusto niya ipacheck ang unit if ano ang problem - Note: if ipapaschedule ng Deliver / paki verify kay Customer if Approved na yung Quotation para sa gagawing installation sa ACU na lo			
Mode Setting (Cool)		No. of Visit	1st Action	Tentative Sched	08/02/2022		
WAC   Setting Temp(16°C-RE)/(10/12-ME)		Findings					
SAC/PAC   Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere		Recommendation					
Wattage (Inverter)							
Voltage							
SAC/PAC   Pressure (PSI)							
Part Code	Description			Qty	Unit Price	Amount	
01120125429 / 110022221791	FAN MOTOR BRACKET (ODU) YKT-63-6-200L : Php3,300.00			1.00	3300.00		
01222221791	Fan Motor Bracket (ODU)			1.00	100.00		
02010256	HV Junction Cable (ODU) ZL91 188MM : Php330.00			1.00	330.00		
<p>Parts- 20% discount Labor- 10% discount</p> <p>Net total: ₱6,444.00</p>							
SR No.	SR-HO-00022016			Labor			
Repair Done	REPLACED FAN MOTOR OUTDOOR UNIT, FAN MOTOR BRACKET, HV JUNCTION CABLE, GENERAL CLEANING AND FLUSHING INDOOR UNIT.			Handling	2,400.00		
Repair Code	SAC07-1 - General Cleaning with Major Repair			Others			
Date Attended	08/03/2022			Total	500		
Time Attended	08:50 am			Amount Paid	7,330.00		
Date Finished	08/11/2022			Balance	0.00		
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		
Served by:	Jonathan Orejo			By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
Created by: NESSA VILLANUEVA CSR				Conformed by:			
Technician(s)				Customer (Signature over printed name)			