



7-Jun-2024

PATTS COLLEGE OF AERONAUTICS

LOMBOS ST., BRGY. SAN ISIDRO, PARAÑAQUE CITY

TEL: 0933-8120909/0995-3650589

Sir/ Madam,

This is to bill you on the service job done to your unit for the following months.
Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
18-Mar-23	HO-00192193	(1) KSG-250B1G	CHECK-UP	450.00
18-Mar-23	HO-00192196	(1) KSG-250B1G	CHECK-UP	450.00
18-Mar-23	HO-00192198	(1) KSG-250B1G	TROUBLESHOOTING	2,500.00
18-Mar-23	HO-00192200	(1) KSG-250B1G	TROUBLESHOOTING	2,500.00
18-Mar-23	HO-00192202	(1) KSG-250B1G	CHECK-UP	450.00
18-Mar-23	HO-00192204	(1) KSG-300B1F-I	CHECK-UP	450.00
19-Apr-24	HO-00196964	(1) KSG-250B1G	PARTS REPLACEMENT	6,850.00
TOTAL				₱ 13,650.00
LESS: DISCOUNT				(955.50)
TOTAL AMOUNT DUE				₱ 12,694.50


For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**


Account #: BDO - KALAYAAN 011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Jarrellen S. Lim
KMI - Assisitant

Noted by:


Mart Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:


Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite
Tel.: (632) 8749-2118
Fax (046) 402-0793
 www.kolinphil.com.ph / kolinphilippines

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,
Makati City
Tel.: (632) 8851-2711, 12 or 15
Fax: (632) 8852-2170
Sales Dept. Fax: (632) 8852-4791



Customer		Pats College Of Aeronautics		No. Previous SJR No.		HO-00192193	
Address		Lombos St., Brgy. San Isidro, PARANAQUE CITY, Metro Manila		Date		03-18-2024	
Telephone No.		8825-8823 / 8825-8824		Mobile No.		0933-8120909 / 0995-3850589	
Contact Person		Mobile No.		Tel. No.		Warranty Type	
Warranty Code		Room Size		Job Class		TS LVL 1	
Model		KSG-250E1G		Call Origin		IO	
S/N (I)		S/N (O)		Permit?		Parking?	
Dealer		DOP		Appointment?		O.R.?	
Installer		Complaint		Ladder?			
Location		Before		After		Notes	
Mode Setting (Cool)		No. of Visit		Tentative Sched		Talevera * Amoy freon pag ino-on yung unit as per customer. * Pls. verify & update unit model and serial #.	
WAC Setting Temp(16°C-RE)/(10/12-ME)		Findings		W/ PARKING			
SAC/PAC Setting Temp (17°)		Recommendation					
Discharge Temperature (High)		2nd Action for replacement of evaporator					
Intake Temperature (High)							
Ampere							
Wattage (Inverter)							
Voltage							
SAC/PAC Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
Amount							
Note: Replacement of Evaporator							
Schedule on Saturday as per							
Miss Roschella							
DATE: 3/20/24							
less 7%.							
SR No.		Labor					
Repair Done		Handling					
Repair Code		Others					
Date Attended		Date Finished		Total		450.00	
Time Attended		Time Finished		Amount Paid		For Collection	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Balance			
Bank / Branch							
Serviced by: Vidal Lajero, Kevin Sener, M		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
VIDAL KEVIN MANUEL		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Created by: GRACE PIELAGO CSR		Conformed by: Jober Lajero					
Technician(s)		Customer (Signature over printed name)					



TIME 35700

No.	HO-00192198
Previous SJR No.	HO-00188537

SVC-SJR-02-020123

White - Customer

Blue - Accounting

Green - Service



1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph     kolinphilippines


SERVICE JOB REPORT

No. _____
Previous SJR No. _____

HO-00192200

HO-0018583F


[illegible]



TPNR 20756

2

[illegible]



SERVICE JOB REPORT

Green - Service



TPWR 2035.2

⑤

Green - Service