



28-Nov-2024

MR. ENRIQUE CHUA YAP

NO. 30, IGDALIG ST., BRGY. MANRESA, QUEZON CITY

TEL: 0918-9029469 / 0917-8194754

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of NOVEMBER 2024.
Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR#	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
25-Nov-24	HO-00231102	(1) KAG-145WCINV	GENERAL CLEANING	800.00
25-Nov-24	HO-00231104	(1) KAG-120RS	GENERAL CLEANING	800.00
25-Nov-24	HO-00231106	(1) KAG-120RS	GENERAL CLEANING	800.00
25-Nov-24	HO-00231108	(1) KAG-80HME4	GENERAL CLEANING	800.00
25-Nov-24	HO-00231109	(1) KAG-120RS	GENERAL CLEANING	800.00
25-Nov-24	HO-00231110	(1) KAG-150RSINV	GENERAL CLEANING	800.00
25-Nov-24	HO-00231111	(1) KAG-145WCINV	GENERAL CLEANING	800.00
TOTAL				P 5,600.00
LESS: DISCOUNT				(560.00)
TOTAL AMOUNT DUE				P 5,040.00

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: BDO - KALAYAAN 011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assistant

Noted by:


Mari Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 Kolin Philippines Int'l., Inc.

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite

Tel: (632) 8749-2118

Fax (046) 402-0793

www.kolinphil.com.ph / kolinphilippines

Operation Office:


1854 Sta. Rita St, Guadalupe Nuevo,
Makati City

Tel: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791





SERVICE JOB REPORT

No. _____
Previous SJR No. _____

Customer	Yap, Enrique Chua						Date	11-18-2024			
Address	50 Igdalig St., Brgy. Manresa, QUEZON CITY, Metro Manila						Start Time	11:59 am			
							End Time	11:59 am			
Telephone No.					Mobile No.	0932-5109783		Relayed by	Ms. Caress / Viber		
Contact Person	Enrique		Mobile No.	0932-5109783		Tel. No.			Warranty Type	C	
Warranty Code						Room Size			Job Class	GC LVL 1	
Model	WAC-INV YAG-120P					Call Origin	ID	Job Type	FD		
S/N (I)				S/N (O)				Permit?	Parking?	Appointment?	O.R.? Ladder?
Dealer	Kitchen			DOP				Notes IH Villafuerte "VIP- IH Only" Appt. Nov. 25 morning WAC for GC			
Installer				Complaint	For GC						
Location	s	Before	After								
Mode Setting (Cool)				No. of Visit	1st Action		Tentative Sched	11/25/2024			
WAC Setting Temp(16°C-RE)/(10/12-ME)				Findings							
SAC/PAC Setting Temp (17°)				Dirty, Un							
Discharge Temperature (High)	14.5 / 13.5										
Intake Temperature (High)	25.1 / 26.3										
Ampere	3.3 / 3.5			Recommendation							
Wattage (Inverter)											
Voltage	220 / 220										
SAC/PAC Pressure (PSI)											
Part Code	Description					Qty	Unit Price	Amount			
Note: Exposed Condenser Metal perforator and fan motor verify noisy fan motor											
15% discount											
SR No.	G. C. N.Y. 50					Labor	#500				
Repair Done	CLEAN					Handling					
Repair Code	11/25/24					Others					
Date Attended	11-25-24		Date Finished	11-25-24		Total	#500				
Time Attended	1:00		Time Finished	1:20		Amount Paid					
				Balance		#500					
This serves as temporary receipt when properly filled up by authorized representative.				Check No.		Bank / Branch					
Serviced by: Gary Munday, Neil Villafuerte, Salomon				By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations. I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
Technician(s) Grace Pielago CSR				Created by: Conformed by: Customer (Signature over printed name)							



Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

SERVICE JOB REPORT

No. HO-00231108
Previous SJR No.

Customer	Yap, Enrique Chua				Date	11-18-2024						
Address	30 Igdalig St., Brgy. Manresa, QUEZON CITY, Metro Manila				Start Time	12:00 pm						
					End Time	12:00 pm						
Telephone No.				Mobile No.	0932-5109783			Relayed by	Ms. Carass / Viber			
Contact Person	Enrique	Mobile No.	0932-5109783		Tel. No.				Warranty Type	C		
Warranty Code					Room Size				Job Class	GC LVL		
Model	WAC-INV / AG-50 / SHME4				Call Origin	10			Job Type	FD		
S/N (I)				S/N (O)				Permit?	Parking?	Appointment?	O.R.?	Ladder?
Dealer	Jack			DOP				Notes	IH Villafuerte "VIP- IH Only" Appt: Nov. 25 morning. WAC for GC.			
Installer	Pon			Complaint	For GC							
Location	4	Before	After									
Mode Setting (Cool)					No. of Visit	1st Action		Tentative Sched	11/25/2024			
WAC Setting Temp(16°C-RE)/(10/12-ME)					Findings							
SAC/PAC Setting Temp (17°)					10.2f							
Discharge Temperature (High)	13.2		12.5									
Intake Temperature (High)	27.2		26.5									
Ampere	3.3		3.5		Recommendation							
Wattage (Inverter)												
Voltage	220		220									
SAC/PAC Pressure (PSI)												
Part Code	Description				Qty	Unit Price		Amount				
ref: slightly												
Auxiliary Fan (not)												
10% discount												
SR No.	6. (Only)				Labor	800						
Repair Done					Handling							
Repair Code					Others							
Date Attended	11-26-24		Date Finished	11-25-24		Total	800					
Time Attended	9:00		Time Finished	1:20		Amount Paid						
This serves as temporary receipt when properly filled up by authorized representative.					Check No.			Balance	800			
Served by: Gary Munday, Neil Villafuerte, Salomon					By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.							
Technician(s)					I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
Created by: GRACE PIELAGO					Conformed by: Customer (Signature over printed name)							



Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

SERVICE JOB REPORT

No. HO-00281109
Previous SJR No.

Customer	Yap, Enrique Chua				Date	11-18-2024			
Address	30 Iralda St., Brgy. Marresca, QUEZON CITY, Metro Manila				Start Time	12:01 pm			
					End Time	12:02 pm			
Telephone No.			Mobile No.	0932-5109783		Relayed by	Ms. Donna / KMI		
Contact Person	Enrique	Mobile No.	0932-5109783		Tel. No.			Warranty Type	C
Warranty Code					Room Size			Job Class	GC LVL 1
Model	WAC-INV/AG-12014				Call Origin	10		Job Type	FD
S/N (I)			S/N (O)			Permit?	<input type="checkbox"/>	Parking?	<input type="checkbox"/>
Dealer	Vip Enrique		DOP			Appointment?	<input checked="" type="checkbox"/>	O.R.?	<input type="checkbox"/>
Installer	Donna		Complaint	For GC		Notes	IH Villafuerte *VIP- IH Only * Appt: Nov, 25 morning. * WAC for GC.		
Location	5	Before	After						
Mode Setting (Cool)			No. of Visit	1st Action		Tentative Sched	11/25/2024		
WAC Setting Temp(16°C-RE)/(10/12-ME)			Findings						
SAC/PAC Setting Temp (17°)			W.A. but						
Discharge Temperature (High)	12.9								
Intake Temperature (High)	11.4								
Ampere	3.4		Recommendation						
Wattage (Inverter)									
Voltage	7m								
SAC/PAC Pressure (PSI)									
Part Code	Description				Qty	Unit Price		Amount	
Note: Corroded Condenser Metal part on fan motor									
10% discount									
SR No.	6				Labor	P 500			
Repair Done	only				Handling				
Repair Code					Others				
Date Attended	11-25-24		Date Finished	11-25-24		Total	P 500		
Time Attended	11:00		Time Finished	1:20		Amount Paid	P 500		
This serves as temporary receipt when properly filled up by authorized representative.					Check No.	Bank / Branch			
Serviced by:	Garry Munday, Neil Villafuerte				By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.				
I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					Created by:				
Technician(s)					Conformed by:				
GRACE PIELAGO CSR					Customer (Signature over printed name)				

No.
Previous SJR No.

HO-00731102



[illegible]



SERVICE JOB REPORT

No.	HO-00231104
Previous SJR No.	

Customer	Yap, Enrique Chua				Date	11-18-2024									
Address	30 Igualig St. , Brgy. Manresa, QUEZON CITY, Metro Manila				Start Time	11:58 am									
					End Time	11:58 am									
Telephone No.				Mobile No.	0932-5109783			Relayed by	Ms. Caress / Vibe						
Contact Person	Enrique	Mobile No.	0932-5109783	Tel. No.				Warranty Type	C						
Warranty Code				Room Size				Job Class	GC LVL 1						
Model	WAC-INV / CAG-12025			Call Origin	IO			Job Type	FD						
S/N (I)			S/N (O)			Permit?	<input type="checkbox"/>	Parking?	<input type="checkbox"/>	Appointment?	<input type="checkbox"/>	O.R.?	<input type="checkbox"/>	Ladder?	<input type="checkbox"/>
Dealer	Main House		DOP			Notes	IH Villafuente *VIP- IH Only * Appt: Nov. 25 morning * WAC for GC.								
Installer	Dami		Complaint	For GC											
Location	2	Before	After												
Mode Setting (Cool)				No. of Visit	1st Action		Tentative Sched	11/25/2024							
WAC Setting Temp(16°C-RE)/(10/12-ME)				Findings											
SAC/PAC Setting Temp (17°)				bry, bry											
Discharge Temperature (High)	11/25		11/25												
Intake Temperature (High)	11/25		11/25												
Ampere	7.4		7.6	Recommendation											
Wattage (Inverter)															
Voltage	170		170												
SAC/PAC Pressure (PSI)															

Part Code	Description	Qty	Unit Price	Amount
	Note: Corroded metal borders per hispan and for motor			
			10% discount	

SR No.			Labor	# 500
Repair Done			Handling	
			Others	
Repair Code			Total	# 500
Date Attended	11-28-24	Date Finished	11-28-24	Amount Paid
Time Attended	9:00	Time Finished	1:20	Balance
This serves as temporary receipt when properly filled up by authorized representative.			Check No.	Bank / Branch
Served by: Garry Munday, Neil Villafuerte		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.		
Technician(s)		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.		
Created by:		Conformed by:		
GRACE PIELAGO CSR		Customer (Signature over printed name)		



SERVICE JOB REPORT

No.	HO-00231110
Previous SJR No.	

[illegible]



SERVICE JOB REPORT

No.	HO-00231111
Previous SJR No.	

[illegible]