



6-Nov-2024

MR. VLADIMIR / BAMBI SAY

ATTN: MS. SHIELA/DONDON

3 YAP ST. COR. TABUENA, CORINTHIANS GARDEN, BRGY. UGONG NORTE, QUEZON CITY

TEL: 0917-5536478

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of OCTOBER 2024.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
09-Oct-24	HO-00225414	(1) KSG-SW30-6H1M	GENERAL CLEANING	1,500.00
TOTAL				P 1,500.00
LESS: DISCOUNT				(105.00)
TOTAL AMOUNT DUE				P 1,395.00

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**.


Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: BDO - KALAYAAN

011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assistant

Noted by:


Mar Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite

Tel.: (632) 8749-2118

Fax (046) 402-0793

www.kolinphil.com.ph / kolinphilippines

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,
Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791



K Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

SERVICE JOB REPORT

No. HO-00225414
Previous SJR No.

Customer	Say Bambi / Vladimir			Date	10-07-2024										
Address	3 Yap St. cor. Tabuena, Corinthians Garden, Bgry. Ugong Norte, QUEZON CITY			Start Time	05:00 pm										
Metro Manila...				End Time	05:06 pm										
Telephone No.	632-0513/514-7889/359-9899		Mobile No.	0917-5536478 / 0998-983118		Relayed by	Ms. Jing of Wimax / 09...								
Contact Person	Ms. Mariel	Mobile No.	0917-5536478	Tel. No.	0917-1147543	Warranty Type	C								
Warranty Code				Room Size			Job Class	GC	LVL	2					
Model	KSG-SW30-6H1M			Call Origin	MH		Job Type	FD							
S/N (I)	18211908-10107		S/N (O)	18221903-10041		Permit?	<input type="checkbox"/>	Parking?	<input type="checkbox"/>	Appointment?	<input type="checkbox"/>	O.R.?	<input type="checkbox"/>	Ladder?	<input type="checkbox"/>
Dealer	KMI		DOP	11/05/2020		Notes IH Talavera - pls check model name onsite									
Installer	Reymon Leyis		Complaint	For GC											
Location			Before	After											
Mode Setting (Cool)				No. of Visit	1st Visit		Tentative Sched	10/09/2024							
WAC Setting Temp (16°C-RE)/(10/12-ME)				Findings											
SAC/PAC Setting Temp (17°)				DIRTY UNIT											
Discharge Temperature (High)				13°C											
Intake Temperature (High)				26°C											
Ampere				10-A											
Wattage (Inverter)				Recommendation											
Voltage				CLEAN AIR FILTER REGULARLY											
SAC/PAC Pressure (PSI)				230V 150PSI											
Part Code	Description			Qty	Unit Price		Amount								
NOTE: PAYMENT 40 KMI															
10-09-24															
less 7%															
SR No.	GENERAL CLEANING			Labor	1500-										
Repair Done				Handling											
Repair Code				Others											
Date Attended	10-9-24		Date Finished	10-9-24		Total	1500-								
Time Attended	8:56		Time Finished	10:55		Amount Paid	1500-								
This serves as temporary receipt when properly filled up by authorized representative.				Check No.			Bank / Branch								
Served by: JOSELO BRASAS, Boyet Cuevas				By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.											
BOYET REX				I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.											
LITO				Created by: ROCHELE D. CORONO CSR		Conformed by: H. G. M. Customer (Signature over printed name)									