



1-Oct-2024

MR. JEROME KATIPUNAN

105 ENGINEERING ROAD, BRGY. POTRERO, MALABON CITY

TEL: 8721-8872/8726-5034

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of SEPTEMBER 2024.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
26-Sep-24	HO-00223635	(1) KSM-IW25-4F1M	LABOR	1,800.00
26-Sep-24	HO-00223635	(1) KSM-IW25-4F1M	PARTS REPLACEMENT (PCB)	7,150.00
TOTAL				P 8,950.00
LESS: 10% DISCOUNT ON PARTS				(715.00)
TOTAL AMOUNT DUE				P 8,235.00

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**


Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: BDO - KALAYAAN

011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assisitant

Noted by:


Mari Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

K Kolin Philippines Int'l., Inc.

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite

Tel: (632) 8749-2118

Fax (046) 402-0793

www.kolinphil.com.ph / kolinphilippines

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,
Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791



Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No. 8852 6868 / Mobile: 0917-811-8982 / Email: service@kolinphl.com.ph
Website: www.kolinphl.com.ph

TPWR 42577

SERVICE JOB REPORT

No.
Previous SJR No.

HO-00223635

Customer	Katipunan, Jerome			Date	09-25-2024		
Address	105 Engineering Road, Brgy. Poliretro, MALABON CITY, Metro Manila			Start Time	10:57 am		
				End Time	11:00 am		
Telephone No		Mobile No	0917-5836723 / 0917-128924	Received by	Yohan Yap		
Contact Person	Jerome	Mobile No		Warranty Type	C		
Warranty Code	KSM IW25 4F 1M			Job Class	TS	LVL	1
Model				Job Type	FD		
S.N (I)		S.N (O)	18101705-12921	Permit?	☐	Parking?	☐
Dealer		DOP	18101701-1145	Appointment?	☐	O/F?	☐
Installer		Complaint	Not Cooling	Ladder?	☐		
Location		Before		After			
Mode Setting (Cool)		Cool		No. of Visit	1st Action	Tentative Sched	09/26/2024
WAC Setting Temp (16 C-RE) (10/12-ME)				Findings			
SAC PAC Setting Temp (17)		17°C		Burnt out PCB (O)			
Discharge Temperature (High)		14°C					
Intake Temperature (High)		23°C					
Ampere		12.7		Recommendation			
Wattage (Inverter)				Clean Air Filter Regularly			
Voltage		235					
SAC PAC Pressure (PSI)		115					
Part Code	Description			Qty	Unit Price	Amount	
	PCB (O)			1	7150	7150 -	
	SILICON PASTE					less 10%.	
						= 6,435.-	
	3 months Warranty.						
NOTE: PAYMENT FOR COLLECTION							
SR No.				Labor	1800 -		
Repair Done	REPLACED PCB (O)			Handling			
Repair Code				Others			
Date Attended	9-26-24	Date Finished	9-26-24	Total	8950 -		
Time Attended	9:42	Time Finished	10:40	Amount Paid			
This serves as temporary receipt when properly filled up by authorized representative.				Balance	8950 -		
Check No.				Bank / Branch	8,235.00 TOTAL		
Served by:	Josefina Briones, Boyet Cuevas			I hereby agree to the above repair charges incurred to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Signature	BOYET REX LITO			Created by:	Sheiry Anne B. Gom... CSR		
Technician(s)				Conformed by:	Yohan Yap (Signature over printed name)		