



1-Oct-2024

MS. FINA CHUA

6 ST. PETER ST., REMERVILLE SUBDIVISION, BRGY. BAESA PROJECT 8, QUEZON CITY

TEL: 0917-5252177

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of SEPTEMBER 2024.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
28-Sep-24	HO-00223743	n/a	SURVEY	500.00
TOTAL AMOUNT DUE				<u>P 500.00</u>

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

**Note:** If check payment, please prepare check payable to **Kolin Philippines International Inc.**

**Account #: BDO - KALAYAAN**


**011808000428**

**Note:** In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi\_asst@kolinphil.com.ph**

Prepared by:

  
**Janellen S. Lim**  
KMI - Assisitant

Noted by:

  
**Mar Nathaniel R. Flores**  
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,  
Brgy. Langkaan I, Dasmariñas, Cavite

Tel: (632) 8749-2118

Fax (046) 402-0793

[www.kolinphil.com.ph](http://www.kolinphil.com.ph) / [kolinphilippines](http://kolinphilippines)

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,  
Makati City

Tel: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791







1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: [service@kolinphil.com.ph](mailto:service@kolinphil.com.ph)  
Website: [www.kolinphil.com.ph](http://www.kolinphil.com.ph)    [kolinphilippines](https://www.facebook.com/kolinphilippines)

## SERVICE JOB REPORT

No.  
Previous SJR No.

HO-00223743

HD-0022840

Customer		Chua, Fina				Date		09-25-2024			
Address		631 Peter St., Remerville Subdivision, Brgy. Baesa Project 8, QUEZON CITY, Metro Manila				Start Time		04:51 pm			
						End Time		04:58 pm			
Telephone No.				Mobile No.		0917-5252177		Relayed by		Chua, Fina	
Contact Person		Fina		Mobile No.		0917-5252177		Tel. No.			
Warranty Code				Room Size				Job Class		SVEY LVL 1	
Model		wa		Call Origin		TF		Job Type		FD	
S/N (I)				S/N (O)				Permit? <input type="checkbox"/>		Parking? <input type="checkbox"/>	
Dealer				DOP				Appointment? <input type="checkbox"/>		O.R.? <input type="checkbox"/>	
Installer				Complaint		For Survey		Notes		DADIOS Note: Yung sa master's bedroom yun yung tatanggalin tapos ilipat sa office nito me'am sa QC. tapos yung ilagay sa master's bedroom mangagaling sa data nito same address, customer is also requesting for discount.	
Location				Before		After					
Mode Setting (Cool)						No. of Visit		1st Action		Tentative Sched	
WAC   Setting Temp(16°C-RE)/(10/12-ME)										09/27/2024	
SAC/PAC   Setting Temp (17°)										Findings	
Discharge Temperature (High)											
Intake Temperature (High)											
Ampere										Recommendation	
Wattage (Inverter)										KSM-1W25-4T1M (OLD UNIT) ST# 30	
Voltage										2 OPTION - 3P2 MTB UNIT ST# 30	
SAC/PAC   Pressure (PSI)										FOR QUOTATION	
Part Code		Description				Qty		Unit Price		Amount	
		QUOTATION SEND TO KASAM FAX									
SR No.		SURVEY AREX				Labor		500			
Repair Done						Handling					
Repair Code						Others					
Date Attended		9-26-24		Date Finished		9-28-24		Amount Paid		FOR COLLECT	
Time Attended		1:00 PM		Time Finished		1:50 PM		Balance		10 km	
This serves as temporary receipt when properly filled up by authorized representative.						Check No.		Bank / Branch			
Served by: Jeffery Darios				By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.							
				I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
Technician(s)				Created by: RECHILLA CSR				Conformed by: JEFFREY D. DARIOS Customer (Signature over printed name)			