

7-Oct-2024

UNITEC RESOURCES INC.

ATTN: MR. JOSEPH DOMINGO

1199 MENDIOLA EXTENSION, BRGY. 532 PACO, MANILA CITY

TEL: 0917-8251434

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of MAY 2024. Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR#	QUANTITY/MODEL	SERVICE JOB DONE		AMOUNT
27-May-24	HO-00204445	(1) KFS-45DINV	GENERAL CLEANING		5,970.00
	TOTAL				5,970.00
	LESS: DISCOUNT				(417.90)
	TOTAL AMOUNT DUE			P	5,552.10

For any clarifications please feel free to call the Undersigned at the telephone number 8852-6473

Note: If check payment, please prepare check payable to Kolin Philippines International Inc.

Account #: BDO - KALAYAAN

011808000428

Note: In case thru Bank Deposit under BDO Account, kindly inidicate SJR# for your Bank Reference in the deposit slip and Fax to (632) 8852-6473 or E-mail to: kmi asst@kolinphil.com.ph

Prepared by:

Janellen S. Lim KMI - Assisitant

Received by:

Signature over printed name

Noted by

Mair Nathaniel R.

KMI - Supervisor



Kolin Philippines Int'l., Inc.

Plant and Head Office: Blk 3 Lt 5 Main Drive, FCIE Compound, Brgy, Langkaan I, Dasmariñas, Cavite Tel.: (632) 8749-2118 Fax (046) 402-0793 www.kolinphil.com.ph / kolinphilippines

Operation Office: 1854 Sta. Rita St., Guadalupe Nuevo, Makati City Tel.: (632) 8851-2711, 12 or 15 Fax: (632) 8852-2170 Sales Dept. Fax: (632) 8852-4791

54 Sta. Rita St. Gua d. No.: 8852-6868 / M ebsite: www.kolinphil.	Philippinodalupe Nuevo, Makati City, obile: 0917-811-8982 / Email: com.ph 1000 Notine	service okoling	No. Previous SIR No.	HO-00204445					
Customer		Previous SJR No Initiac Resources Inc.							
Address	, 1199 Mendiala E	xtension,,	05-24-2024 01:45 pm						
		100000000000000000000000000000000000000					End Time	01:47 pm	
Telephone No.	8562-7132-34			Mobile No.	0917-6	251434/0917-7083	THE RELEASE OF THE PARTY OF THE	RICHARD TALAVERA	
Contact Person	Joseph Domingo	Mobile No.	0956-623	1445	Tel. No.		Warranty Type	C	
Warranty Code		40 1 10 12			Room Size		Job Class	TS LVL 1	
Model	KFS-45DINV			Call Origin	Ю	Job Type	PO		
S/N (I)			S/N (O)	151714	12 - 10152	Permit? Parking?		O.R.? Ladder?	
Dealer			DOP						
Installer			Complaint	Not Co				SOR	
Location	OUTDOOR(HR DI	EDTRafara		INDI CO	oung				
		- ipelore	After			F	12		
Mode Setting (Co					No. of Visit		Tentative Sched	05/30/2024	
	mp(16°C-RE)/(10/12-ME)			1 2 2 2		F	indings		
SAC/PAC Setting						r about			
Discharge Tempe									
Intake Temperatu	re (High)								
Ampere			:	11	11	Recon	nmendation		
Wattage (Inverter)				BOOK .					
Voltage				BY					
SAC/PAC Press	ure (PSI)			DATE		1201 - 1- 3			
Part C	ode		Des	cription		Qty	Unit Price	Amount	
-1105/20/2 TH8010/20/2 15610007/201 E2010013		Frenn 4	10a (11.3)	(II)			170 0	10	
		Access Valve (Affiche)			1		1.00 0.	90	
		Strainer	(5) 6/16x	1/9			1.00 0.		
		Genacitor (rouser Eur Pisco) : Pho220.00			100	1.00	1.00		
			7) AT	4.	1 10000		Samuel and the same of the sam		
				A)	15		The second second	English Street	
			ULL	17,7	14		•		
		A Section 1	164:"	11/13	100				
				10	5/1/1		1 7 7 7 1 1 1 1 1		
		CLA	W 500	1	1/1	1)			
	CONTRACTOR OF THE STATE OF THE	1 J AA				1 6/13			
			of the state of		1	/ ")			
SR No.							Labor		
	SIAHCH00037375					Handling	5,250.0		
Repair Done	Findings - Leak at oil separator, fan capacitor too (60f) under valu						500.00		
Panair Codo							Systematic process.		
Repair Code	Done Ev past	04 28						replace (an capitation)	
Date Attended		1 - System BaterRinished with Ceneral Cleaning					Amount Paid	5,970.0	
Time Attended 05/27/2024					06/11/2024		Balance	0.00	
	corary receipt when properly				Check No.	08:30 tun	Bank / Branch	59700	
Serviced by: Her	nino Barrera	by signing be information for	elow, I authoriz or availing serv	e or give con	sent to Kolin P	hilippines International, Inc.	and its ASC to collect, sto	re and process my personal tions.	
	A STATE OF THE STATE OF	I hereby agre		repair charg	es incurred/to			stated at the back, and that I	