

DR. WELSON YAP / KUN CHI CHIUNG HONGKONG TEMPLE
 2455 TINDALO ST. COR. CAVITE ST., TONDO MANILA
 TEL: 0917-8440817

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of AUGUST 2024.
 Details of the charges are stated below and a copy of the Service Job Report is attached for your references:


DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
05-Aug-24	HO-00215970	(1) KSG-150B1G	GENERAL CLEANING	1,500.00
05-Aug-24	HO-00215973	(1) KSG-150B1G	GENERAL CLEANING	1,500.00
05-Aug-24	HO-00215975	(1) KSG-300B1F	GENERAL CLEANING	1,500.00
05-Aug-24	HO-00215977	(1) KSG-300B1F	GENERAL CLEANING	1,500.00
05-Aug-24	HO-00215978	(1) KSG-100B1G	GENERAL CLEANING	1,500.00
05-Aug-24	HO-00215980	(1) KSG-100B1G	GENERAL CLEANING	1,500.00
05-Aug-24	HO-00215982	(1) KAG-120RS	GENERAL CLEANING	800.00
05-Aug-24	HO-00215985	(1) KSG-300B1F	GENERAL CLEANING	1,500.00
05-Aug-24	HO-00215987	(1) KSG-300B1F	GENERAL CLEANING	1,500.00
05-Aug-24	HO-00215988	(1) KSM-IW15-9L1M-I	GENERAL CLEANING	1,500.00
10-Aug-24	HO-00216700	(1) KSG-100B1G	RELOCATION OF DRAIN LINE	1,500.00
10-Aug-24	HO-00216702	(1) KSG-300B1F	RELOCATION OF DRAIN LINE	2,050.00
22-Aug-24	HO-00218613	(1) KSG-300B1F	INSTALLATION OF DRAIN LINE	1,800.00
TOTAL				₱ 19,650.00
LESS: DISCOUNT				(1,375.50)
TOTAL AMOUNT DUE				₱ 18,274.50

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**
Account #: BDO - KALAYAAN 011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
 KMI - Assistant

Noted by:


Marit Nathaniel R. Flores
 KMI - Supervisor

Received by:


Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:
 Blk 3 Lt 5 Main Drive, FCIE Compound,
 Brgy. Langkaan I, Dasmarinas, Cavite
 Tel.: (632) 8749-2118
 Fax (046) 402-0793
www.kolinphil.com.ph / [kolinphilippines](http://kolinphilippines.com)


Operation Office:
 1854 Sta. Rita St., Guadalupe Nuevo,
 Makati City
 Tel.: (632) 8851-2711, 12 or 15
 Fax: (632) 8852-2170
 Sales Dept. Fax: (632) 8852-4791






No.	HO-00215970
Previous SJR No.	

Green - Service



No. HO-00215973

Case Studies



SERVICE JOB REPORT

~~HO-00215975~~

[illegible]

White - Customer Blue - Accounting Green - Services

K Kolin Philippines Int'l., Inc.

1654 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

SERVICE JOB REPORT

Customer		Yap, Dr. Welson / Kun Chi Chung Hongkong Temple		No. Previous SJR No.		HO-00215977	
Address		2455 Tindalo St. cor. Cavite St. . . Tondo, MANILA CITY, Metro Manila		Date		07-31-2024	
Telephone No.		Mobile No. 0917-8440817		Start Time		02:13 pm	
Contact Person		Dr. Welson		End Time		02:14 pm	
Warranty Code		Mobile No. 0917-8440817		Relayed by		ADR	
Model		KSG-300B1F		Warranty Type		C	
S/N (I)		Unit#5 (I)16111704-10142		Room Size		Job Class GC LVL 1	
Dealer		DOP		Call Origin		Job Type FD	
Installer		Complaint For GC		Permit? ☐ Parking? ☐ Appointment? ☐		O.R? ☐ Ladder? ☐	
Location		Living room		Notes		LOJERO APPT. AUG. 5, 2024	
Mode Setting (Cool)		Before After		Tentative Sched		08/05/2024	
WAC Setting Temp(16°C-RE)(10/12-ME)		Cool		No. of Visit 1st Action		Findings	
SAC/PAC Setting Temp (17°)		17		Water Dripping, clogged Drain line			
Discharge Temperature (High)		12.2					
Intake Temperature (High)		28					
Ampere		12.4A		Recommendation			
Wattage (Inverter)				2MD action For Re location of Drain			
Voltage				Temporary only (Drain sahod lang)			
SAC/PAC Pressure (PSI)		60PSI		A-S M / Schedule			
Part Code		Description		Qty		Unit Price	
Amount							
Needed *		Drain Hoge white 3 mtrs					
		Drain pad Hoge 1pc					
SR No.		Labor		Handling			
Repair Done		Rendered for cleaning & flushing		Others			
Repair Code		Drain line still drain line clogged		Total		1500.00	
Date Attended		8-5-24		Amount Paid		For Collection	
Time Attended		9:25 AM		Balance		1,500.00	
Time Finished		5:25 PM		Bank / Branch			
This serves as temporary receipt when properly filled up by authorized representative.		Check No.					
Serviced by		Kavin Sener, Manuel Raposo		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
Vidal Nallas		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.		Created by:		Conformed by:	
Technician(s)		LUIS KEBUYAS CSR		Customer		(Signature over printed name)	

SERVICE JOB REPORT

No. HO-00215978


Customer	Yap, Dr. Welson / Kun Chi Chung Hongkong Temple			Previous SJR No.			
Address	2455 Tindalo St. cor. Cavite St. , Tondo, MANILA CITY, Metro Manila			Date	07-31-2024		
Telephone No.			Mobile No.	0917-8440617		Relayed by	ADR
Contact Person	Dr. Welson	Mobile No.	0917-8440617	Tel. No.			
Warranty Code				Room Size			
Model	KSG-100B1G			Call Origin	10		
S/N (I)	Unit#6 (I)1601107-18416	S/N (O)			Permit?	Parking?	Appointment?
Dealer			DOP			O.R?	Ladder?
Installer			Complaint	For GC			
Location	Room 3	Before	After				
Mode Setting (Cool)			COOL	No. of Visit	1st Action	Tentative Sched	09/05/2024
WAC Setting Temp(16°C-REY)(10/12-ME)			17°C	Findings			
SAC/PAC Setting Temp (17°)			17°C	DIRTY UNIT			
Discharge Temperature (High)			12°C				
Intake Temperature (High)			25°C				
Ampere			4A	Recommendation			
Wattage (Inverter)							
Voltage			230V				
SAC/PAC Pressure (PSI)			60 PSI				
Part Code	Description			Qty	Unit Price	Amount	
PAYMENT c/o KMI							
				DATE: 8/6/24		BY: [Signature]	
SR No.				Labor	1,500-		
Repair Done	GENERAL CLEANING			Handling			
Repair Code				Others			
Date Attended	8-5-24	Date Finished	8-5-24	Total	1,500-		
Time Attended	9:05	Time Finished		Amount Paid			
This serves as temporary receipt when property filled up by authorized representative.				Check No.	Bank / Branch		
Serviced by:	Kavin Senar, Manuel Rapsung			By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
NIDAL REX				I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Technician(s)				Created by:	Conformed by:		
				LUIS REBUYAS	Customer		
				CSR	(Signature over printed name)		

Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6968 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

SERVICE JOB REPORT

No. HO-00215980
Previous SJR No.

Customer	Yap. Dr. Welson / Kun Chi Chung Hongkong Temple			Date	07-31-2024		
Address	2455 Tindalo St. cor. Cavite St. ., Tondo, MANILA CITY, Metro Manila			Start Time	02:17 pm		
				End Time	02:19 pm		
Telephone No.		Mobile No.	0917-8440817		Relayed by	ADR	
Contact Person	Dr. Welson	Mobile No.	0917-8440817	Tel. No.		Warranty Type	C
Warranty Code		Room Size		Job Class	GC	LVL	1
Model	KSG-100B1G		Call Origin	IC	Job Type	FD	
S/N (I)	Unit#7 (I)16011607-18229	S/N (O)		Permit? ☐	Parking? ☐	Appointment? ☐	O.R? ☐ Ladder? ☐
Dealer		DOP		Notes LOJERO APPT. AUG. 5, 2024			
Installer		Complaint	For GC				
Location	Room 4	Before	After				
Mode Setting (Cool)		No. of Visit	1st Action	Tentative Sched	09/05/2024		
WAC Setting Temp(16°C-RE)(10/12-ME)		Findings					
SAC/PAC Setting Temp (17°)		Water Dripping, clogged Drain line.					
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere		Recommendation					
Wattage (Inverter)		2ND Action for relocation of Drain Temporary only (Drain Sashed lang) ASA schedule					
Voltage							
SAC/PAC Pressure (PSI)							
Part Code	Description	Qty	Unit Price	Amount			
	Needed x Drain Hose white	3 mtrs					
	Drain pad Hose	1 pcs					
							
SR No.				Labor	8/6		
Repair Done	Rendered for cleaning & flushing drain line. still clogged Drain line.			Handling			
Repair Code				Others			
Date Attended	8-5-24	Date Finished	8-5-24	Total	11,500.00		
Time Attended	9:05 AM	Time Finished	5:25 PM	Amount Paid	for collection		
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		
Serviced by Kevin Sener, Manuel Rapera				By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
Vidal Nallas				I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Technician(s)				Created by:	Conformed by:		
				LUIS REJUYAS CSR	Customer (Signature over printed name)		



1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph [kolinphilippines](https://www.facebook.com/kolinphilippines)

SERVICE JOB REPORT

HO-00215982

Previous SJR No.

[illegible]

SERVICE JOB REPORT

No.
Previous SJR No.

HO-00215985

[illegible]


Kolin Philippines Int'l., Inc.

1654 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

SERVICE JOB REPORT

No. **HO-00215987**
Previous SJR No.

Customer	Yap. Dr. Welson / Kun Chi Chung Hongkong Temple			Date	07-31-2024			
Address	. 2455 Tindalo St. cor. Cavite St. ., Tondo, MANILA CITY, Metro Manila			Start Time	02:26 pm			
				End Time	02:27 pm			
Telephone No.			Mobile No.	0917-8440817		Relayed by	ADR	
Contact Person	Dr. Welson	Mobile No.	0917-8440817	Tel. No.			Warranty Type	C
Warranty Code				Room Size			Job Class	GC LVL 1
Model	KSG-300B1F			Call Origin	IO		Job Type	FD
S/N (I)	Unit#10 (I)16111704-10116	S/N (O)			Permit?	Parking?	Appointment?	O.R? Ladder?
Dealer			DOP			Notes LOJERO APPT. AUG. 5, 2024		
Installer			Complaint	For GC				
Location	Living room	Before	After					
Mode Setting (Cool)			COOL	No. of Visit	1st Action	Tentative Sched	09/05/2024	
WAC Setting Temp(16°C-RE)(10/12-ME)				Findings				
SAC/PAC Setting Temp (17°)				14°C DIRTY UNIT				
Discharge Temperature (High)				12°C				
Intake Temperature (High)				26°C				
Ampere				12A				
Wattage (inverter)				Recommendation				
Voltage				230V				
SAC/PAC Pressure (PSI)				60 PSI				
Part Code	Description			Qty	Unit Price	Amount		
PAYMENT c/o KMI								
				DATE CLERK BY: 8/6/24				
SR No.				Labor	1,500-			
Repair Done	GENERAL CLEANING			Handling				
Repair Code				Others				
Date Attended	8-5-24	Date Finished	8-5-24	Total	1,500-			
Time Attended	9:05	Time Finished	5:25	Amount Paid				
				Balance	1,500-			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch			
Serviced by: Garry Munday, Neil Villafuerte, Salomon				By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.				
VIVALDI DEX				I hereby agree to the above repair charges incurred to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.				
VIVANALU JAY				Created by:	Conformed by:			
Technician(s)				LUIS REBLYAS CSR	Customer (Signature over printed name)			



1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph    [kolinphilippines](https://www.facebook.com/kolinphilippines)

SERVICE JOB REPORT

No. _____
Previous SJR No. _____

HO-00215988

[illegible]

Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

SERVICE JOB REPORT

No. HO-00216700
Previous SJR No. HO-00213970

Customer	Yap, Dr. Welson / Kun Chi Chung Hongkong Temple			Date	08-08-2024				
Address	, 2455 Tindalo St. cor. Cavite St., Tondo, MANILA CITY, Metro Manila			Start Time	08:48 am				
				End Time	08:54 am				
Telephone No.			Mobile No.	0917-8440617		Relayed by	lojero		
Contact Person	Dr. Welson	Mobile No.	0917-8440617	Tel. No.			Warranty Type	C	
Warranty Code			Room Size			Job Class	TS LVL 1		
Model	KSG-100B1G		Call Origin	IO		Job Type	FD		
S/N (I)	Unit#7 (I)16011607-18225	S/N (O)			Permit?	Parking?	Appointment?	O.R.?	Ladder?
Dealer			DOP			Notes: LOJERO Findings - Water dripping, clogged drain line and dirty unit. Recommendation - 2nd action for relocation of drain, temporary only (drain sahod lang) asap schedule. Note: Need drain hose white and drain pad hose. (original hose)			
Installer			Complaint	Water Dripping					
Location	Room 4	Before	After						
Mode Setting (Cool)				No. of Visit	2nd Action	Tentative Sched	08/13/2024		
WAC Setting Temp(16°C-REY(10/12-ME)				Findings					
SAC/PAC Setting Temp (17°)									
Discharge Temperature (High)									
Intake Temperature (High)									
Ampere				Recommendation					
Wattage (Inverter)									
Voltage									
SAC/PAC Pressure (PSI)									

Part Code	Description	Qty	Unit Price	Amount
	Drain Hose White	10 feet	10 x 25	250
LIQUIDAT DATE: 8/12/24				
Need Surveyor for relocation of drain line				
8/12				

SR No.	8890216700 - Out temporary	Labor	1,250
Repair Done	Drain line	Handling	
Repair Code		Others	
		Total	1,500
Date Attended	8-10-24	Date Finished	8-10-24
Time Attended	12:30	Time Finished	1:50
This serves as temporary receipt when properly filled up by authorized representative.		Check No.	
Serviced by: Kevin Senior, Manuel Rapana		Bank / Branch	Collection
By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
I hereby agree to the above repair charges incurred to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Technician(s)	Created by: RECHILA	Conformed by:	Customer
	CSR		(Signature over printed name)

Customer		Yap, Dr. Wilson / Kun CHI Chung Hongkong Temple		No. Previous SJR No.		HO-00216702	
Address		2455 Tindalo St. cor. Cavite St. Torio, MANILA CITY, Metro Manila		Date		08-08-2024	
Telephone No.		Mobile No. 0917-8440817		Start Time		08:58 am	
Contact Person		Dr. Wilson		End Time		08:59 am	
Warranty Code		Mobile No. 0917-8440817		Relayed by		Leyro	
Model		KSG-300B1F		Warranty Type		C	
S/N (I)		Unit#5 (I)16111704-10142		Room Size		Job Class TS LVL 1	
Dealer		DOP		Call Origin		Job Type FD	
Installer		Complaint		Permit? ☐ Parking? ☐ Appointment? ☐ O.R.? ☐ Ladder? ☐			
Location		Before After		Notes		L.O.I.E.R.O Findings - Water dripping, clogged drain line. Recommendation - 2nd action for relocation of drain, temporary only (drain siphon long) asap schedule. Note: Need drain hose while 3mtr and drain pad hose 1pc. (original hose)	
Mode Setting (Cool)		No. of Visit		Tentative Sched		08/13/2024	
WAC Setting Temp(16°C-REY(10/12-ME)		2nd Action		Findings			
SAC/PAC Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere				Recommendation			
Wattage (Inverter)							
Voltage							
SAC/PAC Pressure (PSI)							

Part Code	Description	Qty	Unit Price	Amount
	Drain Hose	1	550	550
	Drain Hose white	10feet	10x25	250
Need further of chain line for relocation of chain line LIQUIDATED 8/10/24 8/12				

SR No.	34902 at out temporary	Labor	1,250
Repair Done	Chain line	Handling	
Repair Code		Others	
Date Attended	8-10-24	Total	2,050
Time Attended	12:30	Amount Paid	
		Balance	2,050
This serves as temporary receipt when properly filled up by authorized representative.		Bank / Branch	Collection
Serviced by: Kevin Sesar, Manuel Rapsin By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations. I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition. Created by: RECHILLA CSR Conformed by: LINDA TAN Customer (Signature over printed name)			

