



23-Sep-2024

MS. TIFFANY CHUA SIY

#38 STO. DOMINGO ST. URDANETA VILLAGE, BRGY. URDANETA, MAKATI CITY

TEL: 894-1105 / 0927-6091464

Sir/ Madam,

This is to bill you on the service job done to your unit for the following months of 2024.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
30-Apr-24	HO-00199709	(1) KSM-IW25-4F1M	GENERAL CLEANING	750.00
06-May-24	HO-00200840	(1) KSM-IW25-4F1M	GENERAL CLEANING	1,500.00
13-Aug-24	HO-00217422	(1) KSM-IW25-4F1M	CLOGGED DRAIN LINE	450.00
TOTAL				P 2,700.00
LESS: DISCOUNT				(270.00)
TOTAL AMOUNT DUE				P 2,430.00

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**


Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: BDO - KALAYAAN


011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assisitant

Noted by:


Mari Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:

 Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite

 Tel.: (632) 8749-2118

 Fax (046) 402-0793

 www.kolinphil.com.ph / [kolinphilippines](http://kolinphilippines.com)

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,
Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791







K Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

SERVICE JOB REPORT

No. **HO-00199709**
Previous SJR No.

Customer	Chua Tiffany			Date	04-30-2024		
Address	#38 Sto. Domingo St., Urdaneta Village, Brgy. Urdaneta, MAKATI CITY, Manila			Start Time	10:43 am		
Telephone No.	894-1105	Mobile No.	0927-5091464 / 0917-8932079		End Time	10:53 am	
Contact Person	Tiffany	Mobile No.	...	Tel. No.	894-1105	Warranty Type	C
Warranty Code	M125		Room Size			Job Class	GC LVL 1
Model	KSM-IW20-4F1M		Call Origin	IO		Job Type	FD
S/N (I)	18071701-11869	S/N (O)	ACU#11-1ST FLOOR		Permit?	Parking?	Appointment?
Dealer	1809 702-12533	DOP			Notes	Cuevas ** Pla. verify and update unit's location. * TECH	
Installer	MASTER Bedroom		Complaint	For GC		VIP TEAM * PLS SCHED ASAP * COLLECTION C/O KMI * WITH PARKING	
Location	Daughter's room (ACU#11-15...		Before	After			
Mode Setting (Cool)		No. of Visit	1st Action		Tentative Sched	05/07/2024	
WAC Setting Temp (16°C-RE) (10/12-ME)		Findings					
SAC/PAC Setting Temp (17°)		LEAK AT COMPRESSION / DIRT / UNIT					
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere		Recommendation					
Wattage (Inverter)		CHECK AND FILTER REGULARLY					
Voltage		FOR REPLACEMENT OF COMP.					
SAC/PAC Pressure (PSI)		FOR 2ND ACTION					
Part Code	Description			Qty	Unit Price	Amount	
Ref. # 201444							
PAYMENT FOR COLLECTION 70 KMI							
 							
SR No.				Labor	1500-		
Repair Done	AIR FILTER CLEANING			Handling			
Repair Code	7			Others			
Date Attended	5-6-24	Date Finished	5-6-24	Total	1500-		
Time Attended	12:30	Time Finished	2:30	Amount Paid			
This serves as temporary receipt when property filled up by authorized representative.				Check No.	Bank / Branch		
					(750.00)		
Served by: Joselito Brasos, Boyel Cuevas				By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
 				I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Technician(s)				Created by:	Conformed by:		
GRACE PIELAGO				CSR	JOSUITO Camarling		
				Customer (Signature over printed name)			



SERVICE JOB REPORT

No.
Previous SJR No.

HQ-00200840

[illegible]

