



12-Mar-2025

**DR. WELSON YAP / KUN CHI CHIUNG HONGKONG TEMPLE**  
2455 TINDALO ST. COR. CAVITE ST., TONDO MANILA  
TEL: 0917-8440817

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of MARCH 2025.  
Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
07-Mar-25	HO-00244413	(1) KSM-IW15-9L1M-I	GENERAL CLEANING	1,500.00
				₱ 1,500.00
				(105.00)
				₱ 1,395.00

**Notes:**

\* If check payment, please prepare check payable to **Kolin Philippines International Inc.**  
**Account #: 011808000428 - BDO - KALAYAAN**

\* In case thru Bank Deposit under BDO Account, kindly indicate **(1) SJR#** as Reference No. on the deposit slip  
Kindly send proof of payment to **viber 0917-8078607** or E-mail to: **kmi\_asst@kolinphil.com.ph**

For any clarifications please feel free to call the Undersigned on this telephone number **8852-6473**.

Prepared by:

Janellen S. Lim  
KMI - Assistant

Noted by:

Mart-Nathaniel R. Flores  
KMI - Supervisor

Received by:

Signature over printed name

Kolin Philippines Int'l., Inc.

Plant and Head Office:  
Blk 3 Lt 5 Main Drive, FCIE Compound,  
Brgy. Langkaan I, Dasmariñas, Cavite  
Tel: (632) 8749-2118  
Fax (046) 402-0793  
www.kolinphilippines.com.ph / kolinphilippines

Operation Office:  
1854 Sta. Rita St, Guadalupe Nuevo,  
Makati City  
Tel: (632) 8851-2711, 12 or 15  
Fax: (632) 8852-2170  
Sales Dept. Fax: (632) 8852-4791



# K Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
 Tel. No. 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph  
 Website: www.kolinphil.com.ph     

## SERVICE JOB REPORT

No.  
 Previous SJR No.

HO-00244413

Customer	Yap, Dr. Welson / Kun Chi Chung Hanokong Temple			Date	03-05-2025					
Address	, 2456 Tindalo St. cor. Cavite St., Tondo, MANILA CITY, Metro Manila			Start Time	09:44 pm					
				End Time	09:45 pm					
Telephone No.			Mobile No.	0917-8440817		Relayed by	Caress			
Contact Person	Dr. Welson / Ceasar	Mobile No.	0917-8440817	Tel. No.	0995-6490590	Warranty Type	C			
Warranty Code				Room Size						
Model	KSM-IW15-BL1M-I			Call Origin	ID					
S/N (I)	18562112-11514		S/N (O)	18562112-10323		Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>
Dealer	KMI		DOP	06/15/2022		Notes *Last GC - September 2024				
Installer	Richard Talavera		Complaint	Water Dripping						
Location	TEMPLE 2ND FLOOR		Before	After						
Mode Setting (Cool)				No. of Visit	1st action	Tentative Sched		03/07/2025		
WAC   Setting Temp(16°C-RE)/(10/12-ME)				Findings						
SAC/PAC   Setting Temp (17°)										
Discharge Temperature (High)										
Intake Temperature (High)										
Ampere	7.0		7.1	Recommendation						
Wattage (Inverter)										
Voltage										
SAC/PAC   Pressure (PSI)										
Part Code	Description						Qty	Unit Price	Amount	
SR No.							Labor	81.50		
Repair Done							Handling			
							Others			
Repair Code							Total	81.50		
Date Attended	3/10/25		Date Finished	3/10/25		Amount Paid				
Time Attended	10:00		Time Finished	10:30		Balance	3.50			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.			Bank / Branch			
Serviced by: Garry Munday, Neil Viloria		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.								
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.								
		Created by:		Conformed by:						
		ALVIN DE RIVERA		B. RIVERA						
Technician(s)		CSR				Customer (Signature over printed name)				