

6-Mar-2025

MR. FREDERICK UYSIPUO
ATTN: MS. CHARLENE
654 RICHMOND ST., BRGY. GREENHILLS EAST, MANDALUYONG CITY
TEL: 0917-8162271

Sir/ Madam,

This is to bill you on the service job done to your unit for the following months.
Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR#	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
03-Dec-24	HO-00232919	(1) KSM-30MB1INV	PARTS REPLACEMENT	14,900.00
01-Dec-24	HO-00233317	(1) KSM-30MB1INV	CHECK UP	450.00
05-Dec-24	HO-00233319	(1) KSM-30MB1INV	GENERAL CLEANING	1,500.00
12-Feb-25	HO-00241619	(1) KSM-25MB1INV	CHECK UP	450.00
12-Feb-25	HO-00241620	(1) KSM-20MB1INV	CHECK UP	450.00
TOTAL				P 17,750.00
LESS: DISCOUNT				(1,242.50)
TOTAL AMOUNT DUE				P 16,507.50

Notes:


* If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: 011808000428 - BDO - KALAYAAN

* In case thru Bank Deposit under BDO Account, kindly indicate **(1) SJR#** as Reference No. on the deposit slip.
Kindly send proof of payment to **viber 0917-8078607** or E-mail to: **kmi_asst@kolinphil.com.ph**


For any clarifications please feel free to call the Undersigned on this telephone number **8852-6473**.

Prepared by:



Janellen S. Lim
KMI - Assistant

Noted by:



Mart Nehaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:
Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite
Tel: (632) 8749-2118
Fax (046) 402-0793
www.kolinphil.com.ph / kolinphilippines

Operation Office:
1854 Sta. Rita St, Guadalupe Nuevo,
Makati City
Tel: (632) 8851-2711, 12 or 15
Fax: (632) 8852-2170
Sales Dept. Fax: (632) 8852-4791





HO-00232919

By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.

I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.

Created by:

Conformed by:

Customer
(Signature over printed name)





Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City

Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph

Website: www.kolinphil.com.ph    

SERVICE JOB REPORT

No. **HO-00241619**
Previous SJR No. **HO-00232919**

Customer	Uysipud, Frederick			Date	02-11-2025			
Address	654 Richmond St., Brgy. Greenhills East, MANDALUYONG CITY, Metro Manila			Start Time	08:40 am			
Telephone No.	88725-0026	Mobile No.	0917-8162271	End Time	08:52 am			
Contact Person	Chaffene/ Fred	Mobile No.	0917-8162271	Tel. No.	02-88725-0026	Warranty Type	C	
Warranty Code				Room Size	Job Class			
Model	KSM-25MB1INV			Call Origin	IO	Job Type	FD	
S/N (I)	10911508-15991	S/N (O)	1	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R? <input checked="" type="checkbox"/> Ladder? <input type="checkbox"/>	
Dealer	DOP			Notes Cuevas * 2 units for check-up * PAYMENT COLLECTION C/O KMI * KC REFERRAL				
Installer	Complaint P1 Error Code							
Location	Kitchen	Before	After	No. of Visit	1st Action	Tentative Sched	02/13/2025	
Mode Setting (Cool)				Findings				
WAC Setting Temp(16°C-RE)/(10/12-ME)		—						
SAC/PAC Setting Temp (17°)		17°C	Unit ok as per customer					
Discharge Temperature (High)		15.8°C	(Nag-error dahil sa fluctuation ng kuryente)					
Intake Temperature (High)	N/A	30°C						
Ampere		6.7A	Recommendation					
Wattage (Inverter)		—						
Voltage		225V						
SAC/PAC Pressure (PSI)		146PSI						
Part Code	Description			Qty	Unit Price	Amount		
SR No.				Labor	\$450.00			
Repair Done	Check up / Reset breaker only			Handling				
	Run test / Unit ok			Others				
Repair Code				Total	\$450.00			
Date Attended	2-12-25	Date Finished	2-12-25	Amount Paid				
Time Attended	8:55 am	Time Finished	9:50 am	Balance				
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch For Collection			
Serviced by: Richard Talavera, Michael V.		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.						
TALAVERA VISTAN		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.						
PERMEO RIVERO		Created by: GRACE PIELAGO CSR		Conformed by: Ch. Ge				
Technician(s)		Customer (Signature over printed name)						

Customer	Uysipuo, Frederick				Date	02-11-2025		
Address	654 Richmond St., Brgy. Greenhills East, MANDALUYONG CITY, Metro Manila				Start Time	08:52 am		
				End Time	08:53 am			
Telephone No.	88725-0026		Mobile No.	0917-8162271		Relayed by	Ms. Donna / KMI	
Contact Person	Chadene/ Fred	Mobile No.	0917-8162271	Tel. No.	02-88725-0026	Warranty Type	C	
Warranty Code			Room Size			Job Class	TS	LVL
Model	KSM-S6MB1IIV			Call Origin	IO	Job Type	FD	
S/N (I)	18011506111418 Faded	S/N (O)		Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R. <input type="checkbox"/>	Ladder? <input type="checkbox"/>
Dealer	10391506-17247	DOP		Notes: Cueves * 2 units for check-up * PAYMENT COLLECTION CIO KMI * KC REFERRAL				
Installer			Complaint	EC Error Code				
Location	Living Room	Before	After					
Mode Setting (Cool)			Cool	No. of Visit	1st Action	Tentative Sched	02/13/2025	
WAC Setting Temp(16°C-RE)/(10/12-ME)			17°C	Findings				
SAC/PAC Setting Temp (17°)			15.6°C	(Reset) EC Error Code				
Discharge Temperature (High)			29.5°C					
Intake Temperature (High)		NA	29.5°C					
Ampere			6.8Amp	Recommendation				
Wattage (Inverter)			—					
Voltage			225V					
SAC/PAC Pressure (PSI)			140PSI					
Part Code	Description				Qty	Unit Price	Amount	
SR No.						Labor	\$450.00	
Repair Done	Reset breaker only / Check up					Handling		
	Test / Unit ok					Others		
Repair Code						Total	\$450.00	
Date Attended	2-12-25	Date Finished	2-12-25	Amount Paid				
Time Attended	8:55 AM	Time Finished	9:50 am	Balance				
This serves as temporary receipt when properly filled up by authorized representative.					Check No.	Bank / Branch	For collection	
Serviced by: Richard Tellevera, Michael V.		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.						
T. RIVERA		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.						
PERALTA		Created by: <u>GRACE PIELAGO</u> Conformed by: <u>✓</u> <u>✓</u>						
Technician(s)		Customer (Signature over printed name)						