



19-Feb-2025

**METAFACOR WELLNESS CENTER**

854 APACIBLE ST. COR. LEROY, BRGY. PACO, MANILA CITY

TEL: 0917-5803174

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of FEBRUARY 2025.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
12-Feb-25	HO-00241785	(1) KLM-SS70-4F3M	GENERAL CLEANING	2,800.00
12-Feb-25	HO-00241786	(1) KLM-SS70-4F3M	GC & PARTS REPLACEMENT	5,800.00
TOTAL				P 8,600.00
LESS: DISCOUNT				(602.00)
TOTAL AMOUNT DUE				P 7,998.00

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

**Note:** If check payment, please prepare check payable to **Kolin Philippines International Inc.**


**Account #: BDO - KALAYAAN 011808000428**

**Note:** In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi\_asst@kolinphil.com.ph**

Prepared by:

  
**Janellen S. Lim**  
KMI - Assistant

Noted by:

  
**Mar Nathaniel R. Flores**  
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:  
Blk 3 Lt 5 Main Drive, FCIE Compound,  
Brgy. Langkaan I, Dasmariñas, Cavite

Tel.: (632) 8749-2118

Fax (046) 402-0793

www.kolinphil.com.ph / kolinphilippines

Operation Office:  
1854 Sta. Rita St., Guadalupe Nueva,  
Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791





No. **HO-00241785**  
Previous SJR No.

Customer	Metafactor Wellness Center			Date	02-12-2025		
Address	854 Apacible St. Cor. Leroy, Brgy. Paco, MANILA CITY, Metro Manila			Start Time	11:55 am		
				End Time	11:57 am		
Telephone No.		Mobile No.	0917-5803174		Relayed by	ADR	
Contact Person		Mobile No.	0917-5803174	Tel. No.		Warranty Type	C
Warranty Code		Room Size		Job Class	GC	LVL	2
Model	KLM-SS70-4F3M		Call Origin	IO	Job Type	FD	
S/N (I)	20311909-10038	S/N (O)	20321909-10034	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input checked="" type="checkbox"/>	O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>
Dealer	KMI	DOP	12/09/2022	Notes LOJERO APPT. FEB 15, 2025 9AM			
Installer	Fernando Lopez	Complaint	For GC				
Location	Clinic	Before	After				
Mode Setting (Cool)	COOL	COOL	No. of Visit	1st Action	Tentative Sched	02/15/2025	
WAC   Setting Temp(16°C-RE)/(10/12-ME)			Findings				
SAC/PAC   Setting Temp (17")	12.3	10.1	Defective PCB (100%), Dirty Unit				
Discharge Temperature (High)	25	23.2					
Intake Temperature (High)	22.2	22.2	Recommendation				
Ampere							
Wattage (Inverter)							
Voltage	230	230					
SAC/PAC   Pressure (PSI)	150	150					
Part Code	Description		Qty	Unit Price	Amount		
	<del>PCB (100%)</del>		1	1,500.00	1,500.00		
LIQUIDATED							
2/17/25							
2/17/25							
SR No.				Labor	2800		
Repair Done	Replaced PCB (100%), General Cleaning			Handling			
Repair Code				Others			
Date Attended	02-15-2025	Date Finished	02-15-2025	Total	2800		
Time Attended	9:00 AM	Time Finished	3:35 PM	Amount Paid			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		
Serviced by: Vidal Lojero, Manuel Raposo				By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
Lojero Anton				I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Bermico Raposo				Created by: LUIS REBUYAS CSR			
Technician(s)				Conformed by: JACK HERNANDO Customer (Signature over printed name) 02-15-25			





## SERVICE JOB REPORT

No. \_\_\_\_\_  
Previous SJR No. \_\_\_\_\_

HO-00241786

[illegible]