



24-Feb-2025

ALCHY ENTERPRISE

3 DIAMOND RD. GEN. LUIS ST., BRGY. 166, KAYBIGA, CALOOCAN CITY
TEL: 8939-8170/0930-5880811/0927-9640728

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of JANUARY & FEBRUARY 2025.
Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
03-Jan-25	HO-00236296	(1) KSM-IW25-9L1M-I	GENERAL CLEANING	/ 1,500.00
03-Jan-25	HO-00236298	(1) KSM-25MB11INV	GENERAL CLEANING	/ 1,500.00
03-Jan-25	HO-00236299	(1) KSG-250B1G	GENERAL CLEANING	/ 1,500.00
03-Jan-25	HO-00236301	(1) KSM-20MB11INV	GENERAL CLEANING	/ 1,500.00
03-Jan-25	HO-00236302	(1) KAG-240RSINV	GENERAL CLEANING	/ 800.00
03-Jan-25	HO-00236307	(1) KSM-IW29AE-5G1M	GENERAL CLEANING	/ 1,500.00
03-Jan-25	HO-00236310	(1) KSM-IW25-6H1M	GENERAL CLEANING	/ 1,500.00
03-Jan-25	HO-00236313	(1) KSM-25MB11INV	GENERAL CLEANING	/ 1,500.00
03-Jan-25	HO-00236314	(1) KSG-250B1G	GENERAL CLEANING	/ 1,500.00
11-Jan-25	HO-00237584	(1) KSG-250B1G	GENERAL CLEANING	/ 1,500.00
16-Jan-25	HO-00237869	(1) KSG-250B1G	PARTS REPLACEMENT	/ 3,300.00
10-Feb-25	HO-00241266	(1) KSM-25MB11INV	PARTS REPLACEMENT	/ 1,750.00
TOTAL				P 19,350.00
LESS: DISCOUNT				/ (1,354.50)
TOTAL AMOUNT DUE:				P 17,995.50

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: BDO - KALAYAAN

011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assistant

Noted by:


Mari Nathaniel R. Flores
KMI - Supervisor


Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:
Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite
Tel.: (632) 8749-2118
Fax (046) 402-0793
www.kolinphil.com.ph / kolinphilippines

Operation Office:
1854 Sta. Rita St., Guadalupe Nuevo,
Makati City
Tel.: (632) 8851-2711, 12 or 15
Fax: (632) 8852-2170
Sales Dept. Fax: (632) 8852-4791





SERVICE JOB REPORT

Green - Service



1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph     kolinphilippines

SERVICE JOB REPORT

No.	HO-00236298
Previous SJR No.	117-00000000


[illegible]



SERVICE JOB REPORT

No.	HO-00236301
Previous S.I.R No.	HO-00226070

[illegible]



SERVICE JOB REPORT

No.	HO-00236302
Previous SJR No.	HO-00228075

SVC-SJR-02-020123

White - Customer

Blue - Accounting


Green - Service

SERVICE JOB REPORT

No.
Previous SJR No.

HO-00236307
HO-00236075

[illegible]



SERVICE JOB REPORT

Kolin Philippines Int'l., Inc.						Service Order	
1854 Sta. Rita St., Guadalupe Nuevo, Makati City Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph Website: www.kolinphil.com.ph kolinphilippines						No. Previous SJR No.	HO-00236310 HC-00226075
Customer: Alchy Enterprise / Fina Chua Address: 3 Diamond Rd, Gen. Luis St., Brgy. 165, Kayala, CALOOCAN CITY, Metro Manila						Date	01-03-2025
						Start Time	12:04 pm
						End Time	12:05 pm
Telephone No. 392-4688		Mobile No. 0927-8640728 / 0930-588081		Relayed by	Shara - +63930588081		
Contact Person Shara	Mobile No.		Tel. No. 8939-8170	Warranty Type	C		
Warranty Code 1SM-11425-1111M			Room Size	Job Class GC	LVL	1	
Model KSM-20MBTINV			Call Origin MH	Job Type FD			
S/N (I) 18291910-13462 10851512-17965	S/N (O) 10901512-18028	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>	
Dealer	DOP 15302011-13110 11/28/2019	Notes IH Cuevas-appl.					
Installer	Complaint 10/11/2021 For GC						
Location 11085 Office of the President	Before	After					
Mode Setting (Cool)	Cool	Cool	No. of Visit 1st Action	Tentative Sched	01/11/2025		
WAC Setting Temp(16°C-RE)/(10/12-ME)	Findings						
SAC/PAC Setting Temp (17°)	17°C	17°C	DIRTY UNIT				
Discharge Temperature (High)		17°C					
Intake Temperature (High)		25°C					
Ampere 12A	12	Recommendation					
Wattage (Inverter)		REPLACE FILTER REGULARLY					
Voltage 235	235						
SAC/PAC Pressure (PSI) 115	120						
Part Code	Description	Qty	Unit Price	Amount			
PAYMENT FOR COLLECTION 70 KM							
11/11/25							
SR No.					Labor	1500 -	
Repair Done	GENERATOR DECLINING ONLY				Handling		
					Others		
Repair Code					Total	1500 -	
Date Attended 1-11-25	Date Finished 1-11-25		Amount Paid				
Time Attended 11:10	Time Finished 3:00		Balance		1500 -		
This serves as temporary receipt when properly filled up by authorized representative.			Check No.	Bank / Branch			
Serviced by: Joselito Branos, Boyet Cus... Technician(s)		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations. I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition. Created by: Shery Ann CSR Conformed by: Customer (Signature over printed name)					

Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

SERVICE JOB REPORT

Customer		Alchy Enterprise / Fina Chua		No.		HO-00236313	
Address		3 Diamond Rd. Gen. Luis St., Brgy. 166, Kalyuga, CALOOCAN CITY, Metro Manila		Previous SJR No.		HO-00225075	
Telephone No.		398-4688		Mobile No.		0927-9640728 / 0930-588081	
Contact Person		Share		Tel. No.		8939-8170	
Warranty Code		KSM-25M1511N1		Room Size		Job Class	
Model		KSM-1410AE-501M		Call Origin		MH	
S/N (I)		10221707-1023		S/N (O)		10211407-14082	
Dealer		DOP		Permit?		Parking?	
Installer		Complaint		Notes		IH Cuevas - sppt	
Location		Before		After		Tentative Sched	
Mode Setting (Cool)		Cool		No. of Visit		1st Action	
WAC Setting Temp (16°C-RE)/(10/12-ME)		17°C		Findings		DIRTY UNIT	
SAC/PAC Setting Temp (17°)		17°C		Recommendation		CLEAN AIR FILTER REGULARLY	
Discharge Temperature (High)		H.C.		Voltage		235 235	
Intake Temperature (High)		28.0		SAC/PAC Pressure (PSI)		115 115	
Ampere		10 A 11 A		Part Code		Description	
Wattage (Inverter)				Qty		Unit Price	
Voltage				Amount			
SAC/PAC Pressure (PSI)				PAYMENT FOR COLLECTION C/O KAM			
SR No.		Labor		1500-			
Repair Done		Handling		Others			
Repair Code		Total		1500-			
Date Attended		Date Finished		Amount Paid			
Time Attended		Time Finished		Balance		1500-	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by: Jocelito Bragos, Royal Cuevas		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
I hereby agree to the above repair charges incurred to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
Created by:		Conformed by:					
Technician(s)		Customer					
Sherry Anne B. Gorn...		(Signature over printed name)					



SERVICE JOB REPORT

Previous SJR No.	HC-90226070
------------------	-------------

[illegible]



SERVICE JOB REPORT

No.	HO-00237504
Previous S.I.R. No.	HO-00228584

[illegible]

Customer		Alchy Enterprise / Pina Chua		No.		HO-00237869	
Address		3 Diamond Rd. Gen. Luis St., Brgy. 166, Kaybigan, CALOOCAN CITY, Metro Manila		Previous SJR No.		HO-00226564	
Telephone No.		395-4688		Mobile No.		0927-9640728 / 0930-58808	
Contact Person		Shara		Tel. No.		8939-8170	
Warranty Code				Room Size			
Model		KSG-250B1G		Call Origin		IO	
S/N (I)		16071507-12189		S/N (O)		16081405-10790	
Dealer		KMI		DOP			
Installer				Complaint		Not Cooling	
Location		Billing Dept. 2nd Floor		Before		After	
Mode Setting (Cool)				No. of Visit		3rd Action	
WAC Setting Temp (16°C-RE)/(10/12-ME)				Tentative Sched		01/16/2025	
SAC/PAC Setting Temp (17°)				Findings			
Discharge Temperature (High)				defective Com Unit Wire and Comp Capacitor			
Intake Temperature (High)				Recommendation			
Ampere							
Wattage (Inverter)							
Voltage							
SAC/PAC Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
		Compressor Lead Wire		1		650	
		Compressor Capacitor		1		550	
SR No.		101625		Labor		2,100	
Repair Done		Replaced Comp. Lead Wire		Handling			
Repair Code		Comp. Capacitor. off unit		Others			
Date Attended		1-16-25		Total		3,300	
Time Attended		10:00		Amount Paid			
Date Finished		1-16-25		Balance		3,300	
Time Finished		12:00		Bank / Branch			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.			
Served by: Carry Munday, Neil Villafuerte				By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
				I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Created by: RECHILLA				Conformed by: SHARA			
Technician(s)				Customer (Signature over printed name)			



Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

Facebook: kolinphilippines

SERVICE JOB REPORT

No.

HO-00241266

Previous SJR No.

HO-00231460

Customer	Alchy Enterprises / Fina Chua			Date	02-07-2025		
Address	3 Diamond Rd. Gen. Luis St., Brgy. 166, Kaybaga, CALOOGAN CITY, Metro Manila			Start Time	10:48 am		
				End Time	10:48 am		
Telephone No.	398-4888	Mobile No.	0927-8640728 / 0930-58808	Relayed by	(Ms. Janellen / KMI)		
Contact Person	Share	Mobile No.		Tel. No.	5939-8170	Warranty Type	C
Warranty Code				Room Size			
Model	KSM-25MB1INV			Call Origin	IO	Job Class	TS LVL 1
S/N (I)	10911409-14032	S/N (O)	10921409-14294	Permit?	<input type="checkbox"/>	Parking?	<input type="checkbox"/>
Dealer		DOP	05/12/2015	Appointment?	<input type="checkbox"/>	O.R.?	<input type="checkbox"/>
Installer		Complaint	Malfunctioning	Notes	Talavera "Yung unit daw po doon, cover of vent is not moving daw po. balikbalikan daw po." as per customer. Pls. verify & update unit model.		
Location	OFC 1	Before	After				
Mode Setting (Cool)				No. of Visit	1st Action	Tentative Sched	02/10/2025
WAC Setting Temp(16°C-RE)/(10/12-ME)				Findings			
SAC/PAC Setting Temp (17°)				DEFECTIVE SWING MOTOR			
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere				Recommendation			
Wattage (Inverter)							
Voltage				CLEAN AIR FILTER (REGULAR)			
SAC/PAC Pressure (PSI)							
Part Code	Description			Qty	Unit Price	Amount	
	SWING MOTOR			1	/	500-	
NOTE: PAYMENT FOR COLLECTION							
C/O KMI							
LIQUIDATE							
2/11/25							
SR No.	REPLACED SWING MOTO			Labor	1,250-		
Repair Done				Handling			
Repair Code				Others			
Date Attended	2-10-25	Date Finished	2-10-25	Total	1,750-		
Time Attended	3:26	Time Finished	3:50	Amount Paid			
				Balance	1,750-		
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		
Served by:	Garry Munday, Neil Villanueva, Salomon			By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
KINO REX				I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
MUNDAY				Created by:	Conformed by:		
Technician(s)	GRACE PIELAGO CSR			Customer (Signature over printed name)			