



14-Jan-2025

UNITEC RESOURCES INC.

ATTN: MR. JOSEPH DOMINGO

1199 MENDIOLA EXTENSION, BRGY. 532 PACO, MANILA CITY

TEL: 0917-8251434

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of DECEMBER 2024.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
16-Dec-24	HO-00235062	(1) KFM-400GF1INV	GENERAL CLEANING	2,000.00
16-Dec-24	HO-00235070	(1) KFS-10BMINV	GENERAL CLEANING	1,500.00
16-Dec-24	HO-00235073	(1) KFM-400GF1INV	GENERAL CLEANING	2,000.00
16-Dec-24	HO-00235075	(1) KFM-400GF1INV	GENERAL CLEANING	2,000.00
16-Dec-24	HO-00235077	(1) KFM-400GF1INV	GENERAL CLEANING	2,000.00
16-Dec-24	HO-00235079	(1) KSM-30MB1INV	GENERAL CLEANING	1,500.00
16-Dec-24	HO-00235081	(1) KFS-15BMINV	GENERAL CLEANING	1,500.00
16-Dec-24	HO-00235084	(1) KFS-10BMINV	GENERAL CLEANING	1,000.00
16-Dec-24	HO-00235088	(1) KSM-25MB1INV	CHECK UP	450.00
02-Jan-25	HO-00236164	(1) KSM-30MB1INV	GENERAL CLEANING	1,500.00
TOTAL				P 15,450.00
LESS: DISCOUNT				(1,545.00)
TOTAL AMOUNT DUE				P 13,905.00

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: BDO - KALAYAAN


011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assistant

Noted by:


Mari Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name


 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite

Tel: (632) 8749-2118

Fax (046) 402-0793

 www.kolinphil.com.ph / kolinphilippines

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,
Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791





1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph     [kolinphilippines](https://www.facebook.com/kolinphilippines)

No.	HD-00235062
Previous SJR No.	

[illegible]

Customer		Unifec Resources Inc.		Date		12-16-2024	
Address		1199 Mendiola Extension, Brgy. 832 Paco, MANILA CITY, Metro Manila		Start Time		10:28 am	
Telephone No.		8562-7132-34		Mobile No.		0958-5231445 / 0917-6251445	
Contact Person		Joseph Domingo		Tel. No.		0932580032580	
Warranty Code		KSM-36MB11NV KFS-10BMINV		Room Size		Job Class	
Model		KSM-36MB11NV KFS-10BMINV		Call Origin		TF	
S/N (I)		48914512-47309		S/N (O)		10921512-17868	
Dealer		15121702-11692		DOP		Notes	
Installer		TRAINING Room 1		Complaint		For GC	
Location		ATP CONFERENCE		Before		After	
Mode Setting (Cool)		Cool		No. of Visit		1st Action	
WAC Setting Temp (16°C-RE)/(10/12-ME)		17°C		Findings		12/17/2024	
SAC/PAC Setting Temp (17°)		17°C		Dirty Unit			
Discharge Temperature (High)		16°C					
Intake Temperature (High)		27.9°C					
Ampere		3.6A		Recommendation			
Wattage (Inverter)		—					
Voltage		225V					
SAC/PAC Pressure (PSI)		135PSI					
Part Code		Description		Qty		Unit Price	
SR No.				Labor		1,500.00	
Repair Done		General cleaning / Re-test / Unit ok		Handling			
Repair Code				Others			
Date Attended		1-2-25		Date Finished		1-2-25	
Time Attended		9:25 am		Time Finished		1:00 pm	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by: Garry Muriel, Neil Villaverde, Salomon		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
TALAVEWA VISTAN		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
TECHNICIAN(S)		Created by: ERICA C. CALIBOT CSR		Conformed by: JOSEPH DOMINGO		Customer (Signature over printed name)	



SERVICE JOB REPORT

No.	HC-00235073
Previous SJR No.	

[illegible]







1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph [kolinphilippines](http://kolinphilippines.com)

SERVICE JOB REPORT

No.
Previous SJR No.

HO-00235075

Customer		Unitec Resources Inc.						Date	12-16-2024			
Address		1199 Mendiola Extension,, Brgy. 832 Paco, MANILA CITY, Metro Manila						Start Time	10:37 am			
								End Time	10:38 am			
Telephone No.	8582-7132-34				Mobile No.	0956-5231445 / 0917-8251445				Relayed by	083282 Alexsine E. Vidal / Te...	
Contact Person	Joseph Domingo		Mobile No.	0956-5231445		Tel. No.			Warranty Type	C		
Warranty Code						Room Size			Job Class	GC	LVL	1
Model	KFM-400GF1INV					Call Origin	TF		Job Type	FD		
S/N (I)	10041604-14745			S/N (O)	10951602-14745			Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>
Dealer	10941512-13615			DOP	10951512-14527			Notes IH-Villafuerte - appl - Concern/Request: Cleaning "if under warranty". Need of ladder: YES Working permit: NO With parking: YES				
Installer				Complaint	For GC							
Location	TRAINING ROOM 2		Before	After								
Mode Setting (Cool)	ECO RLM		COOL	COOL		No. of Visit	1st Action		Tentative Sched	01/08/2025		
WAC Setting Temp(16°C-RE)/(10/12-ME)						Findings						
SAC/PAC Setting Temp (17°)			17°	17°		DIRTY UNIT						
Discharge Temperature (High)			14°	13°								
Intake Temperature (High)			27°	26°								
Ampere			18A	19A		Recommendation						
Wattage (Inverter)						CLEAN AIR FILTER /REGULAR						
Voltage			230V	230V								
SAC/PAC Pressure (PSI)			130PSI	125PSI								
Part Code	Description					Qty	Unit Price		Amount			
NOTE: PAYMENT FOR COLLECTION												
c/o KMI												
												
												
SR No.								Labor	2,000			
Repair Done	GENERAL CLEANING							Handling				
								Others				
Repair Code								Total	2,000			
Date Attended	1-2-25		Date Finished	1-2-25		Amount Paid						
Time Attended	8:30		Time Finished	1:20		Balance	2,000					
This serves as temporary receipt when properly filled up by authorized representative.						Check No.			Bank / Branch			
Serviced by: Garry Munday, Neil Villafuerte Calibot			By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations. I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.									
Boyer REX PT			Created by: ERICA C. CALIBOT CSR			Conformed by:  Customer (Signature over printed name) 11/125						



SERVICE JOB REPORT

HO-00235077

[illegible]



1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph     kolinphilippines

SERVICE JOB REPORT

HO-00235079

[illegible]

Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

SERVICE JOB REPORT

Customer		Unitec Resources Inc.		Date		12-16-2024	
Address		1199 Mendiola Extension, Brgy. 832 Paco, MANILA CITY, Metro Manila		Start Time		10:42 am	
				End Time		10:48 am	
Telephone No.		8562-7132-34		Mobile No.		0956-5231445 / 0917-6251445	
Contact Person		Joseph Domingo		Mobile No.		0956-5231445	
Warranty Code		KES15PM1		Room Size			
Model		KSM-T5MB11NV		Call Origin		TF	
S/N (I)		10571512-25093		S/N (O)		10081512-25393	
Dealer		15131603-10770		DOP			
Installer				Complaint		For GC	
Location		PATROL DEPT.		Before		After	
Mode Setting (Cool)		COOL		No. of Visit		1st Action	
WAC Setting Temp(16°C-RE)/(10/12-ME)				Tentative Sched		01/06/2025	
SAC/PAC Setting Temp (17°)		17°C		Findings			
Discharge Temperature (High)		13°C		DIRTY UNIT			
Intake Temperature (High)		27°C					
Ampere				Recommendation			
Wattage (Inverter)				CLEAN AIR FILTER REGULARLY			
Voltage							
SAC/PAC Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
REF STN # 235074							
NOTE: PAYMENT FOR COLLECTION							
Q/O LCM							
SR No.				Labor		1,500	
Repair Done		GENERAL CLEANING		Handling			
Repair Code				Others			
Date Attended		1-2-25		Total		1,500	
Time Attended		8:30		Amount Paid			
				Balance		1,500	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by: Garry Munday, Neil Villafuerte		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
BOYET, REX		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
PJ		Created by:		Conformed by:		1/2/25	
Technician(s)		ERICA C. CALIBOT CSR		Customer (Signature over printed name)			

K Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

SERVICE JOB REPORT

No. HO-00235088
Previous SJR No.

Customer	Unitec Resources Inc.			Date	12-16-2024		
Address	1199 Mendiola Extension, Brgy. 832 Paco, MANILA CITY, Metro Manila			Start Time	10:50 am		
				End Time	10:51 am		
Telephone No.	8562-7132-34	Mobile No.	0956-5231445 / 0917-625143				
Contact Person	Joseph Domingo	Mobile No.	0956-5231445	Tel. No.			
Warranty Code				Room Size			
Model	KSM-25MB1INV			Call Origin	TF		
S/N (I)	10911512-17909	S/N (O)	10911512-17909	Permit?	<input type="checkbox"/>	Parking?	<input type="checkbox"/>
Dealer	10911512-17909			DOP	10911512-17909		
Installer	CONFERENCE # 4			Complaint	For GC		
Location	Before After			Appointment?	<input type="checkbox"/>	O.R.?	<input type="checkbox"/>
Mode Setting (Cool)	COOL COOL			No. of Visit	1st Action		
WAC Setting Temp (16°C-RE)/(10/12-ME)				Findings			
SAC/PAC Setting Temp (17°)	73 17.8			DIRTY AIR FILTER			
Discharge Temperature (High)	46 130						
Intake Temperature (High)	29 260						
Ampere	1.5A 12A			Recommendation			
Wattage (Inverter)							
Voltage	230V 230V						
SAC/PAC Pressure (PSI)	100 175						
Part Code	Description			Qty	Unit Price	Amount	
REF. SJR # 235-081							
KSM-30MB1INV							
SN: 18011603-12709			Ref SJR 236164				
GENERAL CLEANING			1,500				
ACCOUNTING OFFICE DPT.)			1,500				
SR No.				Labor	450		
Repair Done	GENERAL CLEANING			Handling			
Repair Code	CHECK-UP AND GET PARAMETERS			Others			
Date Attended	1-12-25	Date Finished	1-12-25	Total	450		
Time Attended	8:30	Time Finished	1:20	Amount Paid			
This serves as temporary receipt when properly filled up by authorized representative.			Check No.	Bank / Branch			
Balanced by: Garry Munday, Neil Villaverde			By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.				
DOYET LEX			I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.				
PJ			Created by:		Conformed by:		
Technician(s)			ERICA C. CALBOT		Customer		
			CSR		(Signature over printed name)		

Customer		Unitec Resources Inc.		No.		HO-00236164	
Address		, 1199 Mendiola Extension, , Brgy. 832 Paco, MANILA CITY, Metro Manila		Previous SJR No.		HO-00235064	
Telephone No.		8582-7132-34		Mobile No.		0956-5231445 / 0917-8251434 / 0917-7063266	
Contact Person		Joseph Domingo		Mobile No.		0956-5231445	
Warranty Code				Tel. No.			
Model		KSM-30MB1INV		Room Size			
S/N (I)		(i)18011603-12709 (accounting)		Call Origin		IO	
Dealer		DOP		Job Class		GC LVL 1	
Installer		Complaint		Job Type		FD	
Location		ACCOUNTING DEPT.		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input checked="" type="checkbox"/> O.R. <input type="checkbox"/> Ladder? <input type="checkbox"/>			
Mode Setting (Cool)		COOLCOOL		Notes		IH-Villafuerte ADDITIONAL SJR FOR CLEANING - appt - Concern/Request: Cleaning "if under warranty: Need of ladder: YES Working permit: NO With parking: YES	
WAC Setting Temp(16°C-RE)/(10/12-ME)				Tentative Sched		01/02/2025	
SAC/PAC Setting Temp (17°)				Findings		DIRTY UNIT	
Discharge Temperature (High)				Recommendation		CLEAN AIR FILTER REGULATE	
Intake Temperature (High)							
Ampere							
Wattage (Inverter)							
Voltage							
SAC/PAC Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
REF. SJR # 1235088							
NOTE: PAYMENT FOR COLLECTION							
C/O KMI							
SR No.		GENERAL CLEANING		Labor		1,500	
Repair Done				Handling			
Repair Code				Others			
Date Attended		1-2-25		Total		1,500	
Time Attended		8:30		Amount Paid			
				Balance		1,500	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by: JOSEPH DOMINGO, Boyet Cuevas, REX		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
Technician(s)		RECHILLA CSR		Conformed by: Customer (Signature over printed name)			