



14-Jan-2025

ATTN: MS. FINA CHUA

UNIT 2 & 4, 14 LANTANA ST., BRGY. NEW MANILA, QUEZON CITY

TEL: 0917-5252177

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of JANUARY 2025.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
03-Jan-25	HO-00236295	(1) KLG-IF70-2C1M	GENERAL CLEANING	2,000.00
03-Jan-25	HO-00236297	(1) KSM-IW15-6H1M	GENERAL CLEANING	1,500.00
03-Jan-25	HO-00236304	(1) KSM-IW30WAE-7J1M	GENERAL CLEANING	1,500.00
TOTAL				P 5,000.00
LESS: DISCOUNT				(350.00)
TOTAL AMOUNT DUE				P 4,650.00

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: BDO - KALAYAAN

011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assistant

Noted by:


Mari N. Flores
KMI - Supervisor

Received by:

Signature over printed name




 Kolin Philippines Int'l., Inc.

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite

Tel: (632) 8749-2118

Fax (046) 402-0793

 www.kolinphil.com.ph / kolinphilippines

Operation Office:


1854 Sta. Rita St, Guadalupe Nuevo,
Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791

Customer				Date			
Address				Start Time			
Telephone No.				Relayed by			
Contact Person				Warranty Type			
Warranty Code				Job Class			
Model				Job Type			
S/N (I)		S/N (O)		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/>		Appointment? <input type="checkbox"/>	
Dealer		DOP		Notes			
Installer		Complaint					
Location		Before		After			
Mode Setting (Cool)		No. of Visit		Tentative Sched			
WAC Setting Temp (16°C-RE)/(10/12-ME)				Findings			
SAC/PAC Setting Temp (17°)		Discharge Temperature (High)					
Intake Temperature (High)		Ampere		Recommendation			
Wattage (Inverter)		Voltage					
SAC/PAC Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
Amount							
SR No.		Labor					
Repair Done		Handling					
Repair Code		Others					
Date Attended		Date Finished		Total			
Time Attended		Time Finished		Amount Paid			
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
Created by:		Conformed by:					
Technician(s)		Customer (Signature over printed name)					



SERVICE JOB REPORT

HQ-00236297

10-00235659

[illegible]



1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph [kolinphilippines](https://www.facebook.com/kolinphilippines)

SERVICE JOB REPORT

No.
Previous SJR No.

HO-00236304

147-0023568

Website: www.kolinphil.com.ph						KOLIN PHILIPPINES										
Customer		Chua, Fina								Date	01-03-2025					
Address		Unit 2 & 4, 14 Lantana St., Brgy. New Manila, QUEZON CITY.								Start Time	11:40 am					
										End Time	11:51 am					
Telephone No.						Mobile No.		0917-5252177		Relayed by	Engr. Kenneth					
Contact Person		Fina	Mobile No.		0917-5252177		Tel. No.			Warranty Type	C					
Warranty Code							Room Size			Job Class	GC	LVL	I			
Model		RSM-IW30WAE-7JIM					Call Origin	IG		Job Type	FD					
S/N (I)		1B142007-12429		S/N (O)	1B422011-12653		Permit?	<input type="checkbox"/>	Parking?	<input type="checkbox"/>	Appointment?	<input type="checkbox"/>	O.R.?	<input type="checkbox"/>	Ladder?	<input type="checkbox"/>
Dealer		KMI	DOP		11/15/2021		Notes Lotero * 3 SAC for GC.									
Installer		Fernando Lopez		Complaint		For GC										
Location		Alexis Room	Before	After												
Mode Setting (Cool)		Cool	Cool	No. of Visit	1st Action		Tentative Sched		01/07/2025							
WAC Setting Temp(16°C-RE)/(10/12-ME)		Findings														
SAC/PAC Setting Temp (17°)		120	170	Dirty Unit												
Discharge Temperature (High)		15.9	14.9													
Intake Temperature (High)		29.8	26.8													
Ampere		9.24	9.54	Recommendation												
Wattage (Inverter)																
Voltage		237V	233V													
SAC/PAC Pressure (PSI)		125 PSI	115 PSI													
Part Code		Description								Qty	Unit Price		Amount			
SR No.										Labor	1,500.00					
Repair Done		General Cleaning								Handling						
										Others						
Repair Code										Total	1,500.00					
Date Attended		1-F-2025		Date Finished		1-F-2025		Amount Paid		Car Collectio						
Time Attended		9:00 am		Time Finished		12:50 pm		Balance								
This serves as temporary receipt when properly filled up by authorized representative.						Check No.				Bank / Branch						
Serviced by:		Vidal Lorenz, Manuel Rapsing		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.												
		Vidal Lorenz		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.												
		Manuel Rapsing		Created by: GRACE PIELAGO CSR				Conformed by: Customer (Signature over printed name)								