



17-Jan-2025

SPRING PALACE RESTAURANT INC.

ATTN: MS. CECILLE LEI

1947 H. PASEO DE CARMONA, FORMERLY: LEI YUAN GRILL & SEAFOOD RESTAURANT

BRGY. MADUYA, CARMONA CAVITE

TEL: 0966-5262080/0917-5248989

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of AUGUST 2024.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
08-Aug-24	HO-00216336	(1) KSM-25MB1INV	INSTALLATION	15,945.00
TOTAL				P 15,945.00
LESS: DISCOUNT				(2,445.00)
TOTAL AMOUNT DUE				P 13,500.00

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: BDO - KALAYAAN


011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assistant

Noted by:


Mar Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,

Brgy. Langkaan I, Dasmariñas, Cavite

Tel.: (632) 8749-2118

Fax (046) 402-0793

 www.kolinphil.com.ph / kolinphilippines

Operation Office:

1854 Sta. Rita St, Guadalupe Nuevo,

Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791



Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphl.com.ph
Website: www.kolinphl.com.ph

SERVICE JOB REPORT

No. HO-00216336
Previous SJR No. HO-00213453

Customer	Spring Palace Restaurant Inc.			Date	08-02-2024		
Address	1247 H. Pared De Carmona, Fonnerty: Lei Yuan Grill & Seafood Restaurant, Brgy. Kuya, CARMONA, Cavite.			Start Time	02:42 pm		
Telephone No.		Mobile No.	0906-5262080 / 0906-5261762	Relayed by	Joaffray Dadios		
Contact Person	Ms. Cecille	Mobile No.	0917-5248989	Tel. No.	0917-5248989	Warranty Type	C
Warranty Code		Room Size		Job Class	SCF	LVL	1
Model	KSM-25MB11RV			Call Origin	IO	Job Type	FD
S/N (I)	II) 10911311-12117	S/N (O)	IO) 10921311-122	Permit?	☐	Parking?	☐
Dealer		DOP		Appointment?	☐	O.R?	☐
Installer	Left 2 Pcs			Complaint	Others		
Location	VIP Room	Before	After	Notes VILLAFUERTE NEED 4 SETS SACKFOLDINGS			
Mode Setting (Cool)		No. of Visit	1st Action	Tentative Sched	08/06/2024		
WAC Setting Temp (16°C-RE) (10/12-ME)		Findings					
SAC/PAC Setting Temp (17°)		FOR INSTALL					
Discharge Temperature (High)		FOR INSTALL					
Intake Temperature (High)		FOR INSTALL					
Ampere		Recommendation					
Wattage (Inverter)		FOR INSTALLATION					
Voltage		NEED FLARE NUT					
SAC/PAC Pressure (PSI)		1/8 2PCS 3/8 2PCS					
Part Code	Description	Qty	Unit Price	Amount			
	CUTTER 3/8-9/8	1PM	400	5,600			
	R-1000 4x7mm	20PM	100	2,000			
	R-1000 3x5mm	7FT	60	420			
	COMP (D)	10					
	COMP (C)	10					
	PVC PIPE 3/4	2PCS	150	300			
	DRAIN HOSE	7FT	25	175			
	STAR	2PCS					
	PVC ELBOW	4PCS					
	C-BRAKET 30A	1PC	1,000	1,000			
	BRAKET (W2)			1,650			
	INTOUCH 200T						
SR No.	MOUNTING OF INDOOR AND OUTDOOR UNIT			Labor	800		
Repair Done	FIP FITTINGS / INDOOR AND OUTDOOR			Handling	4,000		
Repair Code	F			Others			
Date Attended	8-6-24	Date Finished	8-6-24	Total	15,945		
Time Attended	11:50 pm	Time Finished		Amount Paid	FOR collection		
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		
Serviced by: Gerry Munday, Neil Villafuerte				By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
Technician(s): JUAN MIGUEL VILLAFUERTE				I hereby agree to the above repair charges incurred to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Created by: LUIS REYES				Conformed by: [Signature]			
Technician(s)				Customer (Signature over printed name)			