



27-Jan-2025

**MONACO PLANT 1**

NY COMPOUND, LUGMOK ROAD, BRGY. BAGBAGUIN, CALOOCAN CITY

TEL: 8365-4562 loc 210

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of NOVEMBER & DECEMBER 2024. Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR#	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
28-Nov-24	HO-00232678	(1) KFG-70F1	General Cleaning	2,000.00
04-Dec-24	HO-00233506	(1) KLG-SF70-4D3M	General Cleaning	3,350.00
04-Dec-24	HO-00233522	(1) KFG-70F1	General Cleaning	6,950.00
<b>TOTAL</b>				<b>P 12,300.00</b>
<b>LESS: DISCOUNT</b>				<b>(1,230.00)</b>
<b>TOTAL AMOUNT DUE</b>				<b>P 11,070.00</b>

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

**Note:** If check payment, please prepare check payable to **Kolin Philippines International Inc.**

**Account #: BDO - KALAYAAN 011808000428**

**Note:** In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi\_asst@kolinphil.com.ph**

Prepared by:

  
**Janellen S. Lim**  
KMI - Assistant

Noted by:

  
**Mari Nathaniel R. Flores**  
KMI - Supervisor

Received by:

Signature over printed name

**K Kolin Philippines Int'l., Inc.**

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,  
Brgy. Langkaan I, Dasmariñas, Cavite

Tel.: (632) 8749-2118

Fax (046) 402-0793

www.kolinphil.com.ph / kolinphilippines

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,  
Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791







1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
Tel. No.: 8852-6668 / Mobile: 0917-811-8982 / Email: [service@kolinphil.com.ph](mailto:service@kolinphil.com.ph)  
Website: [www.kolinphil.com.ph](http://www.kolinphil.com.ph)     [kolinphilippines](https://www.youtube.com/kolinphilippines)

(2)

No.	HO-00232678
Previous SJR No.	HO-00232678

[illegible]





# Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph  
Website: www.kolinphil.com.ph

## SERVICE JOB REPORT

No. HO-00233522  
Previous SJR No. HO-0727401

Date 12-04-2024

Start Time 09:54 pm

End Time 09:58 pm

Relayed by neil villafuerte

Warranty Type C

Job Class TS LVL 1

Job Type FD

Permit? ☐ Parking? ☐ Appointment? ☐ O.R.? ☐ Ladder? ☐

Notes LOJERO Upper outdoor fan motor is not working ...

Bring outdoor fan motor, fan capacitor and compressor cap and display board. / Note: As per customer auto on / off / Upon checking upper outdoor fan motor is not working / For collection c/o KJAI

Location Laboratory 2 Before After

Mode Setting (Cool) 17°C No. of Visit 1st Action Tentative Sched 12/09/2024

WAC | Setting Temp(16°C-RE)/(10/12-ME) Findings

SAC/PAC | Setting Temp (17°) 17°C FAN motor (0)

Discharge Temperature (High) 19°C 16°C FAN CAP (0)

Intake Temperature (High) 27°C 29°C

Ampere 16.15 / 16.15 / 16 Recommendation

Wattage (Inverter) For REPLACEMENT OF

Voltage 233 FAN CAP AND FAN MOTOR

SAC/PAC | Pressure (PSI) 05 0.5 OUTDOOR

Part Code Description Qty Unit Price Amount

(4mm) FAN MOTOR 1PC 3,450 3,450

(4mm) FA CAPACITOR 1PC 300 300

Rep STK # 232652 W 6255

10% discount

12/9

LIQUIDATED

12/11/24

3:57 pm

3,200

1

6,950

FOR collection

6,950

3,200

1

6,950

FOR collection

6,950

3,200

1

6,950

FOR collection

6,950


3,200

1

6,950

FOR collection





## SERVICE JOB REPORT

[illegible]