



27-Jan-2025

QC HOLIDAY SPA

150-D TUAZON ST., BRGY. LOURDES, QUEZON CITY

TEL: 0921-9169405

Sir/ Madam,

This is to inform you of your unsettled bill for the service job done to your unit for the month of JULY 2023. Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
27-Jul-23	HO-00164460	(1) KLG-SF40-3D1M	INSTALLATION	19,425.00
	TOTAL		P	19,425.00
	LESS: DISCOUNT			(1,942.50)
	TOTAL AMOUNT DUE		P	17,482.50

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**


Account #: BDO - KALAYAAN 011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assistant

Noted by:


Mari Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,

Brgy. Langkaan I, Dasmariñas, Cavite

Tel.: (632) 8749-2118

Fax (046) 402-0793

 www.kolinphil.com.ph / [kolinphilippines](https://www.facebook.com/kolinphilippines)

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,

Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791



Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

SERVICE JOB REPORT

Customer		QC Holiday Spa		Date		07-25-2023	
Address		150-D Tuzon St., Brgy. Lourdes, QUEZON CITY, Metro Manila		Start Time		04:47 pm	
Telephone No.		Mobile No. 0921-9189405		Relayed by		ANASTACIO TUQUIB / NDR	
Contact Person	Anastacio Tuguib	Mobile No.	917-7998076	Tel. No.		Warranty Type	C
Warranty Code		Room Size		Job Class	INST	LVL	4
Model	KLG-SF40-3D1M	Call Origin	MF	Job Type	FD		
S/N (I)	20211804-14851	S/N (O)	20221806-14852	Permit?	☐	Parking?	☐
Dealer		DOP		Appointment?	☐	O.R.?	☐
Installer		Complaint	For Installation	Notes	LOPEZ		
Location		Before	After	No. of Visit	1st Action	Tentative Sched	07/27/2023
Mode Setting (Cool)				Findings			
WAC Setting Temp(16°C-RE)/(10/12-ME)				Note: Shortcut Royal Cord (28m)			
SAC/PAC Setting Temp (17°)				Lay Copper Tube na Hindi karabang			
Discharge Temperature (High)				ang wire			
Intake Temperature (High)				Recommendation			
Ampere							
Wattage (Inverter)							
Voltage							
SAC/PAC Pressure (PSI)							
Part Code	Description	Qty	Unit Price	Amount			
	Copper Tube 5/8" x 1/4"	28	400	11,200			
	Rubber insulation 2 1/8" x 9/16"	16	350	2,100			
	Drain Hose White	5	25	125			
	Mapp Gas	1					
	Freon 410A	1					
	s-tape	3					
	camp (D)	5					
				Total			
				19,425.00			
				10% discount			
				17,482.50			
SR No.	30371	7/28/2023		Labor	6,000		
Repair Done	Install indoor + outdoor unit			Handling			
Repair Code	Start-up unit run normally operation			Others			
Date Attended	July 27, 2023	Date Finished	July 27, 2023	Total	19,425.00		
Time Attended	9:16 am	Time Finished	1:10 pm	Amount Paid			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		
Serviced by:				By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
Kevin				I hereby agree to the above repair charges incurred to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			