



6-Jan-2025

LUCENDI SHOP

ATTN: MARLO/JOEL

CW HOME DEPOT, JULIA VARGAS AVE., BRGY. SAN ANTONIO, PASIG CITY

TEL: 0917-8855863 / 8655-0715

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of DECEMBER 2024.
Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
04-Dec-24	HO-00233443	(1) KSM-SW25-5G1M	CHECK UP / CLOGGED DRAIN	450.00
TOTAL AMOUNT DUE				P. 450.00

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: BDO - KALAYAAN 011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assistant

Noted by:


Mari Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l, Inc.**

Plant and Head Office:
Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite
Tel.: (632) 8749-2118
Fax (046) 402-0793
www.kolinphil.com.ph / kolinphilippines

Operation Office:
1854 Sta. Rita St., Guadalupe Nuevo,
Makati City
Tel.: (632) 8851-2711, 12 or 15
Fax: (632) 8852-2170
Sales Dept. Fax: (632) 8852-4791





SERVICE JOB REPORT

HO-00233443

[illegible]