



6-Jan-2025

**MONACO PLANT 1**

NY COMPOUND, LUGMOK ROAD, BRGY. BAGBAGUIN, CALOOCAN CITY

TEL: 8365-4562 loc 210

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of NOVEMBER & DECEMBER 2024. Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR#	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
28-Nov-24	HO-00232678	(1) KFG-70F1	General Cleaning	/ 2,000.00
28-Nov-24	HO-00232680	(1) KLG-SF70-4D3M	General Cleaning	/ 600.00
28-Nov-24	HO-00232682	(1) KFG-70F1	General Cleaning	/ 2,000.00
04-Dec-24	HO-00233506	(1) KLG-SF70-4D3M	General Cleaning	/ 3,350.00
04-Dec-24	HO-00233522	(1) KFG-70F1	General Cleaning	/ 6,950.00
<b>TOTAL</b>				<b>P 14,900.00</b>
<b>LESS: DISCOUNT</b>				<b>/ (1,490.00)</b>
<b>TOTAL AMOUNT DUE</b>				<b>P 13,410.00</b>

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

**Note:** If check payment, please prepare check payable to **Kolin Philippines International Inc.**

**Account #: BDO - KALAYAAN**

**011808000428**

**Note:** In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi\_asst@kolinphil.com.ph**

Prepared by:

  
**Janellen S. Lim**  
KMI - Assistant

Noted by:

  
**Mart Nathaniel R. Flores**  
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,  
Brgy. Langkaan I, Dasmariñas, Cavite

Tel: (632) 8749-2118

Fax (046) 402-0793

[www.kolinphil.com.ph](http://www.kolinphil.com.ph) / [kolinphilippines](http://kolinphilippines)

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,  
Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791











## SERVICE JOB REPORT

No.	HO-00232678
Previous SJR No.	HO-00219505

Green - Service





Website: [www.kolinphil.com.ph](http://www.kolinphil.com.ph)     kolinphilippines

No.	HQ-00232680
Previous SJR No.	HQ-00218885

SVC-SJR-02-020123      White - Customer      Blue - Accounting      Green - Service





## SERVICE JOB REPORT

No.  
Previous SJR No.

HO-00232682

HD-00215885

Customer							Monaco Plant 1						Date								11-28-2024																																																								
Address							NY Compound, Lugmok Rd., Brgy. Bagbaguin, CALOOCAN CITY, Metro Manila																			Start Time								01:30 pm																																											
																										End Time								01:31 pm																																											
Telephone No.							5385-4552 loc. 210 / 224												Mobile No.							0958-8197074 / 0939-971403												Relayed by								Ma. Donna / KMI																															
Contact Person							Mr. Winnie Taciza												Mobile No.							0956-8197074												Tel. No.																			Warranty Type								G												
Warranty Code																										Room Size																			Job Class								GC				LVL				1																
Model							KFG-70F1																			Call Origin							IO												Job Type								FD																								
S/N (I)							2 - FADED												S/N (O)																			Permit?				<input type="checkbox"/>				Parking?				<input type="checkbox"/>				Appointment?				<input type="checkbox"/>				O.R.?				<input type="checkbox"/>				Ladder?				<input type="checkbox"/>			
Dealer																										DOP																			Notes								Villafruto * IH Request * 3 units for GC																								
Installer																										Complaint							For GC																																												
Location							Laboratory 2												Before							After																																																			
Mode Setting (Cool)																										No. of Visit							1st Action												Tentative Sched								12/04/2024																								
WAC   Setting Temp(16°C-RE)/(10/12-ME)																										Findings																																																			
SAC/PAC   Setting Temp (17°)																										DIRECT UNIT / UPPER (o) fan																																																			
Discharge Temperature (High)							15.5    14 °C																			15 for ice box working																																																			
Intake Temperature (High)							27.9    27 °C																																																																						
Ampere							22.5    20.3																			for 2nd test																																																			
Wattage (Inverter)																										Recommendation																																																			
Voltage							2mV    2mV																			bring (o) fan motor fan cap																																																			
SAC/PAC   Pressure (PSI)							(60psi)    (60psi)																			cool Comp Cap cool air play board																																																			
Part Code							Description																			Qty								Unit Price								Amount																																			
							As per compressor Auto on/off																																																																						
							not upon checking upper outdoor fan motor is not working																																																																						
																																		\$1800 w/ 10% discount								12/5																																			
							DATE CLEARED 12/5/24																																																																						
SR No.							G-      2710 AM																			Labor								\$2,000																																											
Repair Done																										Handling																																																			
																										Others																																																			
Repair Code																										Total								\$2,000																																											
Date Attended							12-4-24												Date Finished							12-4-24												Amount Paid																																							
Time Attended							1:30												Time Finished							2:45												Balance								\$2,000																															
This serves as temporary receipt when properly filled up by authorized representative.							Check No.																			Bank / Branch																			Collection																																
Serviced by:							Garry Munday, Neil Villafraza <small>Salesperson</small>																			By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations. I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.																																																			
Technician(s)							GRACE PIELAGO CSR																			Created by:								Conformed by:								Customer (Signature over printed name) WINNIE TACIZA																																			





TPWZ 13844

## 2

HO-00227401

Green - Service





# Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City  
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph  
Website: www.kolinphil.com.ph

TPWR 43845

## SERVICE JOB REPORT

Customer		Monaco Plant 1		Date		12-04-2024	
Address		NY Compound, Lugnick Rd. ... Bryg. Bagbaguin, CALOOCAN CITY, Metro Manila		Start Time		03:54 pm	
Telephone No.		8365-4562 loc. 210 / 224		Mobile No.		0956-8197074 / 0939-9714074	
Contact Person		Mr. Winnie Taclica		Warranty Type		C	
Warranty Code				Room Size			
Model		KFG-70F1		Call Origin		KO	
S/N (I)		2 - FADED		S/N (O)			
Dealer				DOP			
Installer				Complaint		Others	
Location		Laboratory 2		Before		After	
Mode Setting (Cool)		COOL		No. of Visit		1st Action	
WAC   Setting Temp (16°C-RE)/(10/12-ME)				Tentative Sched		12/09/2024	
SAC/PAC   Setting Temp (17°)		17°C		Findings			
Discharge Temperature (High)		19°C / 16°C		FAN motor (O)			
Intake Temperature (High)		27°C / 29°C		FAN CAP (O)			
Ampere		16.5 / 16		Recommendation			
Wattage (Inverter)		233		FOR REPLACEMENT OF			
Voltage		233		FAN CAP AND FAN MOTOR			
SAC/PAC   Pressure (PSI)		65 / 65		OUTDOOR			
Part Code		Description		Qty		Unit Price	
		FAN MOTOR		1PC		3,450	
		(4mr) FA CAPACITOR		1PC		300	
		Ref SJR # 232682		W/		6255	
						10% discount	
						12/9	
						LIQUIDATED	
						12/8/24	
						3:57pm	
SR No.				Labor		3,200	
Repair Done		REPLACED FAN CAP AND FAN MOTOR, RUN TEST NORMAL OPERATION		Handling			
Repair Code				Others			
Date Attended		12-7-24		Total		6,950	
Time Attended		10:20am		Amount Paid		FOR collector	
				Balance		6,950	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by: Vidal Lujero, Manuel Repasing		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
TABUERA VISTAN		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
RIVERA		Created by: RECHILLA		Conformed by:		Customer (Signature over printed name)	
Technician(s)		CSR					