



24-Mar-2025

MR. DENNIS CHUA

21 ASTEROID ST., BRGY. BEL AIR 4, MAKATI CITY

TEL: 0917-8901055

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of MARCH 2025.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
13-Mar-25	HO-00245305	(1) KSM-15CB1INV	PARTS REPLACEMENT	930.00
13-Mar-25	HO-00245430	(1) KSM-25CB1INV	REPLACED PCB	8,400.00
TOTAL				P 9,330.00
LESS: OVERPAYMENT				(1,050.00)
				P 8,280.00
LESS: DISCOUNT				(579.60)
TOTAL AMOUNT DUE				P 7,700.40

Notes:

* If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: 011808000428 - BDO - KALAYAAN


* In case thru Bank Deposit under BDO Account, kindly indicate **(1) SJR#** as Reference No. on the deposit slip. Kindly send proof of payment to **viber 0917-8078607** or E-mail to: **kmi_asst@kolinphil.com.ph**

For any clarifications please feel free to call the Undersigned on this telephone number **8852-6473**.

Prepared by:


Janellen S. Lim
KMI - Assistant

Noted by:


Mari Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmariñas, Cavite

Tel: (632) 8749-2118

Fax (046) 402-0793

 www.kolinphil.com.ph / kolinphilippines

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,
Makati City

Tel: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791



Customer		Chua, Dennis		No. Previous SJR No.		HO-00245305	
Address		21 Asteroid St., Brgy. Bel Air 4, MAKATI CITY, Metro Manila		Date		03-11-2025	
Telephone No.		Mobile No.		Start Time		10:47 am	
Contact Person		Dennis Chua		End Time		10:49 am	
Warranty Code		Mobile No. 0917-8901055		Relayed by		Dennis Chua / 8253-091...	
Model		KSM-15CB1INV		Warranty Type		+C	
S/N (I)		10671107-12419		Room Size		Job Class	
Dealer		DOP		Call Origin		TS LVL 1	
Installer		Complaint		Job Type		FD	
Location		Before After		Permit? ☐ Parking? ☐ Appointment? ☐ O.R.? ☐ Ladder? ☐			
Mode Setting (Cool)		WAC Setting Temp (16°C-RE)/(10/12-ME)		Notes			
SAC/PAC Setting Temp (17°)		Discharge Temperature (High)		Findings			
Intake Temperature (High)		Ampere		Recommendation			
Wattage (Inverter)		Voltage		SAC/PAC Pressure (PSI)			
Part Code		Description		Qty		Unit Price	
Amount							
SR No.		Repair Done		Labor		600	
Repair Code		Date Attended		Handling			
Time Attended		Date Finished		Others			
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Total		930	
Bank / Branch		Amount Paid		Balance		930	
Served by: Jonellio Braso, Bayet Cuevas		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.		Created by:		Conformed by:	
Technician(s)		GECILIE A. AMORA		Customer		(Signature over printed name)	



SERVICE JOB REPORT

No.	HO-00245430
Previous SJR No.	HO-00245430

Customer	Chua, Dennis						Date	03-12-2025		
Address	21 Asteroid St., Brgy. Bel Air 4, MAKATI CITY, Metro Manila						Start Time	09:20 am		
Telephone No.					Mobile No.	0917-8901055		Relayed by	Dennis / 0917-8901055	
Contact Person	Dennis Chua		Mobile No.	0917-8901055		Tel. No.	7216-2808		Warranty Type	L C
Warranty Code						Room Size			Job Class	TS LVL 1
Model	KSM-25CB11IW					Call Origin	MH		Job Type	FD
S/N (I)	10711102-124		S/N (O)	Jr. Master's Bedroom		Permit?	Parking?	Appointment?	O.R.?	Ladder?
Dealer			DOP			Notes				
Installer	GROUND FLOOR		Complaint	Not Cooling		Villafuerte as per cust temp set to 22 and cool mode still not cooling previous job done Findings - Dirty unit... Recommendation - Clean Air Filter regularly. Repair Done - General Cleaning & Check Parameters / For Collection c/o KMI 2-21-25				
Location	3rd Floor		Before	After						
Mode Setting (Cool)			No. of Visit	1st Action		Tentative Sched		03/15/2025		
WAC Setting Temp(16°C-RE)/(10/12-ME)			Findings							
SAC/PAC Setting Temp (17°)			DEFECTIVE PCB(O) BOARD, OUTDOOR UNIT NOT WORKING							
Discharge Temperature (High)			Recommendation							
Intake Temperature (High)			CLEAN FILTER REGULARLY							
Ampere										
Wattage (Inverter)										
Voltage	220									
SAC/PAC Pressure (PSI)										
Part Code	Description					Qty	Unit Price	Amount		
	PCB (O) BOARD					1	6,600	6,600		
LIQUIDATED										
3/17/25										
less										
SR No.							Labor	1,800		
Repair Done	REPLACED PCB (O) BOARD, RUN TEST UNIT OK						Handling			
Repair Code							Others	8,400		
Date Attended	3-15-25		Date Finished	3-15-25		Total				
Time Attended	2:20		Time Finished	3:00		Amount Paid	8,400			
This serves as temporary receipt when properly filled up by authorized representative.						Check No.	Bank / Branch			
Serviced by: Genny Murday, Not Verified						By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.				
Technician(s)						I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.				
Created by:						Conformed by:				
GECILIE A. AMORA CSR						Customer (Signature over printed name)				