



5-Mar-2025

GAKKEN PHILS INC.

134 AURORA BLVD. COR. H. LAZADA ST., BRGY. BALONG BALO, SAN JUAN

TEL: 0917-1745759 / 0977-1903459

Sir/ Madam,

This is to bill you on the service job done to your unit for the month of JANUARY 2025.

Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR#	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
14-Jan-25	HO-00237330	(1) KSM-IW25-6H1M	PARTS REPLACEMENT	2,900.00
	TOTAL			P 2,900.00
	LESS: DISCOUNT			(203.00)
	TOTAL AMOUNT DUE			P 2,697.00

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**

Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**


Account #: BDO - KALAYAAN 011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Jim
KMI - Assistant

Noted by:


Mart Nathaniel R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,

Brgy. Langkaan I, Dasmariñas, Cavite

Tel: (632) 8749-2118

Fax (046) 402-0793

www.kolinphil.com.ph / kolinphilippines

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,

Makati City

Tel: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791





Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph

SERVICE JOB REPORT

No. HO-00237830
Previous SJR No.

Customer	Gakken Phils Inc.			Date	01-10-2025		
Address	134 Aurora Blvd. cor. H. Lazada St. Brgy. Balong Bato, SAN JUAN CITY, Metro Manila			Start Time	07:49 am		
Telephone No.			Mobile No.	0917-1745759 / 0977-190345		Relayed by	Gakken PH/ Jonna - +63
Contact Person	Ms. Jonna	Mobile No.	0905-4340664	Tel. No.			
Warranty Code				Room Size			
Model	KSM-IW25-6H1M			Call Origin	MH		
S/N (I)	18292103-16192		S/N (O)	18302011-16077		Permit?	<input type="checkbox"/>
Dealer	KMI		DOP	11/06/2021		Parking?	<input type="checkbox"/>
Installer	Farran Lopez		Complaint	Dead Set			
Location	2nd Flr. Office		Before	After		Appointment?	<input type="checkbox"/>
Mode Setting (Cool)			No. of Visit	1st Action		O.R.?	<input type="checkbox"/>
WAC Setting Temp(16°C-RE)/(10/12-ME)			Findings				
SAC/PAC Setting Temp (17°)			DEAD SET				
Discharge Temperature (High)			12°C				
Intake Temperature (High)			24°C				
Ampere			10.5 A				
Wattage (Inverter)			Recommendation				
Voltage			CLEAN AIR FILTER REGULARLY				
SAC/PAC Pressure (PSI)			230V				
			125 PSI				
Part Code	Description			Qty	Unit Price	Amount	
	POWER MODULE			1	1,100	1,100	
NOTE: PAYMENT FOR COLLECTION							
c/o KMI							
LIQUIDATED							
1/14/25							
SR No.				Labor	1,800		
Repair Done	REPLACED POWER MODULE			Handling			
Repair Code				Others			
Date Attended	1-14-25		Date Finished	1-14-25		Total	2,900
Time Attended	1:35		Time Finished	2:40		Amount Paid	2,900
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Balance		
Serviced by: Joseph Bragas, Boyet Cuevas				By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
BOYET REX LITO				I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Technician(s)				Created by: Sherry Anne B. Gorn...		Conformed by: Mark Viduya	
				CSR		Customer (Signature over printed name)	