



5-Mar-2025

NUAT THAI SPA

ATTN: MS. SARAH

THE CAPITAL TOWERS, GROUND FLR., 222 E. RODRIGUEZ SR. AVE., BGRY. KALUSUGAN, QUEZON CITY

TEL: 0977-1213412/0998-5463460

Sir/ Madam,

This is to remind you for the following unsettled charges of service job done to your unit for the month of AUGUST 2024. Details of the charges are stated below and a copy of the Service Job Report is attached for your references:

DATE ATTENDED	SJR #	QUANTITY/MODEL	SERVICE JOB DONE	AMOUNT
01-Aug-24	HO-00215769	(1) KSM-IW25-6H1M	PUMP DOWN REPAIR	2,500.00
09-Aug-24	HO-00216178	(1) KSM-IW15WAE-7J1M	GENERAL CLEANING	1,500.00
TOTAL AMOUNT DUE				P 4,000.00

For any clarifications please feel free to call the Undersigned at the telephone number **8852-6473**


Note: If check payment, please prepare check payable to **Kolin Philippines International Inc.**

Account #: BDO - KALAYAAN

011808000428

Note: In case thru Bank Deposit under BDO Account, kindly indicate SJR# for your Bank Reference in the deposit slip and Fax to **(632) 8852-6473** or E-mail to: **kmi_asst@kolinphil.com.ph**

Prepared by:


Janellen S. Lim
KMI - Assistant

Noted by:


Mar Nicanor R. Flores
KMI - Supervisor

Received by:

Signature over printed name

 **Kolin Philippines Int'l., Inc.**

Plant and Head Office:

Blk 3 Lt 5 Main Drive, FCIE Compound,
Brgy. Langkaan I, Dasmarinas, Cavite

Tel.: (632) 8749-2118

Fax (046) 402-0793

 www.kolinphil.com.ph / [kolinphilippines](http://kolinphilippines.com)

Operation Office:

1854 Sta. Rita St., Guadalupe Nuevo,
Makati City

Tel.: (632) 8851-2711, 12 or 15

Fax: (632) 8852-2170

Sales Dept. Fax: (632) 8852-4791



1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph    [kolinphilippines](#)

No.
Previous SJR No.

HO-00215769

140 000 12000

Customer						Date					
Address						Start Time					
Telephone No.						End Time					
Contact Person						Relayed by					
Warranty Code						Warranty Type					
Model						Job Class					
S/N (I)						Job Type					
Dealer						Permit? ☐ Parking? ☐ Appointment? ☐ O.R.? ☒ Ladder? ☐					
Installer						Notes					
Location						Findings					
Mode Setting (Cool)						Recommendation					
WAC Setting Temp(16°C-RE)/(10/12-ME)											
SAC/PAC Setting Temp (17°)											
Discharge Temperature (High)											
Intake Temperature (High)											
Ampere											
Wattage (Inverter)											
Voltage											
SAC/PAC Pressure (PSI)											
Part Code						Description					
Qty						Unit Price					
Amount											
SR No.						Labor					
Repair Done						Handling					
Repair Code						Others					
Date Attended						Total					
Time Attended						Amount Paid					
Date Finished						Balance					
Time Finished											
This serves as temporary receipt when property filled up by authorized representative.						Check No.					
Bank / Branch											
Serviced by:						By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
Technician(s)						I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Created by:						Conformed by:					
RECHILLA CSR						Customer (Signature over printed name)					



Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph [kolinphilippines](https://www.facebook.com/kolinphilippines)

SERVICE JOB REPORT

No.	HO-00216178
Previous SJR No.	HO-00212905

SVC-SJR-02-020123

White - Customer

Blue - Accounting

Green - Service