

Customer		Chua Yap, Jake Aaron		No.		HO-00186578	
Address		Unit 74A, Tomas Arguelles St., Brgy. Santol (Entry Point Bayani St. Silencio... St.), QUEZON CITY, Metro Manila...		Previous SJR No.			
Telephone No.		365-4562		Mobile No.		0917-5249738	
Contact Person		Ms. Ellen Jean		Tel. No.		365-4562	
Warranty Code				Room Size			
Model		n/a		Call Origin		IO	
S/N (I)				S/N (O)			
Dealer				DOP			
Installer				Complaint		For Survey	
Location		Before		After			
Mode Setting (Cool)				No. of Visit		1st action	
WAC Setting Temp(16°C-RE)/(10/12-ME)				Tentative Sched		02/03/2024	
SAC/PAC Setting Temp (17°)				Findings			
Discharge Temperature (High)				Recommendation			
Intake Temperature (High)				multiple units			
Ampere				Living Room		3HP 5TR FLOOR	
Wattage (Inverter)				BABY Room		split type 2HP	
Voltage							
SAC/PAC Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
		fit Jake room under 2.4					
SR No.		1-5-24		Date Finished		2-5-24	
Repair Done				Time Finished		9:00	
Repair Code				Amount Paid		5000	
Date Attended		7:30		Balance		10 K	
Time Attended				Check No.		Bank / Branch	
This serves as temporary receipt when properly filled up by authorized representative.							
Serviced by: Rodolfo Dela Cruz		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Technician(s)		Created by: ALVIN DE RIVERA CSR		Conformed by: MONO		Customer (Signature over printed name)	