

Customer		Metropolitan Medical Center		Date		02-05-2024	
Address		1357-G. Masangkay St., Brgy. Tondo, MANILA CITY, Metro Manila		Start Time		10:49 am	
				End Time		10:51 am	
Telephone No.		Mobile No.		0977-8029411		Relayed by	
Contact Person		Ms. Theresa/ Kat		Tel. No.		Warranty Type	
Warranty Code				Room Size		Job Class	
Model		KSM-IW15-9L1M-I		Call Origin		IO	
S/N (I)		S/N (O)		Permit? <input type="checkbox"/>		Parking? <input type="checkbox"/>	
Dealer		KMI		DOP		01/24/2024	
Installer				Complaint		For installation	
Location		Med Express		Before		After	
Mode Setting (Cool)				No. of Visit		1st Action	
WAC Setting Temp(16°C-RE)/(10/12-ME)				Tentative Sched		02/07/2024	
SAC/PAC Setting Temp (17°)				Findings			
Discharge Temperature (High)				Recommendation			
Intake Temperature (High)							
Ampere							
Wattage (Inverter)							
Voltage							
SAC/PAC Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
		Copper tub 1/4 x 3/8		1 ft		\$350 x 1 ft = \$350.00	
		Royal cord 2mm x 4c		12 ft		\$100 x 8 ft = \$800.00	
		PVC pipe 3/4 x 10		1			
		Royal cord 3.5m x 3c		7 ft		\$60 x 7 ft = \$420.00	
		Breaker ROYU 20Amp		1		\$1,000.00 = \$1,000.00	
		Wall bracket		1 set			
		Piping clamp (D)		10			
		Piping clamp (S)		10			
		Iron tape					
		S-tape		1			
SR No.				Labor		\$4,500.00	
Repair Done		Installed unit indoor & outdoor		Handling			
Repair Code				Others			
Date Attended		2-6-24		Total		\$7,070.00	
Time Attended		9:04am		Amount Paid			
Time Finished		10:50am		Balance		\$7,070.00	
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch		For collection	
Serviced by: Fernando Lopez, Michael Vistan		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
Lopez		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Vistan		Created by: LUIS REBUYAS CSR					
Delacruz		Conformed by: Customer (Signature over printed name)					