

## SERVICE JOB REPORT

1854 Sta. Rita St., Guadalupe Nuevo, Makati City Tel. No.: 8852-8868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph Website: www.kolinphil.com.ph										No. Previous SJR No.		HO-00187808	
Customer				Date						HO-00183249			
Address				Start Time						02-14-2024			
20 Firefly Rd., Valle Verde 6, Brgy. Ugong, PASIG CITY, Metro Manila				End Time						08:22 am			
Telephone No.				Mobile No.		Relayed by						08:28 am	
Contact Person				Mobile No.		Tel. No.		Warranty Type				Mart Flores- Kmi	
Warranty Code				0917-8970171		Room Size		0917-8970171		Job Class		C LVL	
Model				Call Origin		Job Type				DSM		1	
S/N (I)				S/N (O)		Permit?		Parking?		Appointment?		O.R.? Ladder?	
Dealer				DOP		ACC47		Notes					
Installer				Complaint		Talavera FOR LAY OUT RELOCATION OF INDOOR UNIT AREA: GUEST ROOM KC REFERRAL COLLECTION C/O KMI KINDLY ADVISE CLIENT AHEAD OF TIME							
Location				Before		After		Others					
Mode Setting (Cool)				Guest Room		No. of Visit		Tentative Sched					
WAC   Setting Temp(16°C-RE)/(10/12-ME)						1st Action		Findings		02/16/2024			
SAC/PAC   Setting Temp (17°)													
Discharge Temperature (High)													
Intake Temperature (High)													
Ampere								Recommendation					
Wattage (Inverter)													
Voltage													
SAC/PAC   Pressure (PSI)													
Part Code		Description				Qty		Unit Price		Amount			
		CHIPPING WORK				1M		500		500			
SR No.		Labor						500					
Repair Done		CHIPPING & RELOCATION OF COPPER tube.						Handling					
Repair Code		Total						500					
Date Attended		2-15-24		Date Finished		2-15-24		Amount Paid		Full collection			
Time Attended		11:50 AM		Time Finished		3:00 PM		Balance		500			
This serves as temporary receipt when properly filled up by authorized representative.						Check No.		Bank / Branch					
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.											
Talavera		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.											
Medina		Created by:				Conformed by:							
Technician(s)		CSR				Customer (Signature over printed name)							