Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph kolinphilippines

(3)

SERVICE JOB REPORT

No.	HO-00189669
Previous SJR No.	

Customer	Ligon, Leticia					Date	02-28-2024
Address	Unit PHC LPL Manor Condominium, #116 LP Leviste St., Salcedo Village, Brgy. B					Start Time	05:28 pm
ir, MAKATI CITY, Metro Manila...						End Time	05:32 pm
Telephone No.			Mobile No.	0907-6302519		Relayed by	KMI- Jozelle
Contact Person	Leticia	Mobile No.	0907-6302519	Tel. No.	0907-6302519	Warranty Type	C
Warranty Code				Room Size		Job Class	SVEY LVL 1
Model	n/a			Call Origin	IO	Job Type	FD
S/N (I)		S/N (O)		Permit? ☐	Parking? ☐	Appointment? ☒	O.R.? ☐ Ladder? ☐
Dealer		DOP		Notes	Dadios * Appt. (Monday) * 1 SAC * Collection c/o customer * Regular Customer		
Installer		Complaint	For Survey				
Location	For Survey	Before	After				
Mode Setting (Cool)				No. of Visit	1st Action	Tentative Sched	03/04/2024
WAC | Setting Temp(16°C-RE)/(10/12-ME)			Findings				
SAC/PAC | Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere			Recommendation				
Wattage (Inverter)			KSM-1W20 WCH0M1M32				
Voltage			ST # 3415				
SAC/PAC | Pressure (PSI)							

Part Code	Description	Qty	Unit Price	Amount

CLEARED
BY
DATE 3/4/24

for collection

SR No.				Labor	550-
Repair Done	SWASEY APEX			Handling	
				Others	
Repair Code				Total	550-
Date Attended	3-4-24	Date Finished	3-4-24	Amount Paid	COLLECTION
Time Attended	1:10 pm	Time Finished	2:30 pm	Balance	c/o KMI
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch	

Serviced by: Jeoffrey Dadios

By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.

I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.

Technician(s)

Created by: GRACE PIELAGO
CSR

Conformed by: LACELL
Customer
(Signature over printed name)

3/4/24