


Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph 

TPWR 28482

SERVICE JOB REPORT

No.	HO-00191014								
Previous SJR No.	HO-00185693								
Customer	Aquino, Alex		Date	03-09-2024					
Address	, 83 Scout Limbaga, (NEAR TOMAS MORATO), Brgy. Sacred Heart, QUEZON CITY, MANILA...		Start Time	03:52 pm					
Telephone No.	0917-8535343	Mobile No.	Relayed by	sir alvin					
Contact Person	Alex	Mobile No.	0917-8452539	Tel. No.	0917-8535343	Warranty Type	C		
Warranty Code	15		Room Size			Job Class	TS	LVL	1
Model	KSG-IWF- W WFY-8K1M32-I		Call Origin	MH		Job Type	FD		
S/N (I)	18472109-10191	S/N (O)			Permit? <input type="checkbox"/> Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>	
Dealer	KMI 18452109-10022(1)	DOP	05/11/2022	Notes LOJERO WATER DRIPPING SA DINGDING AS PER CUSTOMER					
Installer	Reymon Leyls	Complaint	Water Dripping						
Location	2F MASTERS BED Before	After							
Mode Setting (Cool)	JF BEDROOM 2	Cool	No. of Visit	1st Action		Tentative Sched	03/11/2024		
WAC Setting Temp(16°C-RE)/(10/12-ME)		—	Findings						
SAC/PAC Setting Temp (17°)		17°C	Dirty Unit						
Discharge Temperature (High)		11.5°C							
Intake Temperature (High)		24°C							
Ampere	3.8Amp	Recommendation							
Wattage (Inverter)	—								
Voltage	230V								
SAC/PAC Pressure (PSI)	145Psi								
Part Code	Description			Qty	Unit Price	Amount			
SR No.				Labor	\$1,500.00				
Repair Done	General cleaning			Handling					
				Others					
Repair Code				Total	\$1,500.00				
Date Attended	3-11-24	Date Finished	3-11-24	Amount Paid					
Time Attended	11:40 am	Time Finished	2:00 pm	Balance	\$1,500.00				
This serves as temporary receipt when properly filled up by authorized representative.			Check No.	Bank / Branch	For collection				
Serviced by: <u>Vidal Lojero, Kevin Senar, M.</u>		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.							
Lopez	VISTAN	I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.							
DADIOS		Created by: RECHILLA	Conformed by: 	Customer (Signature over printed name)					
Technician(s)		CSR							

Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph     

TPWR 38428 83

SERVICE JOB REPORT

No.
Previous SJR No.


HO-00191041

HO-00191041

03-09-2024

10:22 pm

10:25 pm

Customer	Aquino, Alex				Date			
Address	83 Scout Limbag, (NEAR TOMAS MORATO), Brgy. Sacred Heart, OUEZON CITY, Metro Manila				Start Time	10:22 pm		
Telephone No.	0917-8535343		Mobile No.			End Time	10:25 pm	
Contact Person	Alex	Mobile No.	0917-8452539	Tel. No.	0917-8535343	Warranty Type	C	
Warranty Code				Room Size			Job Class	GC
Model	KSG-IWF-15WFY-8K1M32-I			Call Origin	IO	Job Type	LVL 1 FD	
S/N (I)	2F BEDROOM 1		S/N (O)			Permit? <input type="checkbox"/> Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>
Dealer	KMI 18452109-10036(1)		DOP	05/11/2022		Notes	*8AM to 5PM only *Get unit serial number	
Installer	Reymon Leyls		Complaint	For GC				
Location	2F BEDROOM 1		Before					
Mode Setting (Cool)			Cool	No. of Visit	1st action	Tentative Sched	03/11/2024	
WAC Setting Temp(16°C-RE)/(10/12-ME)			—	Findings				
SAC/PAC Setting Temp (17°)			17°C	Dirty Unit				
Discharge Temperature (High)			11.7°C					
Intake Temperature (High)			25°C					
Ampere			4 Amp	Recommendation				
Wattage (Inverter)			—					
Voltage			230 V					
SAC/PAC Pressure (PSI)			135Psi					
Part Code	Description				Qty	Unit Price	Amount	
SR No.					Labor	\$ 1,500.00		
Repair Done	General cleaning				Handling			
Repair Code					Others			
Date Attended	3-11-24	Date Finished	3-11-24	Amount Paid	\$ 1,500.00			
Time Attended	11:40 am	Time Finished	2:00 pm	Balance	\$ 1,500.00			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch			
Serviced by: Fernando Lopez, Michael V		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.						
LOPEZ		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.						
DADIOS		Created by:		Conformed by: 				
Technician(s)		ALVIN DE RIVERA		Customer (Signature over printed name)				




Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
 Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
 Website: www.kolinphil.com.ph     

TPWR 28450

SERVICE JOB REPORT

Customer	Aquino, Alex				Date	03-09-2024				
Address	83 Scout Limbaga, (NEAR TOMAS MORATO), Brgy. Sacred Heart, QUEZON CITY, Metro Manila				Start Time	10:26 pm				
Telephone No.	0917-8535343		Mobile No.			End Time	10:27 pm			
Contact Person	Alex	Mobile No.	0917-8452539	Tel. No.	0917-8535343	Warranty Type	C			
Warranty Code				Room Size			Job Class	GC	LVL	1
Model	KSG-IWF-30WFY-8K1M32-I			Call Origin	IC	Job Type	FD			
S/N (I)	GF LIVING		S/N (O)			Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>
Dealer	KMI 18512112-10292(1)		DOP	05/11/2022		Notes *8AM to 5PM only *Get unit serial number				
Installer	Reymon Leyls		Complaint	For GC						
Location	GF LIVING		Before							
Mode Setting (Cool)			Cool	No. of Visit	1st action		Tentative Sched	03/11/2024		
WAC Setting Temp(16°C-RE)/(10/12-ME)			—	Findings						
SAC/PAC Setting Temp (17°)			17°C	Dirty outdoor unit only (Slightly used)						
Discharge Temperature (High)			12°C							
Intake Temperature (High)			24°C							
Ampere			12.5Amp	Recommendation						
Wattage (Inverter)			—							
Voltage			230V							
SAC/PAC Pressure (PSI)			135Psi							
Part Code	Description				Qty	Unit Price	Amount			
SR No.										
Repair Done	Cleaning of outdoor unit									
Repair Code										
Date Attended	3-11-24	Date Finished	3-11-24				Amount Paid			
Time Attended	11:40 am	Time Finished	2:00 pm				Balance			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.			Bank / Branch			
Serviced by: Fernando Lopez, Michael Vias Cell: 0917-811-8982				By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.						
LOPEZ	VISTAN	I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.								
DADIOS		Created by:		Conformed by:						
Technician(s)		ALVIN DE RIVERA CSR		Customer (Signature over printed name)						

Customer		Aquino, Alex				Date	03-09-2024			
Address	83 Scout Limbaga, (NEAR TOMAS MORATO), Brgy. Sacred Heart, QUEZON CITY, MANILA...				Start Time	10:27 pm				
Telephone No.	0917-8535343		Mobile No.			End Time	10:28 pm			
Contact Person	Alex	Mobile No.	0917-8452539	Tel. No.	0917-8535343	Warranty Type	C			
Warranty Code				Room Size			Job Class	GC	LVL	1
Model	KSG-IWF-30WFY-8K1M32-I			Call Origin	IO	Job Type	FD			
S/N (I)	GF DINING/KITCHEN		S/N (O)			Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>
Dealer	KMI 18512112-10587(1)		DOP	05/11/2022	Notes *8AM to 5PM only *Get unit serial number					
Installer	Reymon Leyls		Complaint	For GC						
Location	GF DINING/KITCHEN		Before	After						
Mode Setting (Cool)			Cool		No. of Visit	1st action	Tentative Sched		03/11/2024	
WAC Setting Temp(16°C-RE)/(10/12-ME)			—	Findings						
SAC/PAC Setting Temp (17°)			17°C	Dirty outdoor unit only (slightly used)						
Discharge Temperature (High)			11.8°C							
Intake Temperature (High)			24°C							
Ampere			12.2Amp	Recommendation						
Wattage (Inverter)			—							
Voltage			230V							
SAC/PAC Pressure (PSI)			140Psi							
Part Code	Description					Qty	Unit Price	Amount		
 										
SR No.						Labor	\$ 750.00			
Repair Done	Cleaning of outdoor unit only					Handling				
Repair Code						Others				
Date Attended	3-11-24	Date Finished	3-11-24	Amount Paid		\$ 750.00				
Time Attended	11:40 am	Time Finished	1:00 pm	Balance		\$ 750.00				
This serves as temporary receipt when properly filled up by authorized representative.					Check No.	Bank / Branch				For collection
Serviced by: Fernando Lopez, Michael Vic Carillo		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.								
LOPEZ	VISTAN	I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.								
DADIOS		Created by: ALVIN DE RIVERA CSR		Conformed by: 						
Technician(s)		Customer (Signature over printed name)								