

Customer				No. Previous SJR No.		HO-00190621	
Address				Date		HO-00185980	
1357-G. Masangkay St., Brgy. Tondo, MANILA CITY, Metro Manila				Start Time		03-07-2024	
Telephone No.				End Time		10:07 am	
Mobile No.				Relayed by		10:09 am	
Contact Person				Warranty Type		Sir Mart / KMI	
Mobile No.				Room Size		C LVL	
Warranty Code				Job Class		INST	
Model				Call Origin		FD	
S/N (I)				Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/>		O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>	
Dealer				Notes			
Installer				11/22/2023 Talavera * For Start up of SAC & Installation of Air curtain. * EDD: 11/24/2023 * COLLECTION C/O KMI *			
Location				Before After For Installation ECY REFERRAL			
Mode Setting (Cool)				No. of Visit		Tentative Sched	
WAC Setting Temp(16°C-RE)/(10/12-ME)				1st Action		Findings 03/11/2024	
SAC/PAC Setting Temp (17°)							
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere				Recommendation			
Wattage (Inverter)				for installation - Air curtain			
Voltage							
SAC/PAC Pressure (PSI)							
Part Code		Description		Qty	Unit Price	Amount	
L		SN # 14012001-26600					
R		SN # 14012002-27513					
		2 pcs					
		NOTE: ENDORSEMENT OF Remote Control to ENGINEERING					
		and OK					
SR No.				Labor		1,200	
Repair Done		Installation 2 pcs Air curtain		Handling		1,200	
Repair Code		Testing 5 min, unit work		Others			
Date Attended		3-11-24		Total		2,400	
Time Attended		12:10 PM		Amount Paid			
Time Finished		3:20 PM		Balance		2,400	
This serves as temporary receipt when properly filled up by authorized representative.				Check No.		Bank / Branch	
Serviced by:		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
Talavera		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Richard Talavera, Encoson Valle		Created by:		Conformed by:			
Technician(s)		CSR		Customer (Signature over printed name)			