

Customer		QC Holiday Spa		No.		HO-00190811	
Address		150-D Tuazon St., Brgy. Lourdes, QUEZON CITY, Metro Manila		Previous SJR No.		HO-00187512	
Telephone No.		Mobile No.		Date		03-08-2024	
Contact Person		Jonathan		Start Time		11:21 am	
Warranty Code		Mobile No. 0916-8427241		End Time		11:24 am	
Model		KAG-250ME		Relayed by		SIR JONATHAN	
S/N (I)		4		Warranty Type		C	
Dealer		DOP		Room Size		Job Class	
Installer		Complaint		Call Origin		MH	
Location		Men's Massage		Job Type		FD	
Mode Setting (Cool)		COOL		Permit? <input type="checkbox"/> Parking? <input type="checkbox"/> Appointment? <input type="checkbox"/>		O.R.? <input type="checkbox"/> Ladder? <input type="checkbox"/>	
WAC Setting Temp (16°C-RE)/(10/12-ME)		13°C		Notes		CUEVAS	
SAC/PAC Setting Temp (17°)		26°C		Findings		POSSIBLE LEAK DIRTY UNIT	
Discharge Temperature (High)		10A		Recommendation		FOR 2ND ACT. CLEAN AIR FILTER REGULARLY	
Intake Temperature (High)		23V		SAC/PAC Pressure (PSI)			
Ampere				Part Code		Description	
Wattage (Inverter)				Qty		Unit Price	
Voltage				Amount			
NOTE: PAYMENT FOR COLLECTION		c/o KMI		Cleared		10% discount	
BY		DATE		3/11/24		720.00	
SR No.		GENERAL CLEANING		Labor		800-	
Repair Done				Handling			
Repair Code				Others			
Date Attended		3-11-24		Total		800-	
Time Attended		9:30		Amount Paid			
Date Finished		3-11-24		Balance		800-	
Time Finished		2:45		Bank / Branch			
This serves as temporary receipt when properly filled up by authorized representative.		Check No.					
Serviced by: Joselito Brasos, Boyet Cuevas		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
BOYET REX BRASOS		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
Technician(s)		Created by: LUIS REBUYAS CSR		Conformed by: Jonathan Labine		Customer (Signature over printed name)	

SERVICE JOB REPORT

[illegible]

Customer				Date			
Address				Start Time			
Telephone No.				End Time			
Contact Person				Relayed by			
Warranty Code				Warranty Type			
Model				Job Class			
S/N (I)				Job Type			
Dealer				Appointment? <input type="checkbox"/>			
Installer				O.R.? <input type="checkbox"/>			
Location				Ladder? <input type="checkbox"/>			
Mode Setting (Cool)				Findings			
WAC Setting Temp(16°C-RE)/(10/12-ME)				SAC/PAC Setting Temp (17°)			
Discharge Temperature (High)				Intake Temperature (High)			
Ampere				Recommendation			
Wattage (Inverter)				Voltage			
SAC/PAC Pressure (PSI)				Part Code			
Description				Qty			
Unit Price				Amount			
Note: PAYMENT FOR COLLECTION				C/O KMI			
Cleared				10% discount			
SR No.				Labor			
Repair Done				Handling			
Repair Code				Others			
Date Attended				Total			
Time Attended				Amount Paid			
Check No.				Balance			
Bank / Branch				This serves as temporary receipt when properly filled up by authorized representative.			
Serviced by:				By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.			
Technician(s)				I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.			
Created by:				Conformed by:			
Customer				(Signature over printed name)			



No.	HO-00190904
Previous SJR No.	HO-00187312

SVC-SJR-02-020123 White - Customer Blue - Accounting Green - Service



SERVICE JOB REPORT

No.	HO-00190905
Previous SJR No.	HO-00187612

[illegible]