

Customer	Metropolitan Medical Center					Date	03-12-2024			
Address	, 1357-G. Masangkay St., Brgy. Tondo, MANILA CITY, Metro Manila					Start Time	01:22 pm			
						End Time	01:23 pm			
Telephone No.			Mobile No.	0977-8029411		Relayed by	Mart Flores- Kmi			
Contact Person	Ms. Theresa/ Kat	Mobile No.	...		Tel. No.			Warranty Type	C	
Warranty Code				Room Size			Job Class	SVEY	LVL	1
Model	n/a			Call Origin	IO		Job Type	FD		
S/N (I)			S/N (O)			Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>
Dealer			DOP			Notes Dadios FOR SURVEY 3 SAC AREA: RADIOLOGY / CT SCAN NEW AREA COLLECTION C/O CUSTOMER ECY REFERRAL KINDLY ADVISE CLIENT AHEAD OF				
Installer			Complaint	For Survey						
Location			Before	After	TIME					
Mode Setting (Cool)					No. of Visit	1st Action	Tentative Sched		03/13/2024	
WAC Setting Temp(16°C-RE)/(10/12-ME)					Findings					
SAC/PAC Setting Temp (17°)										
Discharge Temperature (High)										
Intake Temperature (High)										
Ampere					Recommendation					
Wattage (Inverter)					2 - WATTAGE 3 - WATTAGE FOR WATTAGE					
Voltage										
SAC/PAC Pressure (PSI)										
Part Code	Description					Qty	Unit Price	Amount		
SR No.							Labor	500 -		
Repair Done	Survey Alex						Handling			
							Others			
Repair Code							Total	500		
Date Attended	3-14-2024	Date Finished	3-14-2024				Amount Paid	500		
Time Attended	9:45 AM	Time Finished	10:40 AM				Balance	0		
This serves as temporary receipt when properly filled up by authorized representative.				Check No.			Bank / Branch			
Serviced by: Jeoffrey Dadios		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.								
		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.								
		Created by: KATHY DE GUZMAN CSR		Conformed by: Customer (Signature over printed name)						
Technician(s)										