

Customer		QC Holiday Spa		No.		HO-00190720	
Address		150-D Tuazon St., Brgy. Lourdes, QUEZON CITY, Metro Manila		Previous SJR No.		HO-00190906	
Telephone No.		Mobile No. 0921-8169405		Date		03-07-2024	
Contact Person		Jonathan		Start Time		04:15 pm	
Warranty Code		Mobile No. 0916-8427241		End Time		04:17 pm	
Model		KLM-SC40-3D1M		Relayed by		dadios	
S/N (I)		Pls update location on site		Warranty Type		C	
Dealer		DOP		Room Size		TS LVL 1	
Installer		Complaint For Leak Testing		Job Class		FD	
Location		Before After		Job Type		FD	
Mode Setting (Cool)		No. of Visit		1st Action		Tentative Sched 03/12/2024	
WAC Setting Temp (16°C-RE)/(10/12-ME)		Findings					
SAC/PAC Setting Temp (17°)		Recommendation					
Discharge Temperature (High)							
Intake Temperature (High)							
Ampere							
Wattage (Inverter)							
Voltage							
SAC/PAC Pressure (PSI)							
Part Code		Description		Qty		Unit Price	
		map GAS		1			
		ACCESS Valve		3			
		C-TUBE 2/8 X 1/4		JPR			
		A10 PSI					
SR No.		Labor		3.500			
Repair Done		Leak TESTING		Handling			
		COPPER TUBE		Others			
Repair Code		Total		2.500			
Date Attended		Date Finished		Amount Paid			
Time Attended		Time Finished		Balance			
This serves as temporary receipt when properly filled up by authorized representative.		Check No.		Bank / Branch			
Serviced by: Richard Talavera, Ericson Vallejo		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
Talavera		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
BAGAT		Created by: RECHILLA		Conformed by: Jonathan Laban			
Technician(s)		CSR		Customer		(Signature over printed name)	