

No.
Previous SJR No.HO-00191441
HO-00185379

Customer	Cayanga, Atty. Efrenilo				Date	03-13-2024	
Address	76 Sanso St., Corinthian Gardens, Brgy. Ugong Norte, QUEZON CITY, Metro Manila...				Start Time	09:27 am	
					End Time	09:36 am	
Telephone No.	8863-0622/ 8633-0618	Mobile No.	0917-5387378/ 0917-624462			Relayed by	4 Mrs. Cayanga/6330-0618...
Contact Person	...	Mobile No.	0917-5387378	Tel. No.	8633-0618	Warranty Type	C
Warranty Code				Room Size	Job Class GC LVL 1		
Model	KSM-25MB1INV KSM-1W25-6HIM			Call Origin	VH	Job Type	FD
S/N (I)	109411512-16975	S/N (O)	10921512-17378	Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input checked="" type="checkbox"/> Ladder? <input type="checkbox"/>
Dealer	KM1	18291812-10646	DOP	Notes -Villafuerte -1st cust. request -please update model name and serial no. cust. can't provide the specific.			
Installer			Complaint	For GC			
Location	Dining	Before	After				
Mode Setting (Cool)		Cool		No. of Visit	1st visit	Tentative Sched	03/18/2024
WAC Setting Temp(16°C-RE)/(10/12-ME)		—		Findings			
SAC/PAC Setting Temp (17°)		17°C	Dirty Unit				
Discharge Temperature (High)		12-2°C					
Intake Temperature (High)		25°C					
Ampere		8.5Amp		Recommendation			
Wattage (Inverter)		—					
Voltage		230V					
SAC/PAC Pressure (PSI)		135PSI					
Part Code	Description				Qty	Unit Price	Amount
SR No.					Labor	\$ 1,500.00	
Repair Done	General cleaning				Handling		
					Others		
Repair Code					Total	\$ 1,500.00	
Date Attended		Date Finished	3-15-24			Amount Paid	
Time Attended	9:58-15:24	Time Finished	12:28			Balance	\$ 1,500
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		
Serviced by: Garry Munday, Neil Villafuerte		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.					
TALAVERA SALON		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.					
VISTAN		Created by:		Conformed by:			
Technician(s)		Christine Joy T. P...		Customer (Signature over printed name)			


Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 0852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph 

SERVICE JOB REPORT

No.
Previous SJR No.

HO-00191442
HO-00185379

Customer	Cayanga, Atty. Efrenilo				Date	03-13-2024				
Address	76 Sanso St., Corinthian Gardens, Brgy. Ugong Norte, QUEZON CITY, Metro Manila				Start Time	09:43 am				
a...					End Time	09:47 am				
Telephone No.	8863-0622/ 8633-0618		Mobile No.	0917-5387378/ 0917-624462		Relayed by	346294 Mrs. Cayanga/6330-0618			
Contact Person	...	Mobile No.	0917-5387378	Tel. No.	8633-0618	Warranty Type	C			
Warranty Code				Room Size			Job Class	TS LVL 1		
Model	SAC-RES KSM-150B1E			Call Origin	VH	Job Type	FD			
S/N (I)	FADED		S/N (O)			Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>
Dealer			DOP			Notes -Villafuerte -gc if needed -1st cust. request -please update model name and serial no. cust. can't provide the specific.				
Installer			Complaint	Water Dripping						
Location	1	Before	After							
Mode Setting (Cool)			Cool	No. of Visit	1st visit	Tentative Sched	03/18/2024			
WAC Setting Temp(16°C-RE)/(10/12-ME)			—	Findings						
SAC/PAC Setting Temp (17°)			17°C	Dirty Unit / Water dripping						
Discharge Temperature (High)			25°C							
Intake Temperature (High)			12°C							
Ampere			5.8 Amp	Recommendation						
Wattage (Inverter)			—							
Voltage			230V							
SAC/PAC Pressure (PSI)			65Psi							
Part Code	Description					Qty	Unit Price	Amount		
SR No.						Labor	₱ 1,500.00			
Repair Done	General cleaning					Handling				
Repair Code						Others				
Date Attended	3-15-24	Date Finished	3-15-24			Amount Paid				
Time Attended	9:56 am	Time Finished	12:10			Balance	₱ 1,500			
This serves as temporary receipt when properly filled up by authorized representative.				Check No.			Bank / Branch	for collection		
Serviced by: Garry Munday, Neil Villafuerte, Selement		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.								
TALAVERA VALLE		I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.								
VISTAN		Created by:		Conformed by:						
Technician(s)		Christine Joy T. P... CSR		Customer (Signature over printed name) 						

Kolin Philippines Int'l., Inc.

1854 Sta. Rita St., Guadalupe Nuevo, Makati City
Tel. No.: 8852-6868 / Mobile: 0917-811-8982 / Email: service@kolinphil.com.ph
Website: www.kolinphil.com.ph    

SERVICE JOB REPORT

No. HO-00191443
Previous SJR No. HO-00185379

Customer	Cayanga, Atty. Efrenilo				Date	03-13-2024				
Address	76 Sanso St., Corinthian Gardens, Brgy. Ugong Norte, QUEZON CITY, Metro Manila				Start Time	09:47 am				
					End Time	09:51 am				
Telephone No.	8863-0622/ 8633-0618		Mobile No.	0917-5387378/ 0917-6244627		Relayed by	Mrs. Cayanga/ 86330-0618			
Contact Person	...	Mobile No.	0917-5387378	Tel. No.	8633-0618	Warranty Type	C			
Warranty Code				Room Size			Job Class	GC	LVL	1
Model	SAC-REG KSM-150BIE			Call Origin	VH		Job Type	FD		
S/N (I)	FADED		S/N (O)			Permit? <input type="checkbox"/>	Parking? <input type="checkbox"/>	Appointment? <input type="checkbox"/>	O.R.? <input type="checkbox"/>	Ladder? <input type="checkbox"/>
Dealer			DOP			Notes -Villafuerte 1st cust. request -please update model name and serial no. cust. can't provide the specific.				
Installer			Complaint	For GC						
Location	2	Before	After							
Mode Setting (Cool)			Cool	No. of Visit	1st action		Tentative Sched	03/18/2024		
WAC Setting Temp(16°C-RE)/(10/12-ME)			—	Findings						
SAC/PAC Setting Temp (17°)			17°C	Dirty Unit						
Discharge Temperature (High)			24°C							
Intake Temperature (High)			11.5°C							
Ampere			5.5Amp	Recommendation						
Wattage (Inverter)			—							
Voltage			230V							
SAC/PAC Pressure (PSI)			65Psi							
Part Code	Description					Qty	Unit Price	Amount		
SR No.						Labor	\$ 1,500.00			
Repair Done	General cleaning					Handling				
Repair Code						Others				
Date Attended	3-15-24	Date Finished	3-15-24		Amount Paid					
Time Attended	9:56 am	Time Finished	12:20		Balance	\$ 1,100				
This serves as temporary receipt when properly filled up by authorized representative.				Check No.	Bank / Branch		For collection.			
Serviced by: Garry Munday, Neil Villafuerte, Salomon		By signing below, I authorize or give consent to Kolin Philippines International, Inc. and its ASC to collect, store and process my personal information for availing service as required by Data Privacy Act of 2012 and other applicable laws and regulations.								
TALAVERA	VALLE	I hereby agree to the above repair charges incurred/to be incurred to my unit and to the terms and conditions stated at the back, and that I received the unit in good working condition.								
VISTAN		Created by:	Conformed by:							
Technician(s)		Christine Joy T. P...	Signature over printed name)							